8.0 Technical Support Appendices

Contents of the Technical Support Appendices are listed below. If a section is not applicable to this Utility Plan and explanation has been given and that item is not included.

Appendix 8.A	Legal Description and Evidence of Site Ownership
Appendix 8.B	Special Surveys (e.g., Endangered Species)
Appendix 8.C	NEPA Process
Appendix 8.D	Site Characterization Report
Appendix 8.E	Soil Test Results
Appendix 8.F	Preliminary Effluent Limits
Appendix 8.G	Effluent Limits (Existing Wastewater Treatment Works)
Appendix 8.H	Planning and Zoning Information (e.g., Portion of Local Comprehensive Plan)
Appendix 8.I	Intergovernmental Agreements
Appendix 8.J	User Charge Study Analysis
Appendix 8.K	Air Quality Permit
Appendix 8.L	Odor Control Studies
Appendix 8.M	Stormwater Management Plan and Permit
Appendix 8.N	Summary of Public Hearings and Process
Appendix 8.O	Infiltration and Inflow Study
Appendix 8.P	City of Loveland Correspondence to CDPHE Regarding Influent BOD Loading
Appendix 8.Q	Rainfall Derived Infiltration/Inflow Analysis Graphs
Appendix 8.R	City of Loveland Annual Data and Assumptions Report, January 1, 2009
Appendix 8.S	WWTP Ammonia Limits Technical Memorandum
Appendix 8.T	Correspondence Between the City of Loveland and the Town of Johnstown regarding Potential Wastewater System Consolidation
Appendix 8.U	Calculations for Future Wastewater Flows

Appendix 8.A Legal Description and Evidence of Site Ownership

The legal description of the WWTP site is found on page 2 of the discharge permit application enclosed in Appendix 8.F. The metes and bounds description is NW $\frac{1}{4}$ of NE $\frac{1}{4}$ of SW $\frac{1}{4}$ and SW $\frac{1}{4}$ of SE $\frac{1}{4}$ of NW $\frac{1}{4}$ and all of NW $\frac{1}{4}$ of SE $\frac{1}{4}$ of NW $\frac{1}{4}$ LY S of Farmers Ditch 19-5-68.

Appendix 8.B Special Surveys (e.g., Endangered Species)


Special surveys are not required for the WWUP and are not included. Special surveys are typically part of the NEPA process for SRF funding as discussed in Section 3 or for new site locations for infrastructure additions. The City currently has no plans for pursuing SRF funding for any projects. Should the City's funding needs change, they will comply with all funding requirements for special surveys. The existing WWTP site will continue to be used throughout the planning period. Any new interceptors or lift station locations are planned for the planning period may require special surveys if federal funding (e.g. SRF) is involved. Other special surveys that could be applicable to a new project site include endangered species and historic preservation.

Appendix 8.C NEPA Process

As noted in Section 3, the City is not applying for an SRF loan or any other federal funding in association with this Utility Plan. There are no improvements immediately proposed that involve federal land management or would constitute a major federal action which would trigger NEPA requirements at this time.

Appendix 8.D Site Characterization Report

The geotechnical investigation for the most recent WWTP improvements project is enclosed. Since this WWUP is not associated with any specific project, no project-specific geotechnical investigation was completed.





GEOTECHNICAL INVESTIGATION LOVELAND WASTEWATER TREATMENT PLANT HEADWORKS IMPROVEMENTS 920 SOUTH BOISE AVENUE LOVELAND, COLORADO

Prepared For:

CH2M Hill, Inc. 9193 South Jamaica Street Englewood, Colorado 80112-5946

Attention: Mr. Steven R. Polson

Project No. FC03906-125

March 15, 2007 Revised April 24, 2007

351 Linden Street | Suite 140 | Fort Collins, Colorado 80524 Telephone: 970-206-9455 Fax: 970-206-9441



TABLE OF CONTENTS

SCOPE	1
SUMMARY OF CONCLUSIONS	1
SITE CONDITIONS	2
PROPOSED CONSTRUCTION	2
INVESTIGATION	3
SUBSURFACE CONDITIONS	4
Ground Water	4
Seismicity	4
CONSTRUCTION	5
Existing Fill and Structures	5
Excavation	6
Temporary Bracing	7
Dewatering	7
Fill Placement	8
FOUNDATIONS	9
Footings	10
Mat Foundations	11
SLABS-ON-GRADE	12
BELOW GRADE WALLS	13
HYDROSTATIC UPLIFT	14
PIPES AND UTILITY CONNECTIONS	15
Thrust Blocks	15
Pipe Bedding	15
Modulus of Soil Reaction	15
ENVIRONMENTAL CORROSION	16
SURFACE DRAINAGE	17
RESTORATION	18
LIMITATIONS	18
FIGURE 1 – LOCATIONS OF EXPLORATORY BORINGS	
FIGURE 2 – SUMMARY LOGS OF EXPLORATORY BORINGS	
FIGURE 3 – SWELL CONSOLIDATION TEST RESULTS	
FIGURE 4 THROUGH FIGURE 6 – GRADATION TEST RESULTS	
FIGURE 7 – EXAMPLE LATERAL EARTH PRESSURE DISTRIBUTIONS	
TABLE 1 - SUMMARY OF LABORATORY TEST RESULTS	



SCOPE

This report presents the results of our geotechnical investigation for the proposed improvements to the wastewater treatment plant located at 920 South Boise Avenue in Loveland, Colorado (Figure 1). The purpose of the investigation was to evaluate the subsurface conditions and provide foundation recommendations and geotechnical design criteria for the project.

The report was prepared from information provided by CH2M Hill and data developed during field exploration, laboratory testing, engineering analysis, and experience with similar conditions. The report includes a description of subsurface conditions found in our exploratory borings and discussions of site development as influenced by geotechnical considerations. Our opinions and recommendations regarding design criteria and construction details for foundations, slabs-on-grade, lateral earth loads, and drainage are provided. If the project grading, building locations/elevations, or proposed construction change, we should be notified. Our opinions are summarized in the following paragraphs. More complete descriptions of the subsurface conditions, results of our field and laboratory investigations and our opinions, conclusions and recommendations are included in the subsequent sections of this report.

SUMMARY OF CONCLUSIONS

1. Soils encountered in our borings consisted of between 3 and 12 feet of fill materials over clayey sands and gravelly sands. In the boring at the planned odor mitigation system, the soils are underlain by claystone bedrock at a depth of 10 feet (elevation 4915, Figure 2). Ground water at this location was measured at a depth of about 13½ feet (elevation 4913). In the vicinity of the grit chamber and associated structures, claystone bedrock was encountered at a depth of 32 feet below ground surface (elevation 4891). Ground water was measured at this location at depths of about 24 to 26 feet (elevation 4896 to 4898). Existing groundwater levels are not expected to significantly affect site development.



- 2. Existing fill was encountered in all four borings. Deeper fill was encountered in the vicinity of TH-2, TH-3, and TH-4. Existing fill should not support foundations. We recommend removal and recompaction of the existing fill beneath the planned headworks structures.
- 3. We believe footing foundations or reinforced concrete mat foundations can be used to support the proposed structures. The structures should be arranged to accommodate minor settlements and relative movements. Foundation discussion and criteria for foundations are provided in this report.

SITE CONDITIONS

The wastewater treatment plant is located on the east side of South Boise Avenue and north of Highway 402, at Tuxhorn Boulevard in Loveland, Colorado (Figure 1). The site consists of an existing wastewater treatment facility with numerous structures and treatment systems. The plant improvements are generally located between, and will connect, to many of these structures.

Typically, the site slopes to the south over most of the plant site. The area north of Tuxhorn Boulevard has a slope of approximately 5 percent and is grass covered. The portion of the site with the majority of the planned upgrades was nearly level with partial grass cover and partial paving, existing buildings and numerous treatment structures.

PROPOSED CONSTRUCTION

Based on conversations with the client and the information provided for our use, we understand the expansion of the wastewater treatment facility headworks will consist of construction of a vortex grit separator with a diameter of 18 feet, a grit pump station, an influent pump station, and a biofilter. Connecting pipelines, channels along with water control and sampling structures will be constructed.

We understand the biofilter will be used for odor mitigation and will consist of a shallow bin type structure containing organic treatment material or similar material. A manifold beneath the organic material will disperse air from the plant for treatment. The biofilter will be located in the vicinity of boring TH-1 (Figure 1), north of the existing administrative building.

The other structures will be located to the west of the administrative building and south of the headworks (TH-2, TH-3, and TH-4). The existing nearby structures are on a variety of foundations including footings and drilled piers. The influent pump station, grit basin and grit pump station will be arranged such that the top of the structures will be near existing ground surface. The bearing elevation of these structures will be between elevation 4904 and 4907 feet (approximately 17 to 19 feet below existing grades).

INVESTIGATION

Subsurface conditions at the site were investigated by drilling four borings in the areas of the proposed structures. The approximate locations of the borings are shown on Figure 1. Our field representative observed drilling, logged the soils found in the borings and obtained samples. Summary logs of the borings, including results of field penetration resistance tests, are presented on Figure 2.

Samples obtained during drilling were returned to our laboratory and visually examined by the geotechnical engineer for this project. Laboratory testing included natural moisture content and dry density, swell-consolidation, Atterberg limits, gradation, pH and water-soluble sulfate tests. Results of laboratory tests are presented in Figures 3 through 6 and summarized on Table I.

4

SUBSURFACE CONDITIONS

Soils encountered in our boring at the planned odor mitigation system

consisted of 3 feet of fill over clayey sands and gravelly sands. The soils in this

area are underlain by claystone bedrock at a depth of 10 feet (elevation 4915,

Figure 2).

Soils encountered in the vicinity of the grit chamber and associated

structures (TH-2, TH-3 and TH-4) consisted of 3 feet of fill over clayey sands and

gravelly sands. Claystone bedrock in this area was encountered in one boring at

a depth of 32 feet below ground surface (elevation 4891).

Ground Water

At the biofilter location (TH-1), ground water was measured at a depth of

about 13½ feet (elevation 4913). Ground water at the grit chamber location (TH-2,

TH-3 and TH-4), was measured at this location at depths of about 24 to 26 feet

(elevation 4896 to 4898). Groundwater levels will vary seasonally and may rise as

development of the site progresses. The existing groundwater levels are not

expected to significantly affect site development. We suggest assuming a

groundwater elevation rise of 5 feet above that measured in our borings during

wetter seasons and wetter years.

<u>Seismicity</u>

This area is subject to a low degree of seismic risk. Based upon the 2003

International Building Code (2003 IBC) and the results of field penetration tests,

the site classifies as Seismicity Site Class C. The soils and groundwater

conditions indicate low susceptibility to liquefaction.

CH2M HILL LOVELAND WWTP HEADWORKS IMPROVEMENTS LOVELAND, COLORADO

LOVELAND, COLORADO CTL T PROJECT NO. FC03906-125 (revised 4/23/07)



CONSTRUCTION

Existing Fill and Structures

Existing fill was encountered in the borings to depths ranging from 3 to 12 feet. Deeper fill areas may be encountered during proposed improvements. The fill is of unknown origin and age, but is assumed to be primarily backfill from the construction of adjacent structures and installation of utilities. There is a significant potential of settlement or heave for improvements supported by the fill. We recommend the fill be removed and recompacted if located beneath any of the planned structures.

The fill removal area should extend beyond the planned structure footprint at least 5 feet. If the excavations are deeper than about 10 feet in the planned improvement area, additional measures should be considered to reduce the potential settlement of backfill. We should be advised if any of the excavations are deeper than 10 feet below the proposed floor. The excavation can be filled with on-site soils, moisture-conditioned and compacted to the specifications in <u>Fill Placement</u>, below. Removal of the existing fill will provide more uniform support for improvements.

The existing fill can also affect pavements and exterior flatwork. The lowest risk alternative for exterior pavement and flatwork would also be complete removal and recompaction. The cost could be significant. If the owner can accept a risk of some movement and distress in these areas then partial depth removal is an alternative. We suggest removal of the existing fill to a depth of 1 to 2 feet below existing grade, proof rolling the exposed subgrade, and additional removal or stabilization of areas where soft, yielding or organic soils or debris is encountered. After this, fill placement can proceed to construction grades.



Excavation

Excavations of up to 20 feet are anticipated for the proposed improvements. Bedrock was not encountered within the planned excavation depths. We believe the soils encountered during this investigation can be excavated with typical heavy duty excavation equipment.

Excavation sides will need to be sloped or braced. We recommend the owner and contractor become familiar with applicable local, State and Federal safety regulations, including the current OSHA Excavation and Trench Safety Standards. The contractor should be aware that in no case should slope height, inclinations, excavations or depths including utility trench excavations exceed those specified in local, State and Federal safety regulations. Specifically, the current "OSHA Health and Safety Standards for Excavations" should be followed.

For this site, the overburden soil encountered in our exploratory borings includes sandy clay and clayey sand fill, clayey sand, and gravelly sand. We believe the overburden soil may classify as Type C soils, allowing excavation slopes of 1.5h:1v. If groundwater is encountered and seeps from the slopes, this may require other precautions.

Our preliminary soil and bedrock classification is based on the materials encountered in our exploratory borings. The soil penetrated by the proposed excavation may vary across the site. The contractor's "responsible person" should evaluate the soil exposed in excavations as part of the contractor's safety procedures. If an excavation (including a utility trench) is extended to a depth of more than 20 feet, it will be necessary to have the side slopes designed by a registered engineer. Vehicles and soil stockpiles should be kept a minimum lateral distance from the crest of the trench slope equal to one-half the trench depth. The exposed slope face should also be protected against the elements. As an alternative to temporary slopes, vertical excavations can be temporarily braced.



Temporary Bracing

Bracing or "trench box" construction may be necessary in order to limit the width of excavations and reduce the amount of surface disturbance. Bracing systems include driven sheet piling, soldier piles and lagging and others. Lateral loading of bracing depends on the depth of excavation, slope of excavation above the bracing, soil stockpiles and other surface loads, hydrostatic pressures, and allowable movement.

For bracing allowed to move enough to mobilize the strength of the soils with associated settlement and cracking of the ground surface, "active" earth pressure conditions are appropriate for design. If movement is not tolerable, "at rest" earth pressures are appropriate. Lateral load can be calculated using an equivalent fluid density of 45 pcf and 55 pcf for "active" and "at rest" conditions, respectively. We suggest assuming a "passive" equivalent fluid density of 250 pcf to calculate soil resistance. Graphical presentations of typical lateral loading configurations are presented in Figure 7 of this report. These pressures do not include allowances for surcharge loading or for hydrostatic conditions. Hydrostatic pressure and surcharge loads should be accounted for, where applicable.

The OSHA construction standard provides recommendations for timber bracing. We are also available to assist further with bracing design if desired.

Dewatering

Groundwater was encountered in three of the four borings at depths of 13 to 26 feet. The shallow groundwater (less than 25 feet in depth) was observed in TH-1, at the location of the proposed biofilter. Our experience in this area suggests that groundwater depths can vary with season and, depending on the time of construction, could be higher than measured in our borings. However, based on our observations we believe ground water will likely not be present in the excavations for the treatment system.



If ground water is observed during excavating, the contractor should consider temporary dewatering prior to and/or during construction. Dewatering can be accomplished using a series of trenches and sumps and granular materials from which water can be pumped, or by a system of well points. The sumps should be several feet below the bottom of the excavations to pump water down through the soil rather than up through the bottom of the excavation. The ground surface surrounding the excavation should be sloped to direct runoff away from the excavation. The design of a well point system will likely require further exploratory drilling to deeper depth and permeability tests both of which were not in the scope of this study.

Fill Placement

The existing on-site soils are suitable for re-use as fill material provided debris or deleterious organic materials are removed. If import material is required, we recommend importing granular soils for use below floor areas. Import fill should contain 10 to 40 percent silt and clay sized particles (percent passing No. 200 sieve) and exhibit a liquid limit less than 30 percent and a plasticity index less than 15 percent. Other materials may be acceptable for use as fill on this project pending our review and approval.

Areas to receive fill should be scarified, moisture-conditioned and compacted to at least 95 percent of standard Proctor maximum dry density (ASTM D 698). The properties of the fill will affect the performance of structures, slabs-on-grade, and pavements. Sand soils used as fill should be moistened to within 2 percent of optimum moisture content. Clay fill soils placed below the building should be moisture conditioned to 1 to 4 percent above optimum moisture content. Clay fill placed exterior to the building can be moistened to between optimum and 3 percent above optimum moisture content. The fill should be moisture-conditioned, placed in thin, loose lifts (8 inches or less) and compacted as above. Placement and compaction of fill should be observed and tested by a representative of our firm during construction. Fill placement and compaction activities should not be conducted when the fill material or subgrade is frozen.

Fill in areas of landscaping where no future improvements are planned can be placed at a density of at least 90 percent of standard Proctor maximum dry density (ASTM D 698). Example site grading specifications are presented in Appendix C.

FOUNDATIONS

We considered several types of foundations to support the structures, including footings, mat foundations, straight-shaft drilled piers penetrating the claystone bedrock and end-bearing piling driven to practical refusal in the claystone. The deep foundation systems of piers or piles would transmit foundation loads to more stable materials at a deeper elevation, reducing the potential for movement. However, we understand that a shallow foundation system is preferred for these additions and the potential for movement can be accounted for in the design of the different components. For this reason we have not discussed deep foundations further in this report. We can provide geotechnical design criteria for these systems, if requested.

We believe footing or mat foundations can be used to support the planned structures. The soils encountered at the foundation elevation include medium dense clayey sands. Footing and mat foundations have a higher risk of movement than deep foundation systems. We estimate potential foundation movements of less than one inch could occur for foundations designed and constructed to the criteria below.

We understand that some of the planned structures lend themselves to either footing or mat foundations due to their configuration. Therefore we have included recommendations for both types of systems. Design and construction criteria for footing foundations are provided below. Criteria for mat foundation follow. These criteria were developed from analysis of field and laboratory data and our experience. The recommended foundation alternative can be used provided all design and construction criteria presented in this report are followed.



Footings

- 1. Footings should be supported on undisturbed natural soils or densely compacted, engineered fill (see CONSTRUCTION). All existing man-placed fill should be removed from under footings and within one footing width around footings and replaced with engineered fill. Where soil is loosened during excavation, it should be removed and replaced with on-site soils compacted following the criteria in the FIII Placement section of this report.
- 2. Footings bearing on the natural soils and/or engineered fill can be designed for a maximum net allowable soil pressure of 2,000 psf. The soil pressure can be increased 33 percent for transient loads such as wind or seismic loads.
- Footings should have a minimum width of at least 16 inches.
 Foundations for isolated columns should have minimum dimensions of 24 inches by 24 inches. Larger sizes may be required depending on load and the structural system used.
- 4. The soils beneath footing pads can be assigned a coefficient of friction of 0.35 to resist lateral loads. The ability of grade beams, or footing backfill to resist lateral loads can be calculated for using a passive equivalent fluid pressure of 250 pcf. This assumes the backfill is densely compacted and will not be removed. Backfill should be placed and compacted to the criteria in the Fill Placement section of the report. These values are considered ultimate values and appropriate factors of safety should be used. Typically, a factor of safety of 1.5 is used for sliding and 1.6 for lateral earth pressure.
- 5. Exterior footings should be protected from frost action. Normally, 30 inches of frost cover is assumed for this area.
- 6. Below grade walls and grade beams should be well reinforced both top and bottom. We recommend the amount of steel equivalent to that required for a simply supported span of 15 feet.
- 7. Completed footing excavations should be observed by a representative of our firm to confirm that the soils are as we anticipated from our borings. Occasional loose soils may be found in foundation excavations. If this occurs, we recommend the loose soils be treated as discussed in Item 1 above.



Mat Foundations

- 1. The mat foundation should be constructed on undisturbed native soils. Where soils are loosened during excavation or in the forming process for the foundation, the loose disturbed material should be removed and replaced with Colorado Department of Transportation (CDOT) Class 6 Road Base (or other approved equivalent) compacted to at least 100 percent of standard Proctor maximum dry density (ASTM D 698) within 2 percent of optimum moisture content. Unevenness in the excavation bottom can be leveled with a course of low strength concrete or flow fill.
- 2. The mat foundation should be designed for a maximum net allowable soil pressure of 1,000 psf.
- 3. Reinforced slabs are typically designed using a modulus of subgrade reaction. We recommend use of a modulus of 60 pounds per square inch per inch of deflection (pci).
- 4. Lateral load applied to mat foundations can be resisted by friction between the concrete at the base of the mat and the ground and by the passive pressure of densely compacted backfill and/or undisturbed ground against the side of a mat provided that soil will not be removed over the life of the structure. A friction coefficient of 0.35 can be used between the foundation concrete and the natural soil, backfill or bedrock. The passive earth pressure against a mat can be calculated using an equivalent fluid density of 250 pcf for undisturbed soil or engineered fill. Graphical presentations of typical lateral loading configurations are presented in Figure 7 of this report. A moist unit weight of 125 pcf can be assumed for natural soils and compacted granular backfill. These values are considered ultimate values and appropriate factors of safety should be used. Typically, a factor of safety of 1.5 is used for sliding and 1.6 for lateral earth pressure.
- 5. The edges of the mats should be thickened or turned down for structural strength.
- 6. Materials beneath the mat foundation should be protected from frost action. Normally, 30 inches of frost cover is assumed in this area.
- 7. The completed foundation excavation should be observed by our representative to verify the subsurface foundation conditions are as anticipated from our borings and are suitable for supporting the mat foundation. Placement and compaction of fill should be observed and tested.



SLABS-ON-GRADE

We understand some portions of the plant improvements will require slab-on-grade floors and/or exterior paved walkways. The majority of the planned improvement area is covered with existing fill. We recommend removing the existing fill under slab-on-grade floors and replacing it with densely compacted, engineered fill as discussed above in the <u>Fill Placement</u> section of this report or remove existing fill and reuse it as compacted fill placed at high moisture content. The use of engineered fill under slab-on-grade floors will reduce the potential for damaging movement of slab-on-grade floors more than will the use of the soils from the existing fill.

If the existing fill soils are planned to be removed and replaced as compacted fill, after removal they should be moisture conditioned to 1 percent above to 3 percent above optimum moisture content (ASTM D 698), replaced in 8-inch maximum loose lifts and compacted to at least 95 percent of standard, maximum, dry density (ASTM D 698) with a heavy tractor towed roller or self-propelled compactor. The placement of this compacted fill should be observed and tested by a representative of our firm. In addition, we suggest:

- 1. Separating the floor slab from all foundation walls and foundations with a joint and provide reinforcement continuous through interior control joints;
- 2. Eliminating underslab plumbing where feasible or where such plumbing is unavoidable, place it in concrete pipe trenches and pressure test it during construction for leaks. Piping passing though floor slabs should be isolated from the slab;
- 3. Plumbing and utilities that pass through the slabs should be isolated from the slabs and/or constructed to permit movement of the slab without causing damage to either the slab or the utilities;
- 4. Separating exterior concrete flatwork and sidewalks from the structures. These slabs should be reinforced to function as independent units. Movement of these slabs should not be transmitted directly to the foundations of the structure; and



5. Providing frequent control joints in all slabs to reduce problems associated with shrinkage. We recommend following the criteria set down by ACI.

The above will not prevent damage should floor slab movement occur but such damage should be reduced for a comparatively small investment.

BELOW GRADE WALLS

All below grade walls should be designed for lateral earth pressures. Many factors affect the value of the design lateral earth pressure. These factors include, but are not limited to, the type, compaction, slope, and drainage of the backfill, and the rigidity of the wall against rotation and deflection. For a very rigid wall where negligible or very little deflection will occur, an "at-rest" lateral earth pressure should be used in design. For walls that can deflect or rotate 0.5 to 1 percent of the wall height (depending upon the backfill types), lower "active" lateral earth pressures are appropriate. Our experience indicates similar walls can deflect or rotate slightly under normal design loads and that this deflection results in satisfactory wall performance. Thus, the earth pressure on the walls will likely be between the "active" and "at-rest" conditions. Graphical presentations of typical lateral loading configurations are presented in Figure 7 of this report.

If on-site soils are used as backfill and the backfill is not saturated, we recommend design of foundation walls at this site using an equivalent fluid density of at least 45 pound per cubic foot (pcf) for the "active" condition. This value assumes deflection; some minor cracking of walls may occur. If very little wall deflection is desired, higher design density may be appropriate. Design for an "at-rest" condition should use an equivalent fluid density of 55 psf. We suggest assuming a "passive" equivalent fluid density of 250 pcf to calculate soil resistance. This equivalent fluid density does not include allowances for hydrostatic pressures or surcharge loads. The structural engineer should also consider site-specific grade restrictions on the behavior of the walls. If a drain is not installed the equivalent fluid density values discussed above will need to be

increased below the free water surface to account for the hydrostatic pressure acting upon the wall.

HYDROSTATIC UPLIFT

The plant additions are all anticipated to be above the groundwater levels encountered during our field testing. Buoyant force uplift caused by hydrostatic pressure is not expected to affect the structures as currently planned. If the planned structures change in the future to include facilities deep enough to be below the groundwater surface, hydrostatic uplift should be included in the design.

The effect of hydrostatic uplift will depend upon the relationships between the weight and elevation of the contents of a structure and the groundwater elevation at any given time. Floors for structures and tank bottoms will experience uplift when they are emptied for cleaning or maintenance or if they do not remain filled above the groundwater level.

Hydrostatic uplift can be relieved by a permanent dewatering system for individual structures, or they will need to be designed and constructed as a heavy, watertight structure capable of resisting a buoyant force consistent with a groundwater rise. We recommend a wet density of 120 pcf for backfill used to "weight" structures. However, backfill that is under water will be buoyant, reducing its density by the density of water. Hydrostatic uplift can be resisted by "tying" structures to deeper, competent soil layers. Anchors can be installed into the bedrock and attached to the structures.



PIPES AND UTILITY CONNECTIONS

Thrust Blocks

Thrust blocks should bear against undisturbed soil at least 3 feet below the ground surface. For thrust restraint, passive earth pressure theory is applicable. We suggest assuming an equivalent fluid density of 300 pcf and a net allowable soil bearing pressure of 2,000 psf to calculate soils resistance for the "passive" earth pressure condition.

Pipe Bedding

We believe sewer pipe is normally bedded in manufactured granular material in accordance with the pipe manufacturer specifications. We believe that sanitary sewer pipe bedding consisting of material that conforms to Larimer County or City of Loveland sanitary sewer design and construction requirements will meet typical requirements. We believe angular crushed rock, conforming to CDOT #67, specifications is usually acceptable bedding material. Squeegee or sand normally is not considered acceptable bedding material. We do not recommend the natural soils or the claystone bedrock encountered on the site be used as bedding material. We recommend bedding material meet current county specifications and be confirmed with the pipe manufacturer.

Modulus of Soil Reaction

We have been requested to provide the modulus of soil reaction (E') for flexible pipe wall design in accordance with ASTM F679 for the site soils. We have used our laboratory test data, and Table 3.4 of "Buried Pipe Design, Second Edition" (A.P. Moser, 2001), to estimate the modulus of soil reaction for the various soil types encountered below the site. We recommend the parameters presented in Table A below.



TABLE A
Modulus of Soil Reaction

	E' for Degree of Compaction of Bedding (psi)				
Soil Type – Pipe Bedding (Unified Soil Classification)	Dumped	Slight <85% Proctor, <40% relative density	Moderate 85-95% Proctor, 40-70% relative density	High >95% Proctor, >70% relative density	
Claystone*	0	50	100	400	
Sandy to Silty Clay (CL, ML)	50	200	400	1000	
Clayey to Silty Sands (SC, SM) and Clayey Gravels (GC)	100	400	1000	2000	
Gravelly Sands (SW) and Sandy Gravels (GW)	200	1000	2000	3000	
Crushed Rock	1000	3000	3000	3000	

NOTE: *Claystone should not be used as bedding material

ENVIRONMENTAL CORROSION

A sample of the clayey sand was tested for soluble sulfates and pH. Soluble sulfates were measured at 0.011 percent, and pH was measured at 8.6. The results of testing are summarized on Table I.

Concrete that comes into contact with soil and/or bedrock can be subject to sulfate attack. Sulfate concentrations less than 0.1 percent indicate Class 0 exposure to sulfate attack for concrete that comes into contact with the soils, according to the American Concrete Institute (ACI). For this level of sulfate concentration, ACI indicates any type of cement can be used in concrete that comes into contact with the soils.



In our experience, superficial damage may occur to the exposed surfaces of highly permeable concrete, even though sulfate levels are relatively low. To control this risk and to resist freeze-thaw deterioration, the water-to-cementitious material ratio should not exceed 0.50 for concrete in contact with soils that are likely to stay moist due to surface drainage or high water tables. Concrete should be air entrained.

SURFACE DRAINAGE

Performance of flatwork and foundations are influenced by changes in subgrade moisture conditions. Carefully planned and maintained surface grading can reduce the risk of wetting of the foundation soils and subgrade. We recommend the following precautions be observed during and maintained after the completion of the building:

- 1. Wetting or drying of the open foundation excavation should be avoided.
- Positive drainage should be provided away from foundations. We recommend a minimum slope of at least 5 percent in the first 10 feet away from the foundations in landscaped areas, where possible. Pavements and sidewalks adjacent to the building should be sloped for positive drainage away from the building. Water should not be allowed to pond on pavements.
- 3. Backfill around foundations should be moisture treated and compacted as discussed in <u>Fill Placement</u>.
- 4. Roof drains of adjacent structures should be directed away from the planned improvements. Downspout extensions and splash blocks should be provided at discharge points. Where downspouts discharge onto pavement, the pavement should be sloped away from the structure. If roof discharge is piped below slabs or flatwork, the pipes should be solid and glued at joints.
- 5. Landscaping should be carefully designed to minimize irrigation. Irrigation should not be located within 5 feet of the foundation. Sprinklers should not discharge within 5 feet of foundations. Irrigation should be limited to the minimum amount sufficient to maintain vegetation; application of more water will increase likelihood of slab and foundation movements.

6. Impervious plastic membranes should not be used to cover the ground surface immediately surrounding the building. These membranes tend to trap moisture and prevent normal evaporation from occurring. Geotextile fabrics can be used to limit weed growth and allow for evaporation.

RESTORATION

Any pavements, sidewalks, curb and gutter, or other structures disturbed during construction should be replaced in accordance with Larimer County and City of Loveland requirements. Pavement repairs should meet, or exceed, existing pavement thickness in the area of construction.

Areas outside pavements should be graded following backfill to follow the contours and merge with adjacent terrain without noticeable breaks. Grading should be arranged to produce a reasonably smooth, well-drained finish with minimal erosion.

LIMITATIONS

Although our borings were spaced to obtain a reasonably accurate picture of subsurface conditions, variations in the soils and bedrock not indicated in our borings are always possible. We should observe pier hole drilling and footing excavations to confirm soils are as we anticipated from our borings. Placement and compaction of compaction fill, backfill, subgrade, and other fills should be observed and tested by a representative of our firm during construction.

This report was prepared from data developed during our field exploration, laboratory testing, engineering analysis, and experience with similar conditions. The recommendations contained in this report were based upon our understanding of the planned construction. If plans change or differ from the assumptions presented herein, we should be contacted to review our recommendations.



We believe this investigation was conducted in a manner consistent with that level of skill and care ordinarily used by members of the profession currently practicing under similar conditions in the locality of this project. No warranty, express or implied, is made.

If we can be of further service in discussing the contents of this report or in the analysis of the building and pavement from the geotechnical point of view, please call.


CTL | THOMPSON, INC. by

R.B. "Chip" Leadbetter,

Geotechnical Department Man

Robin Dornfest, PG

Engineering Geologist











NOT TO SCALE

TUXHORN BOULEVARD





LEGEND:

TH-1

INDICATES APPROXIMATE LOCATION OF EXPLORATORY BORING.

Locations of Exploratory Borings

		NO CONTRACTOR OF THE CONTRACTO
		200
:		
		**
		DERECTOR STATE AND ADDRESS OF THE AD
		A SA
		ST PRODUCTION OF THE PRODUCTIO
		200 ACC ACC ACC ACC ACC ACC ACC ACC ACC A

LOVELAND WWTP HEADWORKS CTL | T PROJECT NO. FC03906-125



LEGEND:

APPROXIMATELY 6 INCHES OF ASPHALT AT SURFACE

FILL, SANDY CLAY OR CLAYEY SAND, GRAVELLY, VERY LOOSE TO LOOSE, MOIST TO VERY MOIST, BROWN

SAND, CLAYEY, LOOSE TO MEDIUM DENSE, MOIST TO VERY MOIST, BROWN, GRAY, RUST

SAND, GRAVELLY, SLIGHTLY CLAYEY, MEDIUM DENSE, VERY MOIST, BROWN

CLAYSTONE, HARD, SLIGHTLY MOIST TO MOIST, BROWN, GRAY, RUST

DRIVE SAMPLE. THE SYMBOL 8/12 INDICATES 8 BLOWS OF A 140-POUND HAMMER FALLING 30 INCHES WERE REQUIRED TO DRIVE A 2.5-INCH O.D. SAMPLER 12 INCHES.

☑ WATER LEVEL MEASURED AT TIME OF DRILLING.

WATER LEVEL MEASURED TWO DAYS AFTER DRILLING.

INDICATES DEPTH WHERE HOLE CAVED.


 INDICATES APPROXIMATE BOTTOM OF SLAB ELEVATION OF NEAREST PROPOSED STRUCTURE.

NOTES:

- THE BORINGS WERE DRILLED ON FEBRUARY 19, 2007 USING 4-INCH DIAMETER CONTINUOUS-FLIGHT AUGER AND A TRUCK-MOUNTED DRILL RIG.
- APPROXIMATE BORING LOCATIONS AND ELEVATIONS WERE SURVEYED BY A
 REPRESENTATIVE OF OUR FIRM REFERENCING THE TEMPORARY BENCHMARK SHOWN
 ON FIGURE 1.
- THESE LOGS ARE SUBJECT TO THE EXPLANATIONS, LIMITATIONS AND CONCLUSIONS IN THIS REPORT.


•






Swell Consolidation
Test Results FIGURE 3









Gradation **Test Results**

PLASTICITY INDEX

GRAVEL









SILT & CLAY PLASTICITY INDEX

47 % LIQUID LIMIT











EARTH PRESSURE



$$P = Y_A * H psf$$


CANTILEVER WALL (Active Condition)





$$P = 0.6 * \gamma_A * H psf$$


BRACED OR TIE-BACK EXCAVATION






$$P_1 = Y_A * (1/2h_s)$$
 psf
 $P_1 = Y_A * (h+1/2h_s)$ psf

CANTILEVER WALL-SLOPING BACKFILL (Active with Surcharge)





$$P = \gamma_o * H psf$$

BASEMENT WALL (At-Rest Condition)

Example Lateral Earth Pressure **Distributions**



SUMMARY OF LABORATORY TEST RESULTS

и-				п-			1	7		7				γ	_	_	
The state of the s	SOII TYPE	9		SAND CLAYEY (SC.)		SAND, CLAYEY (SC)	CLAYSTONE		FILL, SAND, CLAYEY	FILL SAND CLAYEY	SAND GRAVELLY (SD)	CITY CAMP OF AVEN	FILL, DAND, CLAYEY	SAND, CLAYEY (SC)	FILL SAND OF AVEV	CAND CLANCY OCT	
PASSING	NO. 200	SIEVE	(%)		ı	42			45	37	LC.				7.7	1	
SOLUBLE PASSING	SULFATES NO. 200		(%)											0.011			_
	품				1			Ī						8.6		1	-
ERG LIMITS!	L APPLIED LIQUID PLASTICITY	INDEX	(%)					4.5	?.								•
ATTERB	CIONDI	LIMIT	%					30	8								-
L TEST DATA ATTERBERG LIMITS	APPLIED	PRESSURE LIMIT	(PSF)				1,000										
SWELL	SWELL		(%)				3.0										_
		DENSITY	(PCF)	110	***		116	110	2	113	121	114		121	112	118	
	DEPTH MOISTURE	CONTENT	(%)	10.9	707	- 0	16.4	186	2	13.0	7.7	16.8		10.6	16.2	13.1	-
			(FEET)	4	c	ກຸ່	14	4	,	5	24	4	1	.	4	14	
	TEST	HOLE	9	۳	•	,	,	^	,	2	2	8	,	9	4	4	



Section 8 – Technical Support Appendices

Appendix 8.E Soil Test Results


See discussion on site characterization report under Appendix 8.D.

Section 8 – Technical Support Appendices

Appendix 8.F Preliminary Effluent Limits

Since this WWUP is not associated with any specific project, no projectspecific preliminary effluent limits were obtained. The City will obtain preliminary effluent limits as required for future projects.

In February 2007, the City applied for a renewal of their existing discharge permit. The permit was due to expire on July 31, 2007. The City received a letter dated July 31, 2007 (enclosed) that the State was in receipt of the permit renewal application and that the WWTP should continue to abide by the limits of the existing permit until a new permit is issued. A new permit has not been issued to date. The permit renewal application is also enclosed.



STATE OF COLORADO

Bill Ritter, Jr., Governor James B. Martin, Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S. Denver, Colorado 80246-1530 Phone (303) 692-2000 TDD Line (303) 691-7700 Located in Glendale, Colorado Laboratory Services Division 8100 Lowry Blvd. Denver, Colorado 80230-6928 (303) 692-3090

CITY OF LOVELAND, CO

Colorado Department of Public Health and Environment

http://www.cdphe.state.co.us

July 31, 2007

Water & Power

AUS 0 1 2007

STEPHEN C. ADAMS, WATER UTILITIES MGR LOVELAND, CITY OF 200 NORTH WILSON AVENUE LOVELAND, CO 805376017

RE: Administrative Extension

WASTEWATER TREATMENT FACILITY

Permit No.: CO-0026701

Dear Mr. Adams:

The discharge permit issued to you for your facility will expire on <u>July 31, 2007</u>. The Water Quality Control Division has determined that your application for renewal of the permit is complete. We are in the process of developing a renewal permit, but the review procedures required by law have not been completed. Accordingly, we are giving you notice by this letter that your previous permit remains in effect under Section 104(7) of the Administrative Procedures Act, C.R.S. 1973, 24-4-101, et seq (1982 repl. vol. 10).

All effluent limitations, monitoring requirements, and other permit terms and conditions in your current permit will remain in effect until your new permit is issued.

Sincerely,

Loretta Houk, Administrative Assistant

Water Quality Protection Section

Lotta Nonk

WATER QUALITY CONTROL DIVISION

xc: Environmental Protection Agency, Gregory Davis, Permits Team Leader (8P2-W-P) Larimer County, Local Health Department Jennifer Miller, D.E., Technical Services Unit, WQCD Permit File

/lh

City of Loveland Wastewater Treatment Facility

CDPS Permit No. CO-0026701

Domestic Wastewater Discharge Permit Application

Prepared for





City of Loveland

Prepared By

CHZMHILL

February 2007





Department of Water and Power

Service Center • 200 N. Wilson Avenue • Loveland, CO 80537 (970) 962-3000 • Fax (970) 962-3400 • TDD (970) 962-2620 www.cityoffoveland.org

February 8, 2007

Mr. Andrew Ross
Colorado Department of Public Health and Environment
Water Quality Control Division
WQCD-WQP-B2
4300 Cherry Creek Drive South
Denver, Colorado 80246-1530

Subject: Application for Permit Renewal

City of Loveland Wastewater Treatment Plant, Larimer County

CDPS Permit Number CO-0026701

Dear Mr. Ross:

Enclosed are three copies of the City of Loveland's application for renewal of the permit for its wastewater treatment plant, CDPS Permit No. CO-0026701.

The City requests a reduction in monitoring frequency in the renewal permit as allowed for in the Division's policy titled, "Baseline Monitoring Frequency, Sample Type, and Reduced Monitoring Frequency Policy for Industrial and Domestic Wastewater Treatment Facilities" based, at a minimum, on the City's participation in the Big Thompson Watershed Forum monitoring program. The City has been participating in this ambient monitoring program for eight years. We believe that this monitoring program meets the requirements for reduced monitoring frequency under "Ambient Water Quality Monitoring."

If additional information is needed, please contact John McGee of my staff at 970-962-3760 or myself with any questions.

Sincerely,

Ç.

Stephen C. Adams

Water Utilities Manager

Michael McCrary, City of Loveland

AI Paquet, CH2M HILL Pat Nelson, CH2M HILL




Table of Contents

Permit Application

Attachments

Attachment A

- Service Area Map

Attachment B

- List of Commercial Users

- List of Industrial Users

Attachment C

- Process Flow Schematic

Attachment D

- Location Map

Attachment E

- Site Layout Map

Attachment F

- Summary of Upstream Data Parameters

- CD of Upstream Data

Attachment G

- Evaluation of Treatment Facility Capacities

- Process Analysis Technical Memorandum

Attachment H

- Map of Lift Station Locations

Attachment I

- Answer to Question 24.A Regarding Staffing Plan

- Water and Power Department Organization Chart

- Chain of Command Organization Chart

- Answer to Question 24.B Regarding Emergency Response Program

Attachment J

- Answer to Question 24.C Regarding Chemicals Used at Facility

- Material Safety Data Sheets

Attachment K

- Answer to Question 25.C Regarding Analytical Procedures Used

Attachment L

- Answers to Questions 28 through 32 Regarding Biosolids Handling

Attachment M

- Answer to Question 33.A Regarding Pollutants Believed to be in the Influent

- Answer to Question 33.D.1 through 33.D.5

- Procedures to Identify Industrial Users

- Wastewater Discharge Analysis for McKee Medical Center

- Pretreatment Influent Data and Percent Removal During Treatment

- Analytical Methods Used for Pretreatment Monitoring

- Pretreatment Ordinance

- High Strength Sewer Surcharge Rates

Permit Application

DOMESTIC WASTEWATER DISCHARGE APPLICATION

	<u>FOR AGENCY USE ONLY</u> <u>PERMIT NUMBER</u>
	<u>CO-/////</u>
	DATE RECEIVED
	YEAR/MO/DAY
Do not	attempt to complete this form before reading the accompanying instructions.
	PLEASE PRINT OR TYPE
<u>SECTIO</u>	ON 1 - GENERAL INFORMATION
1. A.	Facility Name City of Loveland Wastewater Treatment Facility
В.	This application is for [check the appropriate space(s):] New permit Renewal of existing permitX
	Surface Water discharge X Ground-Water discharge (a) Impoundment (b) Land Application (c) Septic System > 2000 gpd
<i>C</i> .	Existing permit number (if applicable): CO-00_26701
D.	Type of facility ownership (municipality, sanitation district, private individual, corporation, etc.)
	Municipality
	Federal Taxpayer (or Employer) ID#: 8 4 6 0 0 6 0 9
the ma	e, address and telephone number of the legal owner of the wastewater treatment facility producing the discharge. Where facility is owned by a city, town, special district, etc., provide the name of the ranking official (mayor, city/town mager, president, board chairman, etc.) who is legally registered with the Secretary of State's Office and in good nding or the names of any individual who is a part owner of the facility.
A.	Legal Owner, Title Mr. Stephen C. Adams, Water Utilities Manager
В.	Mailing Address 200 North Wilson Avenue
	City Loveland State Colorado Zip Code 80537
C.	Telephone Number (970) 962-3000
	Area Code

Α.	Legal description	(1/4, 1/4 Section, T	ownship, Range, and latitude-longitude)	
	T5N. R68W. SE	1/4, NW 1/4, Section	<u>19</u>	
В.	Street Address (#,	City, Zip Code)	920 South Boise, Loveland, Colorado 80537	<i>i</i> -
<i>C</i> .	County Lari	mer		
4.Oper	ator Information			
1.	Certified operator	· in charge (Name, (Classification, and Number)	
	Mr. Michael McC	rary (interim Waste	water Treatment Manager and Lead Operator). Class A Wastewater Certification
	No. 1214			
В.	Telephone Numbe	r <u>(970) 962-25</u>	<u>72</u>	
	,	Area Code		
С.	Is the facility open	rated by an individu	al or a company through a written contract?	Yes No_X
	If yes, complete th	ne following:		
	Operator	Not applicable		
	Mailing Address			
	City	State	Zip Code	
	Telephone Numbe			
		Area Code		
D.		any owner/operator the permit. Not ap	agreements which are currently in effect or tolicable.	hat are scheduled to be in effect
<u>SECTI</u>	ON II - SERVICE A	REA AND POPUL	<u>4TTON</u>	
an			it and the service area has not changed since legal boundaries of the service area. See A	
6.Prov	ide a breakdown of	the number and typ	e of existing taps in the service area as follow	rs:
<u>Ty</u>	pe of Tap	<u>Number</u>	Description (attach list if necessary)	Total Estimated Flow*
<u>Re</u>	sidential	21,046	Residential Taps	5.0 MGD
<u>]ne</u>	dustrial	278	See Attachment B	0.08 MGD
<u>Cc</u>	mmercial	2,296	See Attachment B	0.8 MGD
<u>01</u>	her (specify)			
,	Fotal estimated flow ow at the WWTP of		proportioned consumptive water use for 2006	for each type of tap and an average
		esign flow of 1 MGL oe of business. See) or greater shall provide a list of non-resider <u>Attachment B</u>	ntial customers which includes the
7.Wha	t is the population o	of the service area?	65,000	
8.Mun	icipalities or Areas	Served		

8.

3.Location of facility

Identify any agreements, for the acceptance and treatment of wastewater, with connector systems, districts, subdivisions, counties, cities, or other agencies or persons within or outside the defined service area.

None, No connector districts

SECTION III - FLOWS AND DISCHARGES

9. Provide the following data on influent flows to the facility during the past calendar year. Effluent flow data may be substituted where that is no influent flow measuring and recording or totalizing device.

Average daily flow (MGD) during the three minimum flow months, month February month March month April flow 5.25 flow 4.82 flow 5.30

Average daily flow (MGD) during the three maximum flow months. month June month July month Aug flow 6.90 flow 6.81 flow 6.89

Maximum peak hourly flow (MGD) 13.5 MGD

10. For each surface water discharge point from the treatment facility indicate the type of discharge (continuous, intermittent, seasonal, etc.), legal description (1/4 of 1/4 Section, Township, Range) and the name and description of the receiving water for each.

Outfall Number Legal Description

Typical Months

Receiving

Latitude/Longitude

(T, R, S, 1/4, 1/4)

of Discharge

Water

of each outfall

(Existing Permit)

T5N, R68W, Sec. 19, SE 14, NW 14 Continuous Big Thompson River 40° 23' 03.16"/ 105° 03'

Method Used

001A 07.40"

11. For a discharge to a ditch provide a copy of: 1) any agreement with the ditch owner which authorizes the discharge and; 2) the notification to the owner that this application is being made and a copy sent to the Division. Not Applicable

- 12. Does facility accept septage? If yes, provide description of procedures and quantities. Septage is not accepted at the plant.
- 13.1s or will land application of any wastewater be practiced? Yes_NoX If yes, answer question 14. If no, go to question 15. Nonpotable waters are used for irrigation of the plant site.
- 14. Provide the information requested in Appendix D and D-2. Not Applicable The Division may request additional information before the permit can be issued.
- 15. Bypassing and Overflow Points for Surface Water discharges and for Ground-Water discharges, as appropriate
 - A. On a separate sheet, provide a diagram/map illustrating 1) the location of any bypass and/or constructed overflow point(s), 2) the receiving water, and 3) a description of any bypass and/or constructed overflow point(s) at the treatment facility that are not described in a current permit for the facility. Also provide this information for any lift station or any point in the collection system.

See Attachment C for a process flow schematic for bypasses at the treatment facility. The only overflow points, designated as OF on the schematic, occur after preliminary treatment and bypass primary and secondary treatment. Secondary settling and disinfection treatment would still occur for the overflow.

There are no known bypasses or overflows to receiving waters that can occur in the collection system. However, there are three lift stations that have overflows to containment areas. These include the East Side Lift Station, the Horseshoe Lake Lift Station, and the Mountain View Lift Station, as described below.

- East Side Lift Station: 148,000 gallon retention pond and 138,000 gallons of interceptor (used in case all backup pumps and power fails). Provides an average of 3.0 hours of retention time.
- Horseshoe Lake Lift Station: This Duplex lift station is equipped with two secondary wet well storage manholes upstream of the lift station wet well. In the event of a power outage and standby generator failure, the secondary wet wells would begin to fill. The secondary wet wells have a total volume of 7,370 gallons, which provides a storage time of 2 hours based average design flow.
- Mountain View Lift Station: This duplex station is equipped with a single secondary containment manhole upstream of the lift station wet well. In the event of a power outage and standby generator failure, the

secondary containment will begin to fill. The secondary containment has a total volume of approximately 3,000 gallons, which would provide a storage time of about 3 hours at average design flow.

B. Include a general discussion of what conditions would cause a discharge from any such point to occur.

There are no locations where a bypass can occur directly to the River. A loss of the influent screw pumps at the treatment facility, such as from a power outage would cause a controlled overflow to occur after preliminary treatment. The waters would go to the final clarifiers where some settling would occur and flow through the UV disinfection facilities. Standby power is provided for the UV disinfection facilities and the WWTP has dual electric circuits that are manually switched following an outage.

It is unlikely that a discharge to a receiving water would occur from any of the lift stations. See the answer to Question 23.C regarding the emergency systems in place to prevent a discharge from the lift stations.

16. Submit a location map showing the facility property and discharge points. The map shall be from a 7-1/2 or 15 minute USGS quad sheet or a map of comparable scale. A north arrow shall be shown. Any public water supply intakes within a 5 mile radius of the facility shall also be identified.

See Attachment D. Please note that there are no public water supply intakes on Big Thompson River within a five-mile radius of the discharge point. The Greeley water supply intake is in Boyd Lake.

17. Submit a diagram of the site which shows appurtenant facilities (buildings, ponds, diversion ditches, treatment processes, etc.), the stream location, numbered discharge points, influent monitoring and effluent compliance sampling points, bypass points and flow monitoring points. The diagram shall be 8 1/2 x 11 inches. A separate treatment process flow schematic may also be submitted.

See Attachment E for the site layout map.

SECTION IV - RECEIVING WATER INFORMATION

18.1s analytical data required to be submitted?	Yes	No X_
If yes, see Appendix G*		

No parameters were checked in Appendix G. Per Lynn Kimble, if no parameters are checked then no samples are required. However, the Big Thompson Watershed Forum and the USGS have been implementing a monitoring program along the Big Thompson River. This program includes a monitoring station upstream of the City of Loveland Wastewater Treatment Facility. The results of the upstream monitoring can be found on a CD in Attachment F. No separate sampling was performed for the application.

Sample Effluent	Yes	No	X	No	paramet	ers w	ere ch	ecked in Appendix G.
								No parameters were checked in Appendix G. Howeve
unstream data are	e includ	ted on	a CD	in At	tachme	nt F.		

*Parameters indicated by an "x" in Appendix G shall be submitted from at least one composite sampling (grab sampling for lagoons) of each discharge point plus at least one representative sample of state waters upstream of each discharge. See instructions accompanying this application for more information on sampling.

19. Provide a copy of any studies or other analyses which you feel may help the Division in its development of effluent limitations for your facility. This would include sampling data for pH and temperature, instream sampling and analyses upstream or downstream of the discharge, modeling results, etc. If this information has previously been submitted, provide a copy with this renewal application. See Attachment F.

SECTION V - TREATMENT FACILITIES AND SEWER SYSTEM

20.Treatment Facility Design Capacity

A. Provide design calculations and other engineering data which define the organic and hydraulic capacity of each unit process and the facilities as a whole. If this information was provided with the application for an existing permit, then provide information on any changes or additions at the facility since that time. Plans and specifications and engineering design studies must be certified by a registered professional engineer. Upgrades have been made to the wastewater treatment plant as well as a rerating of the plant to 10 MGD. See Attachment G for unit design capacities.

1

- B. When did the facility first begin operating? <u>1963 The last time the WWTP was modified was in 2006 and the ongoing modifications are due to be completed in the spring of 2007.</u>
- C. If this is a lagoon system, please provide verification that the lagoons are lined and provide information pertaining to the liner. Do these lagoons meet the allowable seepage rate requirement of less than or equal to 1 x 10⁻⁶ cm/sec? If the lagoons do meet the allowable seepage rate, please submit documentation showing this information. (Also, see Appendix D and D1 of this application.)

 Not applicable.
- D. Has there been an expansion or rerating of the facility since the last permit was issued? Yes X No The City submitted an application for site amendment to rerate the plant for an increase in the permitted flow. The rerating is dated in October 2004, and corrections to the permit were made in June 2005.
- E. Date(s) and Number(s) of the original site approval for the facility and any amendments.

The plant was originally constructed in the 1950's. The City has been unable to locate the original site approval. The most recent site application was approved May 21, 2003 and amended February 2, 2006.

21.Collection System-Infiltration/Inflow

A. Does the 30-day average flow to the facility exceed 120 gallons/capita-day during any month? Yes___No_X If so, attach a discussion of the extent of the problems (quantities, sources, etc.) and any ongoing or proposed correction programs (including scope and budget of programs). Attach a copy of the pertinent portions of any 1/1 studies which have been completed.

Per capita flows have not exceeded 120 gallons/capita-day since 1999. The City is not currently performing any I/I studies.

- B. Attach a description of any ongoing sewer system maintenance/repair/rehabilitation programs.

 The City has an annual contract with Dale's Environmental Service (DES) for cleaning and inspecting sewer lines.

 The annual contract is for \$135,000 at a unit price of \$0.35 which equates to approximately 386,000 feet or 73 miles of sewers contract cleaned each year. Of the 73 miles cleaned, DES will inspect 10% or over 7 miles of the sewers using closed circuit television. The City also contracts with DES for up to \$35,000 per year to conduct additional inspection using closed circuit TV. The City also uses their own crews for cleaning and inspecting sewer lines as required for new connections and regular maintenance. This maintenance and inspection program has greatly improved the conditions of the City's collection system over recent years.
- C. Attach a description of any ongoing interceptor flow monitoring programs if such data is collected. Include a description of monitoring techniques, the locations of monitoring points and any pertinent data.

 The City is not currently performing any ongoing interceptor flow monitoring programs, nor are there any plans to perform an ongoing interceptor flow monitoring program at this time.
- 22.Are any facility or collection system (I/I reduction) expansions or improvements planned during the next five years? If so, describe the extent of the expansions/improvements and list any proposed schedules for planning, design and construction.

The City is planning a rehabilitation / replacement program aimed at "renewing" the wastewater collection system. The major driving forces for this program are to rehabilitate any identified deteriorated sewers (caused by corrosion), reducing I/I, and restoring sewer capacity. Additional funding through a recent rate increase will be devoted to this endeavor. By taking on this program, I/I will be reduced as will other problems associated with maintaining a wastewater collection system. Over the next 5 years, the City is projecting (not yet budgeted) over \$3.2 million on this rehabilitation program. In the summer of 2006, the City of Loveland rehabilitated approximately 3.000 feet of the Fairgrounds Interceptor (30 and 33-inch diameter) and approximately 2.000 feet of 8 to 15-inch diameter sewer lines within the collection system. The rehabilitation was performed using cured in place pipe (CIPP) technology to repair damage due to corrosion and reduce infiltration. A comparison of the pre CIPP and post CIPP video inspection results indicate that the CIPP successfully eliminated the infiltration and restored the capacity of the interceptor.

A. Provide the following information for all lift stations in the service area:

Lift Station Name/No.	Wet Well Volume	# of Pumps and Capacities (gpm and hp)	Current Peak Daily Flow* (MGD)
YOU COLUMN TO COLUMN TO A STATE OF THE STATE	0.475	0.62.161.7760	4.00
Fire Station #2/Taft	9,675 gal	2 @ 10հթ/ 600 ցրու	0.20
Barberry (Cashway Lumber)	338,650 gal	2 @ 5 hp/70 gpm	0.0036
Lakeside Terrace	5,830 gal	2 @ 7.5 hp/100gpm	0.032
Bus Barn (North Lake Estates)	7,640 gal	2 @ 5 hp/125 gpm	0.032
West 29th Street	8,395 gal	2 @ 5 hp/125 gpm	0.028
North Horseshoe	7,520 gal	2 @ 10 hp/ 386 gpm	0.087
South Horseshoe	19,825 gal	2 @ 20 hp/1100 gpm	0.23
Horseshoe Lake	1,100 gal	2 @ 5 hp/175 gpm	0.021
South Side	31,050 gal	3 @ 40 hp/1,859 gpm	0.11**
Boyd Lake	4,335 gal	2 @ 5 hp/150 gpm	0.016
East Side	10,000 gal	2 @ 100 hp/3600 gpm	1.30
Mountain View	1,100 gal	2 @ 3 hp/100 gpm	0.0018
Boedecker	3,085 gal	2 @ 5 hp/80 gpm	0.011
Mariana Cove	7,520 gal	2 @ 3 hp/42 gpm	0.0056
Lakes Place 4 th	9,960 gal	2 @ 3 hp/ 390 gpm	0.022

^{*} Reported are the current estimated daily discharges for a peak day as calculated based on run time and pump capacity. Pump capacity is based on the rated capacity for the lift station. For duplex stations only a single pump is in service.

- B. Include a map which shows the locations of the lift stations. The service area map requested in Question 5 of this application may be used in place of a separate map. See Attachment H.
- C. Describe the emergency systems in place (alarms, dual grid power feed, generators, holding ponds, etc.) which will be used to prevent a discharge from any lift station.

 All lift stations are equipped with standby generators. In the event of a loss of power, an automatic transfer switch will activate the standby generators. If the standby generator would fail, then there could possibly be a lift station overflow once all secondary containment vessels are full. The likelihood of this happening would be very remote. One lift station in the City does not have emergency power, which is the Barberry Station near Cashway Lumber. If this station fails, a high water alarm is activated and the City can respond with a mobile generator for emergency power. All lift stations in the City are remotely monitored by the City SCADA system (RS View with radio/telemetry signal). Each lift station is monitored for pump failure, pump ON/OFF, pump run hours, high water alarm, level in wet well, emergency power ON/OFF, and primary power ON/OFF. The East Side Lift Station is also equipped with a flow meter and is remotely monitored for flow.

SECTION VI - OPERATION AND MANAGEMENT

- 24. Provide the following information for the facility. A <u>current</u> plan of operation which includes this information may be substituted.
 - A. A copy or description of the staffing plan for the facility, including the number of operators and their certification levels, and operating personnel coverage of the facility during weekdays, weekends, and holidays. See Attachment 1
 - B. A discussion or outline of the emergency response program used at the facility. This discussion should include:
 - 1. A description of alternate power sources. See Attachment 1
 - 2. A discussion of alarm systems installed at the facility, including any remote transmission of alarms. See Attachment I
 - 3. A description of the chain of command in emergency situations. See Attachment 1
 - 4. Provide any other information for emergency response. See Attachment I

^{**} South Side Lift Station is operated at 60% speed (1100 gpm), which was used to determine the estimated daily discharge.

Provide these details on separate sheets. If information is not available for any of these items please indicate that this is the case and provide a brief explanation of why the item cannot be discussed or described.

C. Attach a list of any chemicals which are used in the operation of the treatment facility. This includes chemicals added directly to the treatment process (chlorine, copper sulfate, other algicides, alum, etc.) as well as chemicals which are used adjacent to unit processes (ponds, basins, etc.) which may be carried into the treatment system by storm events, snowmelt, etc. MSDS sheets shall be included for any name-brand (Aquashade, Round-up, etc.) products.

See Attachment J for a list of chemicals used at the treatment facility and for the Material Safety Data Sheets.

25. Monitoring and Testing

A. Describe the method of flow measurement for the influent flow to the facility and for each discharge (i.e., V-notch weir, 3-inch Parshall flume, calibrated pumping rate with run-time meter, none, etc.). Also, describe the "range" (minimum-maximum) of any flow metering and recording equipment associated with these devices.

The flow monitoring is unchanged from the previous permit application and is summarized in the table below.

Monitoring Point	Type of Device	Size	Range of Flows	Type of Recorder_Meter (if
			Measured	cary)
3001 (Influent)	Parshall Flume	24 inch	0.273 MGD to 21.4	Ultrasonic Open channel
			MGD	flow transmitter. It also
			Mary Andrews Mary Constitution of the Constitu	totalizes readout.

B. Describe procedures and tests used to determine the accuracy of the flow measuring and recording devices and note how often the devices are calibrated.

Device	Method	Frequency
24 inch Parshall Flume with Ultrasonic flow sensor	No calibration is done to the flume. For the sensor, if a trend of variation over 10% is noted between the manually measured flow from the flume and flow measured by the sensor, the flow sensor unit is recalibrated by the City's Technical Services department. The flow sensor reports alarms and error codes to the operators if there is a system malfunction. Recalibration is performed as necessary to respond to system alarm messages. Recalibration has not been required to date.	The flow sensor reading is checked against a manual measurement of flow from the Parshall flume once per week. Preventive maintenance work is done once per year. This includes checking all electric outputs and calibrations in addition to physical inspection for corrosion, dirt, and moisture.

- C. Attach a description of approved analytical procedures which are used, or will be used, for analyzing each influent and effluent parameter in order to meet the reporting requirements of the permit. Also, describe the location where each analysis is or will be completed and the requirement used for each method not done in the lab. (i.e., BOD₅-Method 5210B from Standard Methods, etc.) Is a commercial or other WWTP laboratory used? If so, identify the laboratory and submit their analytical methods for each parameter.

 See Attachment K for analytical procedures used for influent, effluent and solids analysis and Attachment M for analytical procedures used for the pretreatment program.
- 26.If this application is for renewal of an existing permit and any violations of effluent limits occurred during the period of such a permit, are there any administrative, design, operational, or financial deficiencies which would prevent the applicant from eliminating such violations prior to the issuance of the renewal permit? Yes No X

The applicant shall answer yes if any such deficiencies were previously identified (engineering report, Division inspection, etc.) and have not been eliminated at this time.

There have been no flow limitation violations during the period of the existing permit.

A. If the answer to the above question is yes, then a written report must be included which describes how and when

SECTION VII - BIOSOLIDS HANDLING - BENEFICIAL USE OR DISPOSAL

27.1f facility is a lagoon, last time solids were removed?	MonthYear
Will biosolids be removed within the next 1-5 years?	YesNo
Anticipated date of removal: Year	

Not applicable

28. For a mechanical facility, please attach a short narrative description of the type of treatment (i.e. Class A or Class B), beneficial use (i.e. land application, composting) as described in EPA 503 Regulations/Colorado <u>Biosolids Regulations</u> <u>#164</u>, or disposal method(s) (i.e. landfill, transported to another facility) which are to be utilized.

See Attachment L.

29. Are biosolids being stored at the facility? For how long? No solids are routinely stored on site.

See Attachment L

- 30. Will a contract hauler be utilized? Yes If yes, please give name and frequency used. See Attachment L.
- 31. Please attach a short narrative description on contingency plan for biosolids beneficial use and or disposal practice(s).

See Attachment L.

32. Describe the handling and final disposal method of screenings, grit and any other similar types of material at the facility (i.e. landfill, surface disposal, certificate of designation, storage).

See Attachment L.

SECTION VIII - INDUSTRIAL CONTRIBUTORS AND PRETREATMENT

33.Are industrial wastes, which contain any of the toxic pollutants or hazardous substances listed in Appendix A or B or are from any categorical industry listed in Appendix C, discharged to the sewer system? Yes X No Are there any facilities for acceptance of wastes, other than domestic septage, by rail, truck or dedicated pipeline? Yes No X

If the answers to these questions are no, then answer question 33.B. only.

- A. On a separate sheet, list any of the pollutants found in Appendix A and B which you know or have reason to believe are present in or may be present in the influent to the facility. For every pollutant you list, briefly describe the reasons you believe it to be present and report any analytical data (influent or effluent) in your possession (use separate sheets). If this information has been previously submitted to the Division, please indicate the date of the submittal and who in the Division it was sent to.

 See Attachment M.
- B. Has a list of industrial contributors, including both those referenced in Appendix C and any non-categorical industries, been previously submitted? Yes X No

A list of industrial contributors is included in Attachment B in response to question 6 of this application.

 Identify any industries contributing industrial process wastewater that were not covered by previous submittals.

Woodward Governor Company, 3800 North Wilson Ave., metal finisher

2. Provide procedures for identifying new industrial/commercial dischargers.

Procedures for identification of new industrial users involve various different activities. These are listed in Attachment M.

C. Has an assessment of the quantity and quality of any industrial process wastewater contribution been previously submitted? Yes No X 1. If no assessment has been submitted and is presently available, please provide the data on an attached sheet. The combined domestic and process waste stream from McKee Medical Center was sampled in June of 2006. See Attachment M for the results of the sampling. Has any additional data for industrial wastewaters been compiled which was not previously submitted? No X If yes, please provide the data on an attached sheet. D. If not previously submitted to the Division, provide the following on separate sheets: 1. A discussion of pretreatment provided by each significant industrial user and/or specific treatment, if any, provided at the domestic treatment plan for any industrial waste received. See Attachment M The estimated degree of reduction in the domestic facility of any relevant pollutant listed in Appendices A and B. See Attachment M. 3. A summary or outline of the procedures for monitoring and testing of industrial pollutants generated in the service area. See Attachment M 4. A copy of any pretreatment ordinances and user charge schedules applicable to industrial contributors. See Attachment M 5. A discussion of any problems encountered with contributed industrial wastes and how these problems have been handled. See Attachment M SECTION IX - CERTIFICATION I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment. 2-8-2007 DATE SIGNED Stephen C. Adams Water Utilities Manager NAME (PRINTED) TITLE

Both the owner and the operator must sign the application. Please print clearly. See instructions for definitions of owner and operator.


Michael McCrary

NAME (PRINTED)

Interim Treatment Operations Manager

TITLE

Attachment A



Attachment B

CDOHE
as defined by
Commercial
Profreetment
of Loveiand -
Š

Submary Control of the National Control of the Nat	80537 Art
Subwey 1410 SW 1480 SW 1725 SW 1303 E	
M. CO Twisters Gymnastics LLC 1410 SW 1480 SW 1725 SW 1725 SW 1725 SW 1725 SW 1725 SW 1725 SW 1720 E 1720 SE 1720	
1410 SW 1470 SW 1480 E 1480 E 1480 E 1581 E 158	***
1400 SW 1460 SW 1670	
1460 SW 1470 E 14	
1470 SW 1480 SW 1480 SW 1480 SW 1480 SW 1725 SW 1010 W 1010	80537 Office
1460 SW 1460 SW 1725 SW 1725 SW 1725 SW 1725 SW 1725 SW 1726	
T-Mobile 1450 SW	: \$0537 Hair care
1725 SW 1726 SW 1727 SW 1827 SW 1227	
1010 W W W W W W W W W	80537 Medical
Fe	C. US 80537 Office
1303 E 1303 E 1303 E 1303 E 1303 E 1310 E	80537
1303 E 1310 E 1310 E 1310 E 1410 E 1410 E 1410 E 1410 E 1410 E 1410 E 1510 E 1510 E 1511 E	SOSON SON
1303 E 1310 E	0000
1310 E	
1310 E 1410 E 1410 E 1410 E 1410 E 1511 E 1	75000
N. CO Twisters Gymnastics LLC 410 E 410	1
N. CO Twisters Gymnastics LLC 1410 E 1410 E 1410 E 1510 E	#VV1 80537
1410 E 1510 E 1510 E 1511 E 1	
1410 E 1510 E 1510 E 1511 E 1511 E 1531 E 1551 E 1	,
1510 E 1511 E 1511 E 1531 E 1551 E 1	1/2 80537
1510 E 1531 E 1531 E 1551 E 1	#W3 80537 Vehicles
1511 E 1531 E 1551 E 1	80537
1531	80537 Metal Finishe
1551 E 1551 E 1551 E 1551 E 1551 E 1351 E 135 SE 136 SE 140 SE 174 SE 174 SE 174 SE 187 SE 187 SE 187 SE 187 SE 187 SE SE 187 SE 187 SE 187 SE 187 SE SE SE SE SE SE SE S	80537 Vehicles
1551 E 1951 E 1951 E 135 E 135 SE 135 SE 140 SE 174 SE 174 SE 174 SE 174 SE 187 SE SE SE SE SE SE SE S	80537
1951 E 2105 E 135 SE 136 SE 136 SE 136 SE 137 SE 174 SE 174 SE 174 SE 174 SE 187 SE 187 SE 187 SE SE SE SE SE SE SE S	#B 80537 Score boards
Canine Center of Excellence 2105 E 135 SE 140 SE 174 SE 174 SE 174 SE 177 SE 187 SE 187 SE 204 SE 204 SE 225 SE	80537
135 SE 135 SE 135 SE 136 SE 140 SE 174 SE 174 SE 174 SE 174 SE 187 SE 1	
135 SE 135 SE 138 SE 140 SE 174 SE 174 SE 174 SE 174 SE 187 SE SE 187 SE	
PATRICK KIPPER BRONZE	
140 SE 174 SE 174 SE 1774 SE 187 SE 204 SE 225 SE	
174 SE 174 SE 174 SE 187 SE 187 SE 187 SE 204 SE 204 SE 225 SE	80537
174 SE 174 SE 187 SE 204 SE 225 SE SE	'n
174 SE 187 SE 187 SE 187 SE 187 SE 204 SE 204 SE	80537
187 SE 187 SE 187 SE 187 SE 204 SE 204 SE 225 SE	80537
187 SE LUNA COMPANY 187 SE 187 SE 204 SE 204 SE 225 SE	80537
LUNA COMPANY 187 SE 187 SE 204 SE 204 SE 205 SE 225 SE	80537
187 SE 204 SE 204 SE 225 SE	#2 80537 Office
204 SE 204 SE 225 SE	80537
204 SE 225 SE	80537
225	ĺ
	80537
35.82	80537
233 SE 1	80537 Plumbing
H21 38 121H	(80537 Piumbing

City of Loveland - Pretreatment Commercial as defined by CDPME COMMERCIAL MARKS	Z		Linit Zip Activity
	RICE REPORT TOWNS	207 207 SE	80537
CHACH AND ANOCHARONING		(n)	9
HEARTI AND LABORATORIES (LC		127 SW 12TH ST	ET 80537
HEARTI AND LABORATORIES LLC	and the second of the second o	SW	E-6
Schm dt, Jefrey P	A CAMPAN AND A CAMPAN AND A CAMPAN AND A CAMPAN AND A CAMPANA AND A CAMPAN AND A CA	V.S	E-5
ZASTROW, DICK		V.S	4-대
THOMAS, RONALD	de de la competitación de	Š)	e.
BISON BROTHERS CONSTINC	THE REAL OF STREET, ST	S	E-2
LOVELAND ART CENTER	The company of the property of the company of the property of the company of the	(V)	3008
MILBACH, HERB O	The state of the s	G)	T.
A L PRODUCTIONS INC	The second secon	155 SW 12TH ST	
A PRODUCTIONS INC	And the state of t	SS	D-3
WRICLEY CYNN	BARBARA WOLF STUDIO	V.S	
LOVELAND ART CENTER	A CONTRACTOR OF THE PROPERTY O	Sign	81060
VALPANDO AMY E	A THE TANKS TO SELECT THE TANKS OF THE TANKS	Ś	
SMITH PATTI& THOMAS	and the second second second is the second and the second	163 SW 12TH ST	0F-0
MONINGER WILLIAM	der til det forske skrivere skrivere for det skriver i den skriver skrivere skriver for det skrivere og det skrivere for det skrivere og det skrivere for det s	167 SW 12TH ST	о- О
Smileworks LLC		171 SW 12TH ST	ိုင်
KOKAIN KIRSTEN	AND THE PROPERTY OF THE PROPER	175 SW 12TH ST	C-7
HASKEW, 13	and the second of the second o	179 SW 12TH ST	9-O
WASIE EX LYNN	GLOED FRAMES	183 SW 12TH ST	Ç-2
WOLF BARBARA ANN	a tradición de la company de la compa	187 SW 12TH ST	\$-0
OBSTIN, PATRICIA J	And designed by the control of the c	19 SW 12TH ST	9
Cost Nice		SN	3
Tanner Russell U	A CANADA CANADA MANADA CANADA	Š	5-7
LOVELAND ART CENTER	And the second second property with the second seco	199 SW 12TH ST	
SOS Auto Glass People	and the control of th	S	#114
Knickerbocker Designer inc	entrigen i de	SV	#106
Heusinkveid, Keni	Markei to Markei	200 SW 12TH ST	
Wortson L. Helh	entering and the contract of t	Sis	#126
Knickerbocker Designer inc	o companya da la comp	S	#102
Loveland SW LLC		SV	#110
STANDARD STRUCTURES COLORADO	Standard Structures	SG	BLDGE 80637
GIBSON HEATING & AIR COND		S	
LOVELAND ACADEMY OF FINE ARTS		211 SW 12TH ST	A-1A 80537
The Arts of Living	Yoga by Merkin	217 SW 12TH ST	A-6 80537
MS INTERIORS, LLC		220 SW 12TH ST	#101 80537
MS INTERIORS ILC	and the second of the second o	220 SW 12TH ST	#105 80537
Jorgesen, Hans		Š	
Sellel Steven		VIS.	#113 80537
MIZE & Desp		220 SW 12TH ST	#125 80537
Baker John R	AND THE PERSON OF THE PERSON O	220 SW 12TH ST	#129 80537
NEW NORWAY, LLC	A TANKA MANANA	229 SW 12TH ST	
TISCANY O STON HOWEN	and a fight of the property of	241 SW 12TH ST	
TUSCANY CUSTOM HOMES	The second of th	253 SW 12TH ST	and agree to company a select property of commander comments or company
the second secon	nas indones i databas data data databas da sa sa sa sa sa sa sa da databas databas indonesia da databas da sa d		

COPHE	
as defined by	
Commercial	
Pretreatment	
of Loveland -	
Š	

Soric Loveland Furniture Loveland Furniture Loveland Furniture Loveland Furniture MAGIC CUTS	505 W 12TH ST 1730 W 12TH ST 1730 W 12TH ST 1815 W 12TH ST 2302 E 13TH ST 2305 E 13TH ST 2310 E 13TH ST 2314 E 13TH ST 2322 E 13TH ST 2444 E 13TH ST 2456 E 13TH ST 2462 E 13TH ST 2462 E 13TH ST 2460 W 13TH ST 2400 W 13TH ST 2400 W 13TH ST 2600 E 13TH ST 2400 W 13TH ST 401 W 13TH ST	80537 Storage 80537 Church CHRCH 80537 Church 80537 Church 80537 Construction 80537 Fast Food 80537 Fast Food 80537 Storage
Soric Loveland Furnture Loveland Furnture Loveland Furnture Floyd's Sandwiches Floyd's CUTS	$ \mathbf{x} \leq $	
Soric Soric Loveland Funiture Loveland Funiture Loveland Funiture Royd's Sandwiches Floyd's Sandwiches	$ S \ge S $ m m m m m m m m m m m m m m m $ S \le S $ $ S $ $ S $	
Soric Loveland Furniture Loveland Furniture Loveland Furniture Royd's Sandwiches	$\geqslant \geqslant$ \mod \mod \mod \mod \mod \mod \mod \mod \mod \implies \geqslant \geqslant \bowtie	
Sortic Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches	\geq \square	
Sortic Loveland Furniture Loveland Furniture Loveland Furniture Thyyd's Sandwiches	ᇚᇚᇚᇚᇚᇚᇚᇚᇚᇚᇚᇚᇚ	
Soric Loveland Furniture Loveland Furniture Loveland Furniture Loveland Furniture Royd's Sandwiches	ᆱᇑᇑᇑᇑᇑᇑᇑᇑᇑᇑᇑ	
Soric Loveland Furniture Loveland Furniture Loveland Furniture MAGIC CUTE	ᇚ ᆔᇚᇚᇚᇚᇚᇚᇚᇚᇚᇚᇬ	
E Loveland Furniture Loveland Furniture Loveland Furniture Toyd's Sandwiches Floyd's CUTE	ᄺᄜᇜᇜᇜᇜᇜᇜᇜᇜᇜᇜ ᇑᇜᇬ	
Loveland Furniture Loveland Furniture Loveland Furniture Loveland Furniture Royd's Sandwiches	๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛๛	
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches		80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches		80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches		80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches MAGIC CUTE	ᄱᄢᄢᇜᄝᄝᇎ ᇎᅂ ᄝᅜᄧ	80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537 80537
Loveland Furniture Loveland Furniture Loveland Furniture Loveland Furniture Royd's Sandwiches		80537 80537 80537 80537 80537 Food 80537 Food
Loveland Furniture Loveland Furniture Loveland Furniture Loveland Furniture Royd's Sandwiches	\mathbb{R}^n \mathbb{R}^n \mathbb{R}^n \mathbb{R}^n	80537 80537 80537 80537 Food 80537 Food 80537 Food
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches MAGIC CUTE	\mathbb{R}^n	80537 80537 80537 Food 80537 Food 80537 Food
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches MAGIC CUTE		80537 80537 F090 80537 F000 80537 F000
Loveland Furniture Loveland Furniture Loveland Furniture Loveland Furniture Royd's Sandwiches	៳៳៳៳ៜៜ៳៳៷	80537 F000 80537 F00d 80537 F00d
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches MAGIC CUTE	ᄪᅖᇘᇂᇂᇕᇄᇄ	80537 Food 80537 Bank
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches MAGIC CUTE	ᄪᄪᇂᇂᇶᅄᇄᇄ	SOSS PROPERTY.
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches	ਜ਼≶४%R	
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches	≥ ≥ M m n	#A 80537 Auto
Loveland Funiture Loveland Funiture Loveland Funiture Floyd's Sandwiches	S S C	80537
Loveland Furniture Loveland Furniture Loveland Furniture Floyd's Sandwiches	ល្អ ល ព	
Loveland Furniture Loveland Furniture Floyd's Sandwiches MAGIC CUTS	ក្រ ព	80537
Loveland Furniture Loveland Furniture Floyd's Sandwiches	Li U	80537
Loveland Furniture Floyd's Sandwiches MAGIC CUTE	ָ כ	8
Floyd's Sandwiches MAGIC CUTE	S)	80537
Floyd's Sandwiches MAGIC CUTE	w w	80537
MAGIC CUTE	ស	#2 80537 Food
MAGIC CUTE	S S S	80537
MAGIC CUTE	SE	80537
MAGIC CUTS	S	80537 Food
	ន	80537 Hair care
	S	80537
	W.	80537
	co m	80537
	SE	
	띬	#7 80537 Auto
The state of the s	S.	
Taqueta Jalisco	ខ្ល	80537 Food
Taqueria Jalisco	SE 147H	80537 Food
Zacuera Jalisco	1 SE 147H	80537 Food
an Ocsine	281 SE 14TH ST	80537 Food
Martin, Peggy Ann CHAR IE ELL'S LLC	1 SE 14TH	80537 Bar

	in S	E32,	Dir Sraet		212	Activity
ROSSROADS U-STORE IT		277	SE (14TH ST		80537	Storage
TRAMMEL CROW RESIDENTIAL	and a second of the control of the c	787	SE 14TH ST	LNDRY	80537	Laundry
derean Marren	Warmen Aldonia Algoria	1051	SE 147H ST	14:	80537	Auto
GRANDE VARIETAM O'RE			SE 14TH ST	Z#	80537	A THE RESERVE OF THE PARTY OF T
MACO DE AZ DOCOST LINGON	son the transfer of the production of the produc	ì	SW 34TH ST	And the second s	17	Bank
LONG SECTION CONTRACTOR CONTRACTO	AND THE THE TREE TREE TREE TO THE TREE TREE TREE TREE TREE TREE TREE	1	S/W 14TH ST	BUREU	80537	the second secon
A CONTROL OF THE CONT	the state of the s	į	SW 14TH ST	OFFIC		
ST & MEASUREMENT SYSTEMS INC	the real rate of the real conditions and the conditions and the real parts of the real parts are an expensional transformation of the real parts of the real	ί.	SW 14TH ST		80537	Soltware
TEST & MEASUREMENT SYSTEMS INC	on constructions are explored on a settlement on their contrast of the settlement of	i	SW 14TH ST		80537	Software
ST & WEASUREMENT SYSTEMS INC	der der derste gen der im men nemmen fahresträtigten igsått derfande gallem mårkelminn ter benomflinte de 1900 til minde i der	•	SW:14TH ST		80537	Software
HMIDT'S OLDE TIME BAKERY LTD	The second of the second secon		SW 14TH ST		80537	Вакегу
ATHWAL GURWAIL SINGH	AND THE PROPERTY OF THE PROPER		SW 14TH ST		80537	Gas
MENT TECHNOLOGIES	4	}	SW 14TH ST	EWMT2	80537	Food
ALENT TROUNDOIDE	AND THE RESIDENCE TO THE SAME AND AND THE SAME AND AND THE SAME AND TH		SW 14TH ST	EMTR1		Other
SIENT TECHNOLOGIES	The state of the s		SW 14TH ST	EWMT3	80537	Other
SI FNT TECHNOLOGICALISMS OGIES	TO AND THE PROPERTY OF THE PRO		SW 14TH ST	EMTR4	80537	Other
		3	SW 14TH ST	ECSUB	80537	Other
SECO CATCELLAG	Bergel an attentiation of the properties an application and and the contract of problems of the state of the		SW 14TH ST	ECNTR	80537	
E ENT TECHNOLOGIES	and the second of the second o	ĺ	SW 14TH ST	Angeles 1 - 10-10-11 - 11-11-11 - 11-11-11 - 11-11-11 - 11-11-	80537	Other
CHANTEN CONTRACTOR OF THE CONT	para i caració de altra e i contra proprio de mana mana mana famos distinció defenda calabració despublica consequenció de mana famos de la caración de despublica de la caración de la ca	1	SW 14TH ST	MSTR	80537	Other
Majoraans	11.7	1260	SW 14TH ST	UTIL	80537	Retail
Pefores Charch	erge on a special area of the contract of the	1	SW 14TH ST		80537	Church
TASSESSED	e de la companya del companya de la companya del companya de la companya del la companya de la c	1	n total	The same of the sa	80538	Construction
FOLONGS 1.0	en de la compresa del compresa de la compresa del compresa de la compresa del la compresa de la compresa del la compresa de la		E 15TH ST		80238	
YSTAL RAPIDS	the course from the comment of the properties of the properties of the commentation of the comments of the com	į	E 15TH ST			Entertainment
YSTAL RAPIDS	And a second for the contract of the contract	Ì	E 15TH ST	FILTR	, 1	80538 Entertainment
NNER DEVELOPMENT LLC		1	E 15TH ST	BLDG4		
OGRESSIVE INSURANCE CORP	A CAMPACTURE LANGUAGE OF THE WAY	}	म गुरामध्य	#201	80537	' Insurance
OGRESSIVE INSURANCE OORP			E 15TH ST	#202	*****	Insurance
ANTERIOR LIBRITAGE	AND THE PARTY OF T		E 15TH ST	#102		Office
ASSTANCES TERTAGE	· · · · · · · · · · · · · · · · · · ·	•	ह 151म ऽ1	#103		Office
NNER DEVELOPMENT LLO	and the contraction of the contr	}	后 15TH ST	BLD62	80537	
BENNER DEVELOPMENT LLC	and the second service of the second	1	E 15TH ST	#101		
TRUMBO, DAVID]	E 15TH ST	#202		Insurance
HOUSE, ASSOCIATION TO THE PROPERTY OF THE PROP	And the second s	-	E 15TH ST	#201	80537	
ARNOCK ZEALTY		•	E 15TH ST	#101#	80537	Really
WARNOCK REALTY	And a second state of the contract of the cont		E 15TH ST	#102	80537	
NNER DEVELOPMENT LO	and the second of the second o		E 15th St	BLDG1	80537	
ONT RANGE BANK	inger and management and management and description of the control	1	E 15TH ST		80537	80537 Bank
NO JAKE VETERINARY CENTER	gang displaying ang ang ang ang ang ang ang ang ang a	!	E 15TH ST		80537	Pet care
VAN BUREN SCHOOL	AND]	W 15TH ST		80538	School
ONPSON R2J SCHOOL DIST	TO THE PROPERTY OF THE PROPERT		W 15TH ST	COTTG	80538	School
KER EDWARD	AND THE PARTY OF THE THE PARTY OF THE PARTY	1966	W 15TH ST	유	80538	Office
Premier Massage Therapy Cinic	The second of th	1	W 15TH ST	#£	80538	Office
	是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们就是一个时间,我们	Section and the second section in the second	10 10 10 10 10 10 10 10 10 10 10 10 10 1			

H

by CDPHE	
as defined b	•
Commercial	
Prefreatment	
of Loveland -	
~	

	NO	O SC Num	Dir Street	Cuit	
ACKARD, JAMES			y 15TH ST	#5	œ
KLEN EDWARD		1	V 15TH ST	9#	80538 Office
Nat'l Alliance of Prof Pins Inc	ANALYSIS AND ANALY	1	V 15TH ST	SH	i ac
Monarch Youth Horres, Inc.	and the same of th	1	V 15TH ST	*	80538 Office
Monarch Youth Homes, Inc.	The control of the second of t	i	V 15TH ST	44	80538 Offine
Ionarch Youth Homes	Control of the Contro		V 15TH ST	9# #B	80538 Office
KIN HOWARD	entre de como establista establista de mandramente de la companya de la companya de la companya de la companya	ì	V 15TH ST	Accessed to the second	80538 Office
AHOUREK SYSTEMS INC	and the same of th	:	V 15TH ST	e de la dese des mandres partir en desta dese d _a sacrações y en produções de dese partir de la dese partir de la dese	80538 Videos
ZION AMERICAN OFUROH	AND THE RESIDENCE AND ADDRESS OF THE PARTY O	1	TS H_S	es de deservaçõe de la compansa de constante de la productiva de la produc	80538 Church
OR AMERICAN OLICEOL	A COMPANY OF THE PROPERTY OF T	ì	18TH ST	en regimente anna de anna en calum caración primera, en opera en	80538 Church
& JINVESTMENTS	and the hydrological properties of the decreasing conference parameters of a magnification to be considered.	i	16TH ST		80538
RONSERT, NEIL	American in the constant of the contraction of the	ì	W 16TH ST		80537
EMETH, CLIFFORD	and the state of t	ŧ	18TH ST	#2	. i oo
NEMETH, CLIFFORD	design of the state of the stat		18TH ST	44.	80538 Denial
ESSAGE OF LIFE MINISTRIES	en de la companya de	İ	N 18TH ST	Transmitter de partie de de la companya de la compa	80537 Church
ESSAGE OF LIFE MINISTRIES	A CAMPANE AND	1	M 18TH ST	EWTR2	80537 Church
VANDERBILT'S DBA WHITESIDE'S		:	E 19TH ST	Annual designation of the second seco	80537 Ciothina
suthmarch Veterinary Hospitel		ì	E 19TH ST	and the second s	80537 Vet
HANDY GLASS		į	157.57	ELEC	80537 (Glass
ANDY GLASS		Ì	1STST	WATER	80537 Class
JPER VACUUM MFG CO		1	18787	**************************************	80537 Metal Finisher
ST LOUIS LIQUOR		;	STST		80537 Liquor
MARAJMOFFETT	The state of the s		(STST	ACT AND THE PROPERTY OF THE PR	80537 Tires
MARAJMOFFETT			STST	and the design of the form of the field of the field of the form of the field of th	80537 Tires
Edwards, Meissa			IST ST	1/2	80537 Liquor
MARA J MOFFETT			ISTST		80537 Tires
SUM, JON			187.87		80537
OYDS FURNITURE SERVICE			1ST ST	management of the contract of	80537 Furniture
Robinson, Kirk A	Septien	J 828	ISTSI	EMTR2	80537
and the second	Seption		187.81		80537
			/ (1ST ST		80537 A.1
NUCENT SUPPLY CO			/ ISTST		80537 Supplies
TY P&R SOUTH CENTENNIAL REST		, ;	/ :1ST ST		80537 Park
LOVELAND BASEBALL ASSOC		ĺ	/ '(ST ST		80537 Office
CITY P&R ADATH Centenrial			/ ISTST	BALLE	80537 Park
LOVELAND BASEBALL ASSOC			/ ISTST	•	80537 Office
Klein, Oouglas E			/ 1STST		80537 Office
PACIFIC AUCTION		,	/ ISTST		80537 Auto
OFIC AUCTION			/ : IST ST	EMTR2	80537 Auto
DMCAST COMMUNICATIONS		į	/ 1ST ST		80537 Office
NONT RANGE MORTGAGE PROF			/ isTs1		80537 Office
BACON ENTERPRISES	Dorothy's Catering	2228 W	1STST		80537 Caterer
AOON, KINKEIDEL		2232 W	/ STST		80537
TTLE THOMPSON WATER DIST	The state of the s	3250 W	/ 1STST	The state of the s	80537 Ulity
次のような ごびゅんちょうこうしょ		1. 0000	, , , , , , , , , , , , , , , , , , ,		

ustomer Name	M C	- Size Size	Dir Street	E C	Zip Activity
otorado Commercaí Building	AND THE RESIDENCE OF THE PARTY	290		•	80538 Office
ALILEE BAPTIST CHURCH	er far far de la compressión d	5963	W 25TH ST		80538 Church
American Directory Serv	and the first of the control of the	320		Bidg 3	80538 Office
antro 21 Humba Inc.	9 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	323			80538 Office
political States and S	the second secon	327		Canada paramana and and and and and and and and and	80538 Office
ALSTATE INSURANCE	to be a series of the series o	1402	W 28TH ST	#2	
allow Osleopathic Family	a katalan dan katalan katalan menangkan katalan dan katalan katalan katalan menangkan menangkan dan sebesah da Batalan dan katalan dan bermanan dan bermanan dan katalan dan bermanan dan bermanan dan bermanan dan bermanan	1402		- *	
URN'S LAB, INC	A MANAGEMENT OF THE PROPERTY O	1402		C#	80538
ATTER DAY SAINTS	A CANADANANA MANANANA MANANANANANANANANANANANAN	1445			80538 Church
HE WEXFORD CENTER, INC.	en de la company de la comp	(010			80538 Elderly Care
ORTHWEST NINE		1550	W 28TH ST		15 15 17
Codor II I C	Burger King	102	•		80538 Fast Food
edis Octobralion	COST CUTTERS	104		#2	80538 Hair care
Similar in the second s	galanders de la proposition della proposition de	104	-	Ĉ.	80538 Office
CAS SOME INC.	na y kada, kada u ta'u in sa kanananananananananananananananananana	104	ţ.	***	80538 Spa
the forest minimum of the second of the seco	was New York Subs	104	;	۳ .	80538 Vacant
CAll ster's Pub & Grub	Eddie's	106			80538 Restaurant
6 LO	e en proprio de la companya de la c	10	ž.		80537 Retail
G L.C	on your many or experience of the property of a state of the property of the p	114			80538 Retail
HICAGO TIMES	e bedere kanton (m.). De tapa de la correra de la basanta santo de la compaña de la co	15	5 :		80538 Fast Food
GIO	AND THE RESERVE OF THE PROPERTY OF THE PROPERT	118			80538 Retail
POLIC	entra i desenta esta esta de la composito de l	122		Control (C), 11, min to the second of the se	80538 Food
irsthand Management, ELC	TO A COURT OF THE PARTY OF THE	125		en e	80538 Cas
Club Corona		126		the second secon	80538 Bar
Club Corona		130	ł		80538 Bar
PG LLC		134	E 29TH ST	The second secon	80538 Retail
(ARKS COMPUTER SERVICES, INC.		(%)	: :	#	80538 Retail
I, SOL ENTERPRISES, U.C.		142	1	The second section of the second seco	80538 Retail
DVANCE AMERICA CASH ADVANCE		145		The second of th	80538 Office
6 LC		458	,	Comments of the contract of th	80538 Retail
PGLLC	Slewart Title	150	- 1	HOR	80538 Office
PGLLC		154			80538 Retail
و ۱ ر ر د ار ر		154	;	LOBBY	80538 Retail
PG LLC		156	- 6	more and any sound on the first own of the company	
		200		A COMPANY OF THE PARTY OF THE P	
Vorkout Center	and the second of the second o	162			80538 Gym
PO I C		168			တ္သ
PG (1.0	PETS PLUS	170	į.		ca
YONUT HOUSE 2		174	E 29TH ST		80538 Bakery
NONUT HOUSE 2		178		æ ‡±	m
PEUC		178	E ,29TH ST	्र स	40
FOREY NOW INC	re despendent and the second second of the control of the second	182	E 297H ST		80538 Office
Topsaff Tax Service	Jackson Hewitt	106	E 297H ST	The state of the s	80538 Taxes
GOVER, ERIO T'AFF DAVITY		180	E 29TH ST	e des allegares esta esta de la companya del companya de la companya de la companya del companya de la companya	80538
COMMISSION OF THE PROPERTY OF	Consider the complete and considerate and cons	6.0.8	F4 - F44		CCL-(C

CDOME	
defined by	•
ialas de	
Commerc	
- Pretreatment	
hty of Loveland -	

Jusiomer warre	BLCN	NGH NGH	A	Cuit	Zip Activity	
Gasca, Crystal K	Senor Rafael's	198			80538 Restaurant	T.
ાા	Senor Rafeal	198			80538 Restaur	ant.
210 PROPERTIES, INC.	enterancing properties of the standard properties and a contract a	209			80538	***************************************
SREITBARTH, DENNIS	en en da en	208		om de generalism de se deservant partir es se deservant asses es de	80538	
ASPEN FOOD SERVICE, INC.	MCDONALD'S RESTAURANT	203	2		80538 Fast Foor	70,
210 Properties LLC	A STATE OF THE PARTY OF THE PAR	210	4		Offic	The state of the s
210 PROPERTIES, INC	a kana ana manaya a delebara ana a ana ana ana ana ana ana ana an	212	2	militaria managaman a para para para da cara d		The state of the s
RESTAURANT CONCEPTS !! LLC	Applebse's	213	3	***************************************	ിയ	ani
GIBBY'S BAKERY INC	GROUNDS 'N ROUNDS	216	E 29TH ST	AND REAL PROPERTY AND REAL PROPERTY OF THE PARTY OF THE P	80538 Food	the same of the boundary of the same of th
KOSE TESTYN A	and several decisions of the several decisions	216	i	HOWA	80538 Service	
Vells Fargo Financial	ale de la company de la compan	220			80538 Office	of the second problem was the second
AATADOR, ORCHARD LLC	A THEORETICAL TO A CONTRACT OF THE ACTION OF	221	1			'nď
TRAN'S TAE-KWON-DO ACADEMY INC	Activity County on the first dame of County County participates and county on materials contained and other participates.	222	5		80538 Office	,
Dog Club L.C	The state of the s	224	× .			olies
IRSTBANK OF NORTHERN COLORADO	Triple 1 County of the County	225	1	and the American control of the cont	80538 Bank	The second secon
NDERSON, JAOK A		226	: .	The state of the s		
04NX OVE #516500	The state of the s	227			80538 Bank	
APA JOHN'S USA SITE #001462		228			80538 Fast For	Ö
ELLULAR JUNCTION, INC		229			80538 Cell pho	388
Invsetments, LLC		233			80538 Fast For	1 0
invselments, LLC	Odoba Factory Outlet	235	: 1		80538 Fast Food	Ç
MOUNTAIN WEW PIZZA LLC		237	- 2		80538 Fast Food	Ğ.
OSE LESLYN A	este una cum pastro es describe es es cede faires de la competencia de competencia de construer es conjugadamen asua en actual	240		The second secon	80538	
adres Mexican Restaurant	Casa Grande	243			80538 Food	
OSE LESLYN A		244			:80538 Food/Gr	gnimoc
Manuel, Horacio Catano	Tortilleria Y Panaderia	246			80538 Food	
MBR ENTERPRISES LLC	Baskin Robins	243	: :	Ç	80538 Food	
RCHARDS SHOPPING CTR PARTNER	Baskin Robins	249	ς.		80538 Food/Gr	poning
MOULTON, NANCY	CURVES FOR WOMEN	249		₹ ##	80538 Gym	
RCHARDS LIQUOR	THE STATE OF THE S	249		14	80538 Liquor	
CHECK INTO CASH OF CO, INC	e de participa de la composition della compositi	249	E 29TH ST	m H:	co.	
IUSIC AND ARTS CENTER		249	1	Ш *#:		
LECHNER, NAN	ту об общения в туте и от дене и без в постоя на выполняем веделей дене выполняем выполняем выполняем выполняе	250	•		80538	
TB Loveland LLC#2010	SUBWAY	252	ì		80538 Fast Food	Ģ
ING SOOPERS 62000074		253	- 1		80538 Grocery	
RTB Loveland LLC#5160	L & L SUBWAY NO 2010	256		and the same of th	80538 Fast Foc	ָּם קר
ADIO SHACK 8663	Appelling appelling and because the majority and the period of the perio	257	- :	<u>က</u>	80538 Electronics	CS
ADIO SHACK 8663	e de la companya	257	- 1	() **	80538 Electron	SS
Trackside Collectables		257	- 1	유	80538 Retail	:
SNEAKERS		257	,	₹¥	80538 Shoes	
ORCHARDS SHOPPING CTR PARTNER	enteres (1999) (1995) (257	3		80538	
guyen, Thanh Houng Thi	Today's Nails	258			80538 Beauty 9	alon
GOYEN, TEANT FLOONG TEL	Today's Nail & Pedicure	250			80538 Beauty 5	alon
ROSEWARYS HALLWARK SHOP		281	E 297H ST		80538 Retail	
OSEMARYS HALLMARK SHOP		261	E 29TH ST	भर दर्	SO532 Refail	

SCORE NAME		EDZ W	Stree		15/7 MOUNT MOUNT
FFLER CORP	Fantastic Sams	262	29TH		80538 Hair care
FLER CORP	Fantastic Sams	264	29TH		80538 Hair care
S & Darie C	enter orden parameters, mer en parameterpropries enterpropries and parameters and construction of a construction of	265	29TH	₽ 	80538 Computers
IN TORMAN CONS	and the second s	265	8	и Чт.	80538 Cosmetics
SCHARDS SHOPPING OTR PARTNER	Main Moon Buffel	265	29TH	The state of the s	80538 Food/Graeming
JONES DENNIS A	The same of the same and the same of the s	265	29TH	## ##	80538 Office
WARD DJONES & CO	gan i dak algadigangan salampan manapanan salampan salampan salampan salampan in mila di manapanan in in	285	29TH	Ç.	80538 Office
wards Judy	A CANADA AND AND A CANADA MANAGEMENT OF BOTH OF A CANADA CONTRACTOR	265	291T	T.	80538 Office
OGGIF DIES & CHIPS	Here is the support of the state of the support o	265	29TH	#C	80538 Pet care
AN MOON CHINESE KITCHEN	production of the control of the con	265	į	T #	80538 Restaurant
ORCHARDS SHOPPING CTR PARTNER	gamma, ang itang ing propriesa kata kata kata kata ing pakanana ana manda yamanan may ampada atau ana da ang a Bananan ang itang pagagan pagagan kata kata ang ang ang ang ang ang ang ang ang an	265	ì	#	80538
HAR-TOUR	angles, summannes angeres i magamanger at departeur da anjewere a prefere, e fan i in trop to projekt and i go	267	,		80538 Hair care
VETOUS	ender in der	267	1	₹	80538 Hair care
1988 Store	er e	267	,	⊕	80538 Retail
CHICK ZITING	ORCHARD ACE HARDWARE	259	:		
Ar Tak Communications II C	1	273	ŧ	Ç	80538 (Cell phones
ORCHARDS OF FAMERS	And the second s	273	5	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	80538 Cleaners
Loveland Mutrition Inc.	GNO #2571	273	1	A #	80538 Food
OPCHARDS SHOPPING CTR PARTNER	and compared to the contraction of the contraction	273	*		80538 Pet care
America's Satellite	ar karalana - amilan da karaman da da karaman da karaman da karaman da karaman da karaman da karaman da karama	273		#	80538 Retail
TO KARI	ALL VACUUM	273	•	9	80538 Vacuums
OFFICE DEPOT #580	The second secon	277	E 29TH ST	m dagen i sagar aggraph, amont y a byt to by a a patriotic on the aggraph con-	80538 Office
Golf 18A	en en de la reporte de la reporte de la reporte de la companyación de la companyación de la companyación de la	280	•	A CAMPAGNA	80538 Gof
LOVELAND NAILS	entre of party appropriate and the contract of the set indicate and the contract of the contra	281	8	æ æ	80538 Beauty Salon
Bingo Planel	opposed on the control of the contro	281	2STH	¥12	80537
ORCHARDS SHOPPING CTR PARTNER	sector configuration to the telegraphic configuration and other majority configuration become spaces of the sector configuration and	281	29TH	WMTR1	30538
NT-4-CENTER		281	29TH	7	80538
IT BELFORD CORP	Out of Bounds	283	29TH	*	80538
tchins, Kurt/Cherie	THE REPORT OF THE PARTY OF THE	281	29TH	44	80538
THE CIGARETTE STORE	The state of the s	281	29TH	<u> </u>	80538
FAMILY DOLLAR, INC STORE #3414		281	29TH	() *#:	80538
NN. JOEN F		281	281TH	Q.	80538
S Lovelands MTA JUICE	And the second s	283	29TH		80638 Fast Food
Loveland Martial Arts Academy		285	29TH	Ω ##	80538 Books
DARDWALK PIZZA INC	CORENZO'S	C.9 C.0 I.U	29TH	₹	80538 Fest Food
ORCHARDS SHOPPING CTR PARTNER	LOPENZO SIES	285	29TH		80538 Food/Grosming
Jensen Robert	Jensen Amis	285	29TH	Ar III	50538 Retail
Alebster Ardel	energy design of some confidence of the foresteen process of the figure	285	291H	C#	80538 Weight confroi
ORCHARDS SHOPPING CIR PARTNER	ANNEARY OF COLOR OF THE COLOR O	285	29TH	HOUSE	80538
SE LESIYN A	The second second and additional second seco	288	E 29TH ST	The same of the sa	80538
Genne Finess Groso inc	ORCHARDS ATHLETIC CLUB LLC	289	29TH	EMTR1	80538
mini Finess Group Inc	7	289	29TH	EMTR2	80538
RED DRAGON	ter den de la companya de la company	296	E 29TH ST		80538
HOME STATE BANK	ANDRONA PROPERTY AND THE TOTAL PROPERTY OF THE	300	E 29TH ST		œ

	Unit Zip Activity		80538 Coffee
		610 E 291H ST 80538 Travel A	620 E 29TH ST
defined by CDPHE	MOTE		
City of Loveland - Pretreatment Commercial as define	Customer_Neme	TRAVEL SERVICE, INC	Sax5y's Coffee 80538 Coffee 805

Only of control of the season of the confine that as well found the Confine that as well found the confine that the confine the confine the confine the confine that the confine the confi		Ĉ	10,000		7.	A
WORLD VIEW TRAVEL ABOVIDE	The first section of the first		יייייייייייייייייייייייייייייייייייייי	5	12.12 FUCIONY	
Activities and the second seco	to perfect the destruction of the destruction of the second of the secon		10 0167 0	Openin - assembly the second second second second second second	0000	
OBACT O COURTS	a elektronise et 100 km et elektronise et elektronise et elektronise et elektronise et elektronise et elektron L	nze	r zemsi	-	80538	Сопее
COLCAG	. The second	630	E 29TH ST		80538	Fast Food
SIC	Quizno's	650	E 29TH ST		80538	80538 Food
SHOWTIME USA		099	E 29TH ST	About to be the second of the	80538	Videos
MARY BLAIR ELEMENTARY	ANTENNA CONTRACTOR CON	860	E 29TH ST		80538	School
JOHNSON PROPERTIES	Caldwell Banker	100	W 29TH ST	The state of the s	80538	Office
FIRESIDE LIGHTING	to the first of the second description of the second secon	107	W 29TH ST	WATER	80538	Lights
	AND THE RESERVE THE PROPERTY OF THE PROPERTY O	101	W 29TH ST	1-1#	80538	1016
Firesice Lighting		107	W 29TH ST	#5	80538	Lights
FIRESIDE LIGHTING	and the second s	107	W 29TH ST	45	80538	Lights
ELLIOTT, SEAN	A STATE OF THE CONTROL OF THE CONTRO	101	W 29TH ST	E##	80538	Commence of the contract of th
Soard, Catherina M	A CONTRACTOR OF THE PARTY OF TH	107	W 29TH ST	#4	80538	A production of the second
FIRESIDE SOUARE		107	W 29TH ST	74	80538	
STONYBROOK HOMES, INC.		201	S 20TH ST	- C#	80538	designations and passes of comparations are also produced to the control of the c
JOHNSON PROPERTIES		108	W 29THST		80538	
ERTIES		7.7	W 29TH ST		80538	
	was Miler's Crossing	122	W 29TH ST		80538	Restaurant
		215	W 29TH ST	en element de mande de la companya del companya de la companya de la companya del companya de la companya del la companya de l	0.1	Propane
OHURCH OF NAZARENE		708	W 29TH ST		80538	Chuch
THOMPSON R2J SCHOOL DIST		850	W 29TH ST	WHSEZ	80538	Warehouse
LOVELAND HIGH SCHOOL		025	W 29TH ST		80538	School
NORTH SHORE MANOR	A DETERMINENT OF A DESCRIPTION OF A DESC	1365	W 29TH ST	WATER	80538	Elderly Care
NORTH SHORE MANOR		1365	W 29TH ST		80538	Elderly Care
THE GROUP INC	The second secon	1401	W 29TH ST	∀ #	· ~	तें हुई। तह हो। स
THE GROUP, INC	and the state of t	1401	W 29TH ST	က #±	80538	Resity
THE GROUP INC		1401	W 29TH ST	Q.	80538	Realty
THE GROUP, INC	The state of the s	1401	W 29TH ST	## ()	80538	Recity
THE GROUP, INC	Topographic and the state of th	1401	W 2STH ST	WATER	80538	रेटगी
THE GROUP, INC	TOTAL TO THE TOTAL CONTRACTOR TO THE PROPERTY OF THE PROPERTY	1403	W 29TH ST	₹#	80538	રેક્ટાં પ્ર
THE GROUP, INC	the first contribution of the contribution of	1405	W 29TH ST	æ	80538	Resity
THE GROUP, INC	e de la referencia de la composition della compo	1407	W 29TH ST	U	80538	Resity
THE GROUP, INC		1409	W 29TH ST			Realty
WALTERS MARY M	enem mener i den spress de de de sidemport. Les pois de se person explosit de secondidades de siste dell'explosit de poste de se person	1440	W 29TH ST	#200	80538	Massage
THE PEARING CENTER	A CAMPAGE AND A	1440	W 29TH ST	#300	80538	Medical
AMERICAN FAMILY INSURANCE		1440	W 29TH ST	#100	80538	Office
PETERSON, JOHN W		1440	W 29TH ST	#700	80538	
MINGES, RICHARD		1510	W 29TH ST	EMTR1		
CITY P&R GOLFMT CART WASH	The second content of the second of the seco	2115	W 29TH ST	SHOP	80538 (Golf
CITY P&R GOLFMT LMGC MAINT BLG	anna i demak demak demak demak kaja kaja dela saja dela dela de anna de kind deja melan appendanta penda penda	2115	W 29TH ST	MAINT	80538	Gol'
OTY P&R GOLFMT LMOC		2115	W 29TH ST		80538	Golf
OITY PAR GOLFMT 2" WETER		2115		DWATR	80538	30f
OLTY PAR GOLFMT LIMBO CART BARN		2115	W 29TH ST	CARTA	80538	601
88 Q	THE PARTY OF THE P	2115	W 29THST	CARTB	80538	,iog
MENS GOLF ASSN		2115	W 29TH ST	BARN	80538	

	City of Loveland - Pretreatment Commercial as defined by CUPHE Confirmant Name	Z116 W 29TH ST	WATER	The second secon	SND GT	SE 2ND ST	ZND ST	SE 2ND ST	144 SE 2ND ST 80537	2ND ST	ZND ST	Cafeleria 302 SE 2ND ST (8055)	TS ONS WE CAN THE TANK THE TAN	18 SW 2ND ST	TS ONS	Siv	210 SW 2ND ST 8055	M	(19 W 2ND ST 80537	M	W 2ND ST	127 W 2ND ST	W 33RD ST	រ	# 377H ST	169 E 37TH ST 80538	E 37TH ST	121 E 37TH ST	The Down Low LLC 125 E 37TH ST 80538	m	133 E 37TH ST	37TH ST	37TH ST	W 37TH ST	Ã	W 37TH ST	W 37TH ST	3	W 37TH ST	w	E 3RD ST	3RO ST EMTR1	E 3RD ST		:
--	---	----------------	-------	--	--------	-----------	--------	-----------	---------------------	--------	--------	--------------------------------	--	--------------	--------	-----	--------------------	---	--------------------	---	----------	--------------	-----------	---	-----------	---------------------	-----------	---------------	--------------------------------------	---	---------------	---------	---------	-----------	---	-----------	-----------	---	-----------	---	----------	--------------	----------	--	---

CHOKON CHANGE TO THE WEST OF THE CONTROL OF THE CON	2	<u></u>	Unit Zip Activity
OA LOOKSWITH		226 E 3RD ST	80537
Erion, Travis/Amy		329 E 3RD ST	80537 An
HE TAX CONSULTANTS	A CAMPANA MANAGEMENT OF THE PROPERTY OF THE PR	403 E 3RD ST	80537 Office
EMMANUEL BAPTIST	eres de la companya de la compa	404 E 3RD ST	80537 Church
Angie the Dream Weaver Salon		418 E 3RD ST	80537 Hair care
IELKE, DANIEL M	inder commendate the second of	420 E 3RD ST	
CITY P&R PBGRN CIVIC CENTER	e de la companya del companya de la companya del companya de la companya del la companya de la c	500 E 3RD ST	MECHL 80537 Office
ITY FOMAN MUN BLD		LIJ	80537
ITY P&R CHLSN SR, REC CENALIB		500 E 3RD ST	SO/RC 80537 Recreation
T INDUSTRIES MMI	Caterer	SE	80537
ALD FEED & GRAIN		×	80537
LVLD FEED & GRAIN		M	i
CRUPLES BEAUTY SUPPLY & SALON	ere de la companya del companya de la companya del companya de la companya del la companya de la	103 E 42ND ST	80538
CRUPLES BEAUTY SUPPLY & SALON		:07 E 42ND ST	80537 Beauty supplier
SRUPLES SEAUTY SUPPLY & SALON	TATION OF THE PROPERTY OF THE	109 T 42ND ST	eigens ynseg 7 Besulty supplies
JGARLOAF ESTATE	AT THE COLUMN TWO IS NOT THE COLUMN TO THE COLUMN THE COLUMN TWO IS NOT THE COLUMN TO THE COLUMN TWO IS NOT TH	225 E 42ND ST	1/2HO 80538
TANSBERRY ELEMENTARY	The second secon	407 E 42ND ST	80538 Scrool
DA ASSOCIATION OF COLORADO		\s.s	
DRD, MONTE	Sonic	120 W 45TH ST	80538 Fast Food
OMONDSON SCHOOL	A CANADA MANAGA MAN	307 W 49TH ST	5 Sc)-c
POEELKS			
MS COMMUNITY COLLEGE			ς.
JEHLER, JEFF/CHERY/L			80537
Astride A Starship L.L.C		111 E 4TH ST	80537
Skylard, James A			80537 Tatioo
ARISTIAN SCIENCE READING	on dess indicate and interest policinal interest of plants of the system is because the second of th		537
Richards, Susan	Bella Beads & Wax LLC	មា	53
Jazz Alley			80537 ; Bar
MODUCH JUDY	COUNTRY JUNCTION	ш	80537 Restaurant
McCoy, Ronald/Aveine, James	R&J antiques		I ~
ADDEN, ROCKY			80537
DRNES ALAND			80537
Cipoletti's	TO THE PARTY OF TH		80537 Restauran
LEORD OXFORD INC	4TH STREET CHOP HOUSE		80537 Restaurant
BELFORD OXFORD INC	4TH STREET CHOP HOUSE	m	1/2 80537 Restaurant
e CANTINA		ιIJ	80537 Restaurant
Susar Davis	Lux of Loveland		37
Reuben Stron		เม	80537
Madigan, Terry Louise	NOT JUST GYROS INC		80537 Fast Food
HART, JOHN W			80537
All School Uniform Inc			80537 Clothing
WHITE, BARBARAJ	Coins & Collectables		80537 Retail
ALY HARLEY		138 E 41HST	WMTR1 80537
ALY, HARLEY		136 E 47HST	WMTR2 80537
4CNUGA SCAGUCINE	Theory of Flow Market	1-0 Lifez III CX4	C CECO

Costoline region	J.	Ö	:	3	J. ACIIVIIIY
AND THE RESERVE OF THE PROPERTY OF THE PROPERT	Angelo's	4		8	80537 Fast Food
			- 1	8	
And the second s		200		36	
EXWEAVE PRESS INC	A CONTRACTOR OF THE PROPERTY O	201		8	80537 Publishing
4F DEVELOPMENT	MAN	504		သိ	537 :Retail
MONE DEVELOPMENT		206	E 4TH ST		537 Retail
LF ORVEIO PERST		206		38.	537 Refail
KEY, KOGER A		208		8	537 Refail
anominimos mir uparazamino pirio usasanin ampiro usaminimos primarios promissiones. Randy Fund	DBA: Came Castle	210			80537 Retail
4F DEVELOPMENT	endry programme destructions of the destruction of	210		HOUSE 80	537 Retail
PINKERTON, LINDA L	to the control of the	212	E 4TXST		637
Forma furniture		213		#1 80	80537 Fumiture
Blodeau, James R	Loveland Music	213		~]	637 Instruments
GAN BROTHERS RENTALS LLC		213		#1A/C 80	80537 Office
(GAN BROTHERS RENTALS LLC	r der i de la fait de la comparta en la fait de de de la desta monte de des desta de la desta de desta de desta	214		808	237
FAM SOS	THE REPORT OF THE PROPERTY OF THE PARTY OF THE PROPERTY OF THE PARTY O	214		8	(507)
NELSON MARY C	A CONTRACTOR OF THE PROPERTY O	217	ž.	808	£37
aco Flat. Inc (lialan)		218	5	8	80537 Restaurant
OUALITY SHOE REPAIR		224	:	8	80537 Shoes
NEAT'S TUX SHOPS	The second secon	225	!	36	537 Clothing
	e de la company de la comp	228	:	36	80537 Enrertainment
MULSTEIN BLARK	The company of the co	233		305	537
and considerable in the constitution of a constitution of the cons	Henrys Pub	234		<u>න</u> ්	80537 Restaurant
and the part of the state of th		236		6	80537 Hair care
THE CYCLONE ENTERPRISES CORP	SCOTTY OBRIAN'S	237		6	50537 Bar
Momina Style		238		8	80537 Retail
chard, Sally	Laughing Parrol Gallery	239		8	80537 Art
BINDER, ROBERTA/MOORAOKEN, KEV	ì	241		808	537
spick Health, Inc	Cabin Country Foods	243	E 4THST	9	
SO DE TAXOS.	The state of the s	246			
STROH REALTY	<u></u>	247		EMTR1 8(n 1
The second secon	ATTENDED TO THE STATE OF THE ST	247			80537 Realty
STROH, DANIEL G		247			
Carl's Carteen	Company of the common of the common of the common of the company of the company of the common of the	248		ŏ	80537 Fast Food
THE MISTER PAWN SHOP OF LYLD		308		EMTR2 80	
Justin Morales		309	TSHT4	EMTR1 8	80537 VACANT
RANATIVES TO STOURNOR, INC.	A CAMPAGNA AND AND AND AND AND AND AND AND AND A	313		WATER 80	
ALTERNATIVES TO VIOLENCE, INC.		313	E 4THST	ELECT &	80537 Office
Cojorado Country Candles	Southern Scent	3,4	7. T.)& C#	337 Retail
GREEN, GARLAND BRUCE	and the second s	450	4 TH		80537
Jow Play Films	The course of th	314)¢ ⊃#	80537
SKY-WAY PUBLICATIONS		314	4TH		80537
MORGAN BROTHERS RENTALS LLC		314	E 47HST		De l
Rosado, Nelson	Cherry Biossom Consignment	3,5	E 4TH ST	EWTR2 80	80537 Boulique
1			* C - 1 . · · · · · · · · · · · · · · · · · ·		,

2000	- 5	}		THE CAME OF STREET STREET, STR		
TOWACC, RAINOR	Cherry Blossom Consignment			ENT N	80537	Borlique
1					80537	Restaurant
KENNEDY, AMY					80537	
COLORADO HEIRLOOM		333 E		##	80537	Wood placues
HAUSMAN G/ FLOYD B			2 - "	PA1	80537	
USMAN G/ FLOYD B				PA2	80537	
WHITING, FRANK	A CONTRACTOR OF THE PROPERTY O	333	9 - 1	#3	80537	The same of the sa
VARDS UNLIMITED					80537	Тгорһу
REMO'S BAR & GRILL	TO COMMENT AND ADMINISTRATION OF THE PROPERTY			***************************************	80537	Resiauran:
NDEEN, GEORGE					80537	
YOUNGBLOOD, LEE J	The first own to the control of the			And the second s	80537	
LUNDEEN INVESTMENTS		342 E		The state of the s	80537 Art	Art
WHITE, ANY D	The second second of the second of the second of the second secon			the state of the s	80537	
NDEEN INVESTMENTS	energy and the company of the company of the company was a second of the company of the company of the company				80537	Απ
MOSTA WERCHANTLE	of the deviation of the				80537	Color brown and managed on any or the second of the second
NUMBER INVESTIGENTS	AND THE PARTY OF T				80537	and the second s
LUNDEEN INVESTMENTS	AND THE TRANSPORT OF THE PROPERTY OF THE PROPE	356			80537	
1ST PRESBYTERIAN CH	A CAMPAGA TANÀN NA TRANSPORTANTANA NA TRANSPORTANTANTANA NA TRANSPORTANTANTANA NA TRANSPORTANTANTANTANTANTANTANTANTANTANTANTANTANT				80537	Church
PRICE, MICHAEL D	Plumbing & Sprinkler Supply			and the second of the second o	80537	Office
				e de la faction de la companya del companya de la companya del companya de la companya del la companya de la co	80537	Office
PRICE MICHAEL D	Plumbing & Sprinkler Supply	421			80537	Office
Coffee Tree					80537	Coffee
Growhi, Hassanifrani, Massoumeh		425 E				Restauran
Larry Sanner		,		* *t:	80537	Beauty Salon
Hargrave Enterprises, LLC		441		9#	80537	Refail
grave Enterprises, LLC				න ‡‡	80537	Refail
grave Enterprises, LLC				#5	80537	Refail
grave Enterprises, LLC	The Analysis of Control of Contro	্ক্		φ	80537	Refail
Hargrave Enterprises, LLC				C#	80537	Retail
grave Enterprises, LLC				#2-9	80537	Keizis
TORTICLERIA LA AUTENTICA				The state of the s	80537	Focd
RAGUE, RUSS					80537	
SAUER EDWARD					80537	**************************************
OTT, TROLENE	The same of the sa	ļ		7,7	80537	
RORAVE, JAMES		ļ		indigent and a supplier of the state of the	80537	The second secon
JOHNSON PRINTING-LOVELAND		102 W			80537	
INSON PRINTING-LOVELAND					80537	
Louis J Partipilo	Partipilo's Pizza & Panini				·	Fast Food
GUESWEL, BRUCE					80537	Retail
ESWEL BRUCE	Mayatek - Brown, Steve	133 W	3		80537	Realty
CLEMENTS, DEE D		(35)	4 :		80537	
JOHNSON PRINTING-LOVELAND		136 W	ATT ST		80537	
THU HOW NOW		V 205	11. S.T.		80537	Restauran:
HE HOB NOB		W 202	4TH ST		80537	Restaurant
Leveland Professional Offices		231 W	47H ST		80537	Office

		1202 0	כב סבעם	2	JD (Activity
GRACE COMMUNITY CHURCH		240	W 4THST	00	9537 Church
Sharpes, Letand R	Sharpes Really Vestors LLC	245			10537 Rehab
THOMPSON R2J SCHOOL DIST	Bill Reed	320			10537 School
THOMPSON R2J SCHOOL DIST	TO THE PARTY OF TH	370	W 4TH ST	80	10537 School
MIL ZAVA	AMERICAN CONTRACTOR OF THE CON	448		8	10537
ALFORD MEADOWS COMMUNITY ASSOC	The first make any control of the first control of	1397			80538
/ELAND PROTESTANT CHURCH	mana dia 100 dengan dan dan 100 dengan dan 100 dengan dan	705	3	·~	10538 Church
D PROT REF SCHOOL	And the state of t	705	•	SCHOLB	0538 School
City of Loveland	The state of the s	101	ļ.	(O	30537 Office
Otto of Loveland	ende by a second manufacture of the contract of the contract and the contract of the contract	5		9	30537 Office
Bartosa Alica	(All About You Day Stra	111	1	80	10537 Beauty Salon
THR ASTR	Andrews See See See See See	114	3	00	
CHAMBERS PLEG & HEATING INC	territor de l'est come despetitives de tradegia de l'Albert para l'estable de maneral personal de l'estable d	119	1	8	0537 Piumbing
Saragust Fine Arts Callery	andere of the company	121	1	1/2 8	
agyadi Fide Aris Callery	A CONTRACTOR OF THE CONTRACTOR	123			10537 Art
	A STATE OF THE PROPERTY OF THE	123		12	10537 Bar
NATIONAL WATER	The second of th	123	!		30537 Bar
ATOREX AANDY	Sandy's Libracistery & Flads	129	:	SHOP	0537 Upholsfery
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	i	129	1	i	
LOVE AND BLIST INTING CORP	the second secon	205	ì	201E1 8	0537 Newspaper
OTYPOTAN SEINER	Constitution of the second sec	241	1	į.	10537 Entertainment
	Company of the Compan	266	,	00	30537 Office
SCHUETT, KINDERLEE A	NORTHERN COLO KARATE	304	5		50537
Noonan, Steve		308		Φ.	0537 Insurance
rology Center of the Rockies	and professions and another state of the second	310		(Q)	0537 Medical
TIERDAEL CONSTRUCTION	endal) under spielen der meleberatern met mellen met dem bester meleberatern bester der meleberatern met der m	329	m stroil	80	80537
Iverson, Zana V	The Peaks (2/8/06)	405	7	ł	30537 Restaurant
Y FOMAN PUB SAFETY	raine de la conditionata conframente mont contratan trafic de la principal de la contrata de la contrata de la	410	1	EMTR1 8	
OTY FORAN PUBLIC SAFETY		410			10537 Office
SON POWER SYSTEMS, INC.	a designation des des commentes de commentes	910		8	30537 Supplies
CHURCH AT LOVELAND	ing to provide the control of the first control of the forest of the standard of the control of the forest of the first control of the	745	t .	160	30537 Church
Y PAR SOUTH SUNNYSIDE PARK	The control of the co	පිහිල	:	co	30537 Park
THOMPSON R2J SCHOOL DIST	The state of the s	1307		8	30537 School
Y FOWAN OLD WHSE		105		ij	30537 Office
Y FOMAN OLD WHOM	example and the control of the contr	105	Į.	WATER 8	30537 Office
OTY FORSE OLD WHSE	e de la companya de desta de la companya de la comp	105	÷	90	30537 Office
OVELAND SERTHOUD INTERFAITH	design of the control	50		0	30537 Office
IMER CTY BULDING & GROUNDS	and the second s	205	1	CO.	30537 County
A NID RENTAL	Olfv News stand	218	\$.	,	30537 Food
ANTIRO TEL THOTAX	And a second contract of the second contract	303	1	·	30537 Bank
COMMERCIAL FEDERAL	er i	303	1	EWTR2 8	30537 Bank
IN VERTICAL STATES	p. Companyor companyor production that a sound of the second company of the second compa	335	1	(80537 Office
CHAVEZ ADELLA W	Adella's	414	E 6TH ST	α	80537 Restaurent
- 1977年 - 1978年 - 19	Adella San Commence and the second se	4	:	ω	P.

HE CO
defined by C
ial as
Commerc
Pretreatment
y of Loveland -
ity of

		S Num Dir Street	Ong	Zip Activity
CONTROL RZJ SCHOOL DIST	e de la se entre de ser de seu entre des masores antiques de quida, el la labora de la bobel en la relation de la bola de seculos de la labora de la bola de seculos de la labora de labora de la labora de la labora de la labora de labora de labora de labora de labora della labora	2	EMTR2	80537 School
SST BAPTIST CHURCH		*		80537 Church
NNER AND FIFE INC		ļu.	The state of the s	80537
Y BANK OF COLORADO		125 E 7TH ST		80537 Bank
NNERS APPLIANCE LLC		ເບ		80537 Appliances
PENNER Appliance LLC		Ш	The same and the same of the s	80537 Appliances
WARD WEST, LLP		ш		80537
ARD WEST, LLP	e de la compressión de la propertie de la compressión de la compressión de la compressión de la compressión de La compressión de la	П	WATER	80537 Office
WARD WEST, LLP	en en de grande de destantant delución de consentadores de presentados de presentados de participados de la consentado de la cons	200 E 7TH ST	MSTR2	80537 Office
W PROPERTIES	**************************************	ļu.		80537
ITED AGENCIES FACILITY, INC.		(II)		80537 Office
GOOD & BALL		m		80537 Office
IG. LINDA LUE		uJ		80537
וס' רמעוז (ס'		m	i	80537
& S PROPERTIES	Sun Spirit Designs	w	ì	80537 Jewelry
ERGY FINANCIAL SERVICES INC	e en de la companya d	ມນ	;	80537 Office
ERGY FINANCIAL SERVICES INC	to the first of th	£.1.3	41.10	80537 Office
MAIG, ROGER	and the second s	w	t	80537 Office
ERGY FINANCIAL SERVICES INC	emineral management of the second of the sec	ш	Î	80537 Office
OMPSON SOCCER ASSOCIATION	The Company of the Co	(1	80537 Office
IS COMMUNITY COLLEGE		u.	į	80537 School
A 3 PROPERTIES	AND ADD THE CONTRACT OF THE CO	l U.	į	80537
S PROPERTIES	the constraint and contribute the season of the grant against the chapter of the field of the production of	1	į	80837
L B & S PROPERTIES	The state of the property of the state of th	350 F 7TH ST	#13	80537
& 3 PROPERTIES	and the second contract of the second contrac	l u	ŧ	80537
UE DOUGLAN K	OF THE PROPERTY OF THE PROPERT	3 11	S. C.	20537
	the state of the complete control of the control of	J L) t	00000
O C TRUTAIN THE CONTRACTOR OF	derica en demonstrativos de decontratores responsariados de espações registrativos de la compressión de designados de espações de especial	มใ	The state of the s	Jecos
CKLING, DANA I.		us		80537
				80537 Church
OON ENTERPRISES		m	1/2	80537 Office
RLEY, HAROLD		w		80537
WERS, DAVE F		N		80537 Retail
ALEY, KEVIN	A TOTAL OF A TOTAL OF A TOTAL AND A STREET OF A ST	γ.		80537
CTROM CORPORATION		w		80537
CTROM CORPORATION		111	A common the common accommon to make a common to the property of the property	80537
CTROM CORPORATION		i		80537
John/Susan Hutchins	B & S Products	ш		80537 Retail
Ison, Damian Warc				80537 Retail
ALTERNATIVES TO VIOLENCE INC		w		80537 Cffice
KISSELBACH, PAUL L		S E		
Carpei Network		339 SE 8TH ST		80537 Carpet
Cill. Ron F	Landmark Component Co	SE		
Lambert, James/Sharon		S EII		80537 Art
Organ Chaser's Metal Works		405 SE 8TH ST	## (0)	80537 Art
Original Other Control of the Contro	A Service of the serv	HOTHOUSE WOLLD'S CONTROL TO THE SECOND STREET	-	Control of the Contro

Customer_Name	NOTE	S Zum	ځ	iro T	Zip	Activity
Shippers Supply	Jim/Sherry Lambert	405	S)	φ# Ψ	80537 W	Warehouse
Shippers Supply	Jim/Sherry Lambert	405	S TH	4±	80537 W	Warehouse
SPECIALIZED BALSA WOOD	en de la compressión	405	S	#2	80537 W	Wood
SPECIALIZED BALSA WOOD	e de la companya del companya de la companya del companya de la companya del la companya de la c	405	S	**	80637	
SIFRRA PLAZA CONDO ASSOCINO	A CONTRACTOR OF THE CONTRACTOR	405	S		80537	
MGNERY, HERB H	***	405	SE	**	80537	AND THE RESERVE OF THE PROPERTY OF THE PROPERT
MIGNESY KERS H	The state of the s	408	S T	44	80537	The second secon
WENTER TOWN	AND THE PROPERTY OF THE PROPER	405	S	Ç.	80537	
HAWKEYE HOLDINGS LLC	THE RESIDENCE OF THE PROPERTY	405	S	8#	80537	
ORREZ ROBERT	ROB'S IMPORT MOTORS	405	SE	470	80537	
IBBALS WOOD STUDIO	A CONTRACTOR OF THE PROPERTY O	405	n.	#12	80537	
TAMOLD & C	The second contract of	408	S	£13	80537	en e
NOKERSON ROBERTOIANE	and the second s	405	S E	** 4	80537	
CHOCKNER JAN	Consideration of Market consistency of the consistency of the constant of the	405	S III	up #	80537	
Called Bridge B	Custom Casino	418	S	0.4	80537 Art	
your minimum of the control of the c	and the second	4 Δ	(C)	r- < ₹		Flooring
IMBLE PRECISION INC	AND THE PARTY OF T	4 18	S	φ <u>-</u> α		Machining
IMBLE PRECISION INC	The second section of the second many many many many to the second secon	418	ល កា	රුගි	80537 M	Machining
IMBLE PRECISION INC	o to provide a service de la company de la c	418	S	8-10	80537 Ma	Machining
IMBLE PRECISION, INC	,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们就是一个人,我们	418	S	8-11	80537 M	Machining
INSLE PRECISION, INC.	entransia del destruire de la compansia de la compa	418	S)	9-5	80537 M	Machining
IMBLE PRECISION, INC.	ender gegen ein eine der eine	4.00	SE	۲ <u>٠</u>	80537 M	Machining
CULPTURE DEPOT	ment and the state of the state	418	S	B-S		Materials
SCULPTURE DEPOT	AND	8,4	S	တ္ထ	80537 Ma	Materials
Hapi Skratch Records, Inc	COs & DVOs	418	S III	8-2	80537 M	Media
McDonald Homes	AND THE STATE OF T	4.18	S T	A-1	80537 Of	Office
ion Plains Physical Therapy PC		418	13.1 (/)	A-8	80537 Of	ffice
NTERPRISE TECHNOLOGIES, INC.	e de facilità de la companya del companya del companya de la companya del la companya de la comp	418	s rn	စ ပ်	80537 Of	Office
INTERPRISE TECHNOLOGIES, INC		& 100 100 100	s m	တ ()	80537 Of	Office
INTERPRISE TECHNOLOGIES, INC	THE THE PARTY OF T	410	S III	0.10	80537 O	Office
ENTERPRISE TECHNOLOGIES, INC		φ. Φ.	13.3 (/)	7.7	80537 OI	Office
rice. Michael	CJ&J Plumbing	418	យ	ස-ය ය	80537 P	Plumbing
SIERRA PLAZA SOUTH CON ASOC		418	SE	BLDGA	- 1	THE PROPERTY OF THE PROPERTY O
HERRA PLAZA SOUTH CON ASOC		418	S	8,008	i	A planting and the control of the co
HERRA PLAZA SOUTH CON ASOC		418	(C)	SCIB		The state of the s
HE ARTS OF LIVING		514	(V)	4.2	80537	
Owens, Chris	a de la companya del companya del companya de la companya del la companya de la c	413	ςς ΠΩ	A-3	80537	Control Contro
Avens, Ohris		418	ς. Π	A-4	80537	A PARTY OF THE PAR
Avens, Ohris		4.18	S	জ ক	80537	
Owens. Chris		418	SE	A-6	80537	
GROS, REBECCA J	AND	418	S.	 	80537	
Marie Commence of the Second o	AND THE CONTRACT OF THE PROPERTY OF THE PROPER	418	S)	ું	80537	
FASTENAL	AN ANALAMAN PARAMANAN TARAMAN MANAMANAN MANAMANAN MANAMANAN MANAMANA	418	S	C-2	80637	An annual and a design of the second of the
Richardson, Seorde A	Custom Fabrications	413	ςς ΠΊ	(P)	80537	
The second secon	The second secon	0 1	1.	u (100	

Customer Name	utCZ	S. S.	Dir Span		12in Languite	
ART CASTINGS OF COLORADO		514	SE 8TH ST	FMTR1	00557 AL	mat :
Sculpture by Joe Campbell	TO DESCRIPTION OF THE PROPERTY	878	SE STH ST	£ 0,#	SOCOTO STATE OF THE PROPERTY O	
Ankmar Door, Inc.	A STATE OF THE STA	545	NT STATE	10.04	RAST Garade Done	
Ankmar Door, Inc	A CONTRACTOR OF THE PROPERTY O	543	ST 87H ST	#012		
Ankmar Door, Inc	eren er	546	SE 8TH ST	#013	Garade	
Ankmar Door, inc	entral de la companya	546	SE 8TH ST	#C14	Garade	
Ankmar Door, Inc		548	SE 8TH ST	#C15	Garage	
Ankmar Door, Inc	on the second beautiful to the second and the second second to the second secon	549	SE 8TH ST	#C16	80537 Garage Doors	
M L S AIR CONDITIONING INC		549	SE 8TH ST	#86	HVAC	
Front Range Specialists Inc		549	SE 8TH ST	*2*	80537 Painting	
Front Range Specialties		546	SE 81HST	#C1	80537 Painting	
C& C Automotive Specialists		545	SE STH ST	#C2	80537 Storage	
C & C Automotive Specialists	The Section Control of the Control o	546 546	SE 8TH ST	#C3	80537 Storage	
Oriess, Glen E		546	SE 8TH ST	#C10	80537 Storage	
Olark Donald R	The state of the s	546	SE 8TH ST	00	80537 Storage	
		548	SE 8TH ST	#B3	80537	
MLS Air Conditioning		345	SE STH ST	# 104 204	80537	
Builder Fireplace Supply, Inc.	with the property of the control of	546	SE STH ST	1. 10.00 10.00	80537	
Amkmar Door Inc		546	SE STH ST	#05	80537	
BAE Systems Container Solution		546	SE 8TH ST	#C#	80537	
BAE Systems Container Solution	om metalen oberine kan kan de de en en en en de propose op de object de en	548	SE STH ST	#013	80537	
BAE Systems Container Solution	C. C. Seller C.	545	SE STH ST	#0# 410#	80537	
BAE Systems Container Solution	The second street of the secon	546	SE STH ST	# 70#	80537	
BAE Systems Container Solution		546	SE STH ST	#53	80537	
PENROD, DAVID M	CUSTOM CREATIONS WOODWORKING	646	SE 8TH ST	m m T	80537	
-		546	SE 8TH ST	#A.1	80537	
	ROCKY MTN BRONZE SHOP	545	SE 87H ST	#A2	80537	
		546	SE 3TH ST	#A4	80537	
MUHLSTEIN BLAIR H		546	SE 8TH ST	#43	80537	
Basy Shop Inc		540	SE 8THST	£ A5	80537	
THE BASE STOP INC	TOTAL TO A CONTROL OF THE PROPERTY OF THE PROP	546	SE 8TH ST	#46	80537	
Struckman, Teo/Lesie	Struckman Sculpture Ice	546	SE STH ST	#C6	80537	
GRAYBILL PUD Bus Condes	The second secon	546	SE 8TH ST	HO/A	80537	
GRAYBILL PUD Bus Condos	The second of th	546	SE STH ST	HO/B	80537	
GRAYBILL PUD Bus Condos	The second secon	546		HOVC	80537	
GRAYBILL PUD Bus Condos	The service of the se	546	шi	HOD	80537	
GRAYBILL BUCK (SR)		546	ш	#87	80537	
GRAYBILL BOCK (SR)		546	ш	#C8	80537	
GRAYBILL PUD Bus Condes		546		HO/C2	80537	
GRAYBILL PUD Bus Condos		546	SE 8TH ST	HO/D2	80537	
BRENT WHITE DESIGN, LLC	The state of the s	904		¥ŧ	80537 Art	
BRENT WHITE DEGIGN, L.C.		804		C) ##	80537 Art	
Rusport Inc	e men i kan mangali sa dakin da kan kan pelabanga Masama an mang-angan an mangalikak kanan at bahanga.	604	SE STH ST	ti #	80537 Construction	
PEARSON MASONRY		604	SE STH ST	(D) ##:	80537	
MOUNTAIN STATES SIGN'S LLC	ephone de la production de la composition de la management de la managemen	904	SE 8TH ST	U- Эй:	80537	

City of Loveland - Pretreatment Commercial as defined by CDPHE

Customer Name	w w	Enz S		200	2/2	Activity
SESIGN, LLC		604		φ#: (Δ)	80537	and the state of t
PEARSON MASONRY		804 408			80537	
DCS (Ac		702				Concrete
O'BRIEN CONCRETE PUMPING	de la companya de la	702		SHOP		Concrete
DOS MO		702		7,5		Concrete
USENGINEERING		729	SE 8TH ST		80537	Construction
Precision Service E ec Inc	and fine continues of the professional conference continues when the continues of the conti	1320		Brook a	80537	
Neckel, Florik A	THE STATE OF THE PARTY OF THE PROPERTY OF THE PARTY OF TH	216			80537	Hearing Aid
and the second s	e or it for the first of the fi	443		H	80537	
RAL CHARLES	AND THE TOTAL PROPERTY OF THE	1231			80537	
DEDECKER JANE/DALLABETTA KYLE		1503	W STH ST	∰ ##	80537	Art
LLOYD, MARLA	on glassing, or professional formal property was extended to the absence of a formal solutions of the commerce and the commerce of the commerce and the commerce of the commer	1730	W 8TH ST		80537	80537
の次々と用しば、成文をと	Hargrave Enterprises	1905			80537	Cabinets
Jim & Dave's Appliance	AND THE PROPERTY OF THE PROPER	2003	W 8TH ST		80537	80537 Appliances
2 Dave's Appliance	despektives and season management of the production of the first lead of the season of	2003		12	80537	Appliances
CN SECTION TO	Analysis of the desirement and the seconds and the seconds are	2021		and the special of the state of	80537	Office
PRINT FROM STS INC	The second secon	2121		The same of the state of the st	80537	Office
NTARK - FF A	The second secon	2205		1/2	80537	
- R DROPERTIES - C	A CONTRACTOR OF THE PROPERTY O	2211	1	and the second of the second s	80537	80537 Warehouse
	are a designative to the second second and the second seco	2307	W 8TH ST	a comprises a summand describer to the second of the second	80537	Contractor
Character Application	A contribution of a supplied contribution of the adolption for champion additional to the contribution of	2319	W STH ST	A CONTRACTOR OF THE PROPERTY O	80537	Appliances
LADD JAMES A	and the second second in the second s	2323			80537	
Ploneer Manufacturing	e de la compresa que la compresa de compresa de la compresa del compresa de la compresa del la compresa de la compresa de la	2327	W 8TH ST	and the same of th	80537	80537 Meat grinders
LADD, JAMES A	er en de de la companya de la compa	2331		/ I	80537	
Dave's Appliance		2335			80537	Storage
XXXPD JAMES		2343			80537	the second secon
1 G Kins	A CAMPAGA CANADA CA	2347			80537	Storage
z. Daniel B	received the contract of the c	2351			80537	Cycle
SAON DY ORIGINAL DIAZETT	AND THE RESIDENCE OF THE PARTY	2355			80537	Ad
WILSON BUSINESS COMPLEX	e department des dans est de constituent de managerisment des constituents des des des constituents constituents de la constituent des la constituent de la	2355		CH	80537	
1		2363			80537	
McCrimmon, Cliffon	McCrimmon Alliance	. 2367	:		80537	
n Sulfon Electric Inc	A CONTRACTOR OF THE CONTRACTOR	2371	, ,		80537	Fiectric
CIALIZED TEST ENGINEERING		2375	W 8TH ST		80537	
SIAUZED TEST ENGINEERING	and the second s	2378			80537	
TEB TEBE		2383			80537	
Robert Laverentz	ROCKY MOUNTAIN WHOLESALE	2387			80537	Tropical fish
MENARD CONSTRUCTION INC		2391	W 8TH ST		80537	
TOONSTRUCTION		2395			80537	product and death of the product of the contract of the contra
SON BUSINESS COMPLEX		2399	W STHST	-	80537	
OREED ELECTRIC SERVICE INC		2399			80537	
SEVEN DAKS ACADEMY OF LYLD, INC	Bright Horizons	2420		200000000000000000000000000000000000000	80537	School
סביביים אל השנים לעמים		2384	E OTH ST	***************************************	80537	The state of the s
EBELL EQUIPMENT CO INC		2384	3	₹°	80537	
The second contract of	And interest to produce the contract of the co	0000	;		1000	

Control of the contro	The Control of the Co	KIN NO.	Oil Joiree:		717	ACTIVITY
CLINEBELL FOURWENT CO INC	a de la districtió de la contractió de despendente de despendente de la propertie de despectación de la compandente de despendente de la contraction de la c	2388			80537	
U STORE COLORADO, LLC		2389			80537 Storage	ි ස්ටූප
GLEN DIX, INC		2396	:		80537	
COLCRADO BARRICADE INC		2456	E STH ST	WATER	80537 Signs	15
COLCRADO BARRICADE INC		2456	i .	ELECT	80537 Signs	75
Ground Engineering Consultants		2468	:		80537 End	Engineering
Ground Engineering Consultants		2468	:	9	} r~	ineering
Ground Engineering Consultants		2468	:	WIR#2	80537 Eng	Engineering
Loveland Saplist Church		2530		#200	1~	Church
1		2530	ABARE DR	#120		Medicai
KOLDEWAY, ARTHUR TAGNES R		2530	ABARR DR			A de la responsable de la companya d
		2530	ABARR OR	#100	80538	a de la companie de l
BUCHMAN, HAROLD J	Cattail Creek Bad & Breakfast	2665	ABARR DR		80538 Bec	& Bricst
OITY 2&R GOLFMT COGC RESTROOM		2665	ABARR DR	<u>ک</u> ان		and a property of the lay, public on the winders are of our property and an extension of the public
OITY FOWAN LIBRARY		300	N ADAMS AVE	1987		Education
LOVELAND BIBLE CHURCH		450	N ADAMS AVE			Church
Zerges, Stephen Minifany J		355	N ADAMS AVE	Control of the second s	80537	
PERFECT, SABRINA J		1421	N ADAMS AVE		80538	The state of the s
Carson, Joel D		·	ASPEN DR	Q.		88
SCHROEDER STEVE	Roney & Harris	-	ASPEN DR	4±	80538 Office	30 30
SCHUMM, STANLEY "V"		-	ASPEN DR	># #		
NELSON, MAURICIE O	The second secon	-	ASPEN DR	SOP#	80538	A CARA CARANA MATANTANA MA
SCHROEDER, STEVE		-	ASPEN DR	Z#	80538	Milyanda Market agains a chapte again and a sa a chapter again a communication
SCHROEDER, STEVE		7	ASPEN DR	W#	80538	and design
SCHUMM, STANLEY "L"	To day a mining the following the second of		ASPEN DR	#	80538	
SCHROEDER, STEVE	A CASTALAN AND A CASTALAN AND AND AND AND AND AND AND AND AND A	g	ASPEN DR	⊋≉	80538	
HOLLEY, JENNIE FAYE			ASPEN DR	ä	80538	
SCHROEDER, STEVE	ter in the last for the well special and the state of the	-	ANPEN UR		80538	
SOHUTE, STACEY LYNN	ARREST LAS DE LA SERVINS A RESISTA CARREST DE RESEAU DE COMPRESE DE LA SERVINS DE LA S		ASPEN DR		80538	
SCHULTE, STACEY LYNN	Construction of Angle Annual Construction of Angle Annual Construction of the Angle Angle Angle Angle Angle Ang	The state of the s	ASPEN DR		80538	
SCHROEDER, STEVE			ASPEN DR		80538	
SCHROEDER STEVE	turb and the second sec	_	ASPEN DR	Í	\$0538	The second secon
Jenelle E Ogrodnick		2903	ASPEN DR	i	80538 Mas	Sage
Cusion On Site	and the second the second the second transfer of the second transfer of the second second second transfer of the second s	2903	ASPENOR	į	80538 Off	90
McOracken, Kuri		2903	ANDEROR		80538 Office	e.
THE MORGANTI GROUP, INC	ter i to en to en	2903	ACO KINGO		80538	
RONEY & HARRIS, LLC	į	2903	AND UNITED THE		80538	
SABEY, CAROL P	Gray's	138	BARSERRY PL		80537 Res	Restaurant
SABEY, CAROL P		142	BARBERRY PL			ail.
Pellican, Diane J		146	BARBERRY PL		80537 Hair	Hair care
SABEY, CAROL P	WAS Prime Time Pizza	150	\.		80537 Retail	
UNIQUE PHYSIQUE	J & J PITNESS	154	BARBERRY PL	4 4 4	80537 Gym	
UNIQUE PHYSIQUE	J&JFITNESS	154	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	m it	80537 Gym	
SABEY, CAROL P	į	162	BARBERRY FL	A CONTRACTOR OF THE PARTY OF TH	80537 Retail	
	EHEART FLOORING AMERICA	174	BARBERRY FL		80537 Floo	ring

ustorner_Name		St Num	Dir Street	25	Zip Activity
HEART DESIGN CENTER		192	BARBERRY PL		80537 Ficoring
THE AND DESIGN OF NEW	EHEART FLOORING AMERICA	210	BARBERRY PL		80537 Flcoring
COVE AND DESTREE DESTRE		211	SARRERRY DI	Management of the first of the	80537 Storage
o control of the cont	and the second s	228	RAPHERRY DI		80537 Refail
	and the second s	OYC.	20 >000000	ENTD1	80537 Limber
	eren i demonstratorio, il cambo del trado i conferencia francia i debenda deservità i extrema forma della della	9 0	מטטטטטטטטטטטטטטטטטטטטטטטטטטטטטטטטטטטטט	COLVE	90500 FC:1001
COLLEG CAUTERY TOWNER	terrene en	257	מלאמונגעריי	7 L S D	OCCO, CONDE
		7000	מרטע שניים	particular de ser en estado esta en en en entre en estado en entre en estado en entre en entre e	80538 vieo.cai
fallory Osteopathic Family		1974	BLUE WESA OT	a in erwis in franchische strattgeberte authorites is welches	80538 [Medical
0/20 OPTICAL AND EYECARE		2020	BLUE MESA CT		80538 Eyecare
tewad, Gary S	, and section is a second contract to the second contract of the sec	2022	BLUE MESA OT		80538 Accounting
Rush Jack Enterprises 1.6	The first of the f	2024	BLUE MESA CT	remaining the second of the se	80538
reemen Architecta	reasonable telephonological university for the formula group on a policy of the second	2026	BLUE MESA CT		80538 Office
Marie Dewolf Insurance	A REAL TO THE TRANSPORT OF THE TRANSPORT	2028	BLUE WESA CT	A CONTRACTOR OF THE PROPERTY O	80538 Insurance
Pansy Designation	Promotest Ca	2630	BLUE MESA CT	and the state of t	80538
Coxon Mod Dark III Condo Asso	manus de la companya	2032	BLUE MESA CT	a separate de la constituente de la colonia de la colonia que postelo est dela mante	80538
Africa Ad Promotions inc.	Chapterde Scafetire Park	1052		4	80537 Art
VARD CONSTRUCTION		1052	N BOISE AVE	A#	80537
DYNEMIC MOI DING	o de la companya del companya de la companya de la companya del companya de la companya del la companya del la companya de la companya de la companya de la companya de la companya de la companya del la compan	1106		Q#	80537 Inimoid (plastic)
CALCASS AND TANK DESCRIPTION	ere anne d'estre e response establisse estable establisse d'establisse et en la companyation de la companyat	1108		C#	ini mold
		1100		## ##	
TENTINE CONCEDED AND CONCEDED TO THE CONCEDED AND CONCEDE	A CASA - CII AGA II COLO COMPONINA - ROLLA DELL'ARCO COMPANIA ROMAN DELL'ARCO COMPANIA ROLLA COM	3000	11/2 10/00	700 8/V	80538 (hi mold (wastio)
UNDER CONTROL SACIONAL SACRAMENTAL SACRAME	en per un traspeta de de deserva en generalmente mante proposit de presentation de la mante deservat per per en	0000		0.00	80400 (Fig. 1) 80400
DYNAMIC WOLDING	 From a control of the acceptance of	951.		774	9000 T 10000 T 10000
THE BREAKFAST CLUB		1451		Address of the contract of the	80538 Restaurant
Bolam, John/Barbara	Grandma's Mtn Cookies/Pizza Street	1475	N BOISE AVE	#2	80538 Bakery
J&L Enterprises LLC	One Eyed Jack's	14747 U		*	80538 Bar
8 Forestan I C	One Eved Jack's	1475	N BOISE AVE	€# #3	80538 Bar
OP OF THE LINE FAR ARTISTS	and defended and process and all the special of the special and the special an	1475	N BOISE AVE	#	80538 Hair care
minimum management of the control of	MANUS AND STATES OF THE STATES	1530	N BOISE AVE	#204	80538 Office
WEST VERN WIRUST	AND SECTION OF THE SE	1530	N BOISE AVE	#203	80538
VEST VERN W TRUST	de de la compara de la comparación del comparación de la comparación de la comparación del comparación de la comparación de la comparación de la comparación del comparación de la comparación del comparación del comparación del c	1530	N BOISE AVE	#209	80538
WEST VERN WIRUST	and the property of the property of the control of	1530	N BOISE AVE	#205	80538
VEST VERN WIRUST		1530		#103	80538
Onafede, Kathy Jo	The control of the co	1530	N BOISE AVE	#106	80538
VEST, VERN V/ TRUST		1530	N BOISE AVE	#104	80538
VEST VERN WIRDST	er der der dem dem der der der der der der de der de der de	1530	N BOISE AVE	#105	80538
NORTH SHORE HOLDING COLLC	A CAMPAGNA AND A	1548			80538
CKEE MEDICAL CENTER	estantes des acceptantes esto non aproximações, estada que manara acaminante en estada de destada de destada de	1850	N BOISE AVE	a control en agranda de la control de la con	80538 Restaurant
MCKEE MEDICAL CENTER	and the state of t	2000		WLC_R	80538 Hospital
IOXFF OFFICE SUITES		2033	N BOISE AVE	HOUSE	
GOOD DAY PHARMACY	ere	2033			80538 Pharmacy
MOKEE WEDLOEVIER	The second secon	2050		CNCTR	80538 Medical
HOMPSON VALLEY HOSP DIST	the experience of the desired and construction of the construction	2100			80538 Ambulance
CITY P&R SOUTH DSBORN PARK	processing in a contract of the contract of th	201		<u>n</u>	120.
THOMPSON R2J SCHOOL DIST	department of the control of the first control of the control of t	201		SCHOL	80537 School
				:	4

	-
	LECT
defined by CDPHE	
: Commercial as	
l - Prefreatmen	(
City of Loveland	Contomor Mag

Customer_Name	NOTE	Wnw)S	Dir Street	- Chil	Zin	Activity
First National Bank	Starbucks	1450	N Boyd Lake Ave		80537	8ank
EVEROREEN TENNIS COURTS, INC	entral and a second confidencial and additional to the major continue and according to the continue of the continue of	1331	W BROADMOOR DR	Mark of the application of the state of the	80537	The state of the s
EVERGREEN TENNIS COURTS, INC.	and the second s	1337	W BROADMOOR DR	A CANADA	80537	And the second s
COURTYARD OF LOVELAND INC	e de la compresa del compresa de la compresa del compresa de la compresa del la compresa de la compresa de la compresa de la compresa del la compresa de la compresa de la compresa del la compre	605	5		80537	Elderly Care
Tulip Creek Masters Assoc	despisation of the specific and and the specific specification of the specification of the specific of the spe	604	Callisto Dr	SPR		Í
WALT CLARK JR HIGH		2605	CARLISLE DR	A Principal of the Prin		School
GROUP PUBLISHING, INC		1615	CASCADE AVE		80538	Publishing
LAS 3 MARGARITAS	The second secon	7.4	N CHEYENNE AVE		80538	Restaurant
ALBRECHT COMPANIES, INC	Comfort inn	1500	N CHEYENNE AVE	to the party was to the party being supported to the party being the party bei	80538	Holei
LOVELAND WOMEN'S HEALTH CENTER		1813		Ę	80538	Office
LOVELAND GLASS CO		130	N CLEVELAND AVE	,	80537	Glass
Brien DiCiacco	Colorado Lifestyle Furniture	135			80537	Furniture
Brían DiCíacco	Colorado Lifestyle Furniture	139	N CLEVELAND AVE	SHOP	80537	Fumilure
NEMETH, ANDREW WUR		145		∓ 1:	80537	
Geiger, Chuck	CONTROL OF THE PROPERTY OF THE	209	•		80537	and provided programmed for an appropriate control of the control
Geiger, Chuck	All Star Windows & Sidingg Inc.	211			80537	a de la companya del companya de la companya de la companya del companya de la companya del la companya de la c
Sive Sky Church		245	N CLEVELAND AVE	WHSE		Church
LTD Enterprises	Sun Salon	304		o a company and a company of the company of	80537	CONTRACTOR OF THE PROPERTY OF
ASSOCIATED VETERANS	Accounts to the second	305	N CLEVELAND AVE			ðar
Christ's Church of the Rockies		310				Church
Slife Sky Church		310				Charach
U CARE PROJECT		322	N CLEVELAND AVE			
POHLT, NICHOLAS		325	N CLEVELAND AVE		80537	
James L Lechleidner		328	N CLEVELAND AVE		80537	Ciothing
BLUE SKY CHURCH		330	N CLEVELAND AVE		Γ.,	Church
DAILY, SUSAN MARIE		331		LPST		Office
DAILY, HARLEY		331	N CLEVELAND AVE	LONG	80537	Office
Garner, Sidney Gray	Eco-Moda	333	: 1		~	
Blue Sky Church		350				Church
FLOYD, BARRY	The second secon	407	N CLEVELAND AVE			
LOPEZ, EDWARDIAURORA		411		and the second s	80537	The second secon
LOVELAND VACUUM CENTER	the color beam content of the public terms of the public terms of the public terms of the color terms of the	415	- 6		80537	Vacuums
LOVELAND VACUUM CENTER	e de la companya de la constituir de la	423				Vacuums
MOKER MEDIOAL CENTER	Thrift Store	428	N CLEVELAND AVE	and the second s	80537	Netall Commence of the Commenc
MOKER MEDICAL BONKISE COM HILL	de destro de se de la meste de extensión de la terror de la meste de la defenda de la decentración de la constr La destro de la constitución de la meste de la constitución de la consti	450	•	S	80537	Medical Dental
LOVELAND PUBLISHING CORP	A complete the second of the s	450	N CLEVELAND AVE	***	80537	Newspaper
SENNETT REALTY	e for the second	501	,		80537	Office
Jean Griffith	Natureworks	505			80537	
Jackson, Wary S		507	N CLEVELAND AVE	*****	80537	
3		908			80537	
LVLD PUBLISHING		510			80537	
LOVELAND CYCLE 'N FITNESS		524	- 1			Bikes
EDWARD DJONES & CO	 The distribution of the distribut	525	EVEL AND		80537	Office
The Wool Basket LLC	1	526	N CLEVELAND AVE			Craft supplies
CAP THING OHNORD CHAIRE		528	N CLEVELAND AVE		80537	Sevring

Customer_Name	U		ر دون دون		i
RYLAURKEN INC	ingleknook	530	CLEVELAND		80537 Resfaurant
OTYNEWS		534	CLEVELAND	EMTR2 8	
CITY NEWS		534			
CITY FOMAN COMMUNITY BLD	aiso Houses - Main Street Catering	545			
HOUSE OF NEIGHBORLY SERVICE	and the second comment of the production of the control of the second of	565			
HOUSE OF NEIGHBORLY SERV OF		565		EMTR2 8	
US POST OFFICE	and the state of t	601			
LOVELAND UQUORS	AND COMPANY OF THE CO	639			3537 Liquor
COVELAND LIQUORS	A(so Doc's Blueprin(639		EMTR2 8	80537 Printing
TAAG. JERRY I	A PARTIE NA CONTRACTOR DE L'ARTE L'AR	730	in C		
EDWARDS, JIM D	A CANADA MANADA	740	N CLEVELANDAVE	œ	80537
BIG T FEDERAL CREDIT UNION	A MANAGEMENT OF THE PROPERTY O	746	CLE	ά	0537 Bank
TRINITY U METHODIST		801		ã	0537 Church
FALCON PROPERTIES, INC		833	CLE	Ö	80537
Circle Moon Daffee	THE REPORT OF THE PROPERTY OF	843	C E	σ̈.	0537 Coffee
SAFEWAY STORES #22915		880		80	0537 Grocery
ROWES FLOWERS	AND THE PROPERTY OF THE PROPER	863	CLE	ã	0537 Flowers
HALLIBURTON, SILAS	er de de la companya	873		Ø	J537
ROADS, HELEN L	Mtn Spirit healing Aris	883		čó	0537 Office
BBAB PARTNERSHIP	Companies the control of the control	803		80	J537
SHEPPARD, CHARLES W	a designada de experior de la companya de la designada de la companya de la companya de la companya de la comp	916		Ö	0537
77H DAY ADV CHURCH	resident in the second of the	630		8	0537 Church
TOME STATE BANK	endybras (final political) is the membranishment of contract and contract of the contract of t	935		8	0537 Bank
77H DAY ADV CHURCH	AND AND A THE WASHINGTON ON THE WORLD AND AND A MARKET AND	950		1	80537 Church
71H DAY ADV OHUROH	entre de la comunitat de manda de la companya de l	950		EMTR2 3	JE37 Church
PITMON INSURANCE INC	AND AND THE PROPERTY OF THE PR	1001			0537 Insurance
WADMAN, BRUCE	THE	1052		Ö	80537
EMPIRE MANAGEMENT INC	nessas, dasa cemendelevida e summera penate manumero. Mort e electrosti pero e person plantes entre entre entre	1055		æ	80537
BOOK-NIELSEN, CLO		1113		ώ.	0637
BUDDE CONRAD	The first the second se	1146			0837
BUDDE, CONRAD		1146		1,2	7500
O'Gorman, Julie		1215	CLEVELAND	Č	3537
SANDERS, PAUL		1235	1	Ö	<u>_</u> ;
HÓDGES, TÓDD A		1259	CLEVELAND AV	8	80537 Office
INTERMILL LARRY G		1301	CLEVELAND AV	rio (80537
DIGUGLIELMO, JEANNINE		1302		(C)	0537 Office
US FJEL& FOOD CORP	Whitaker Oil	1325	CLEVELAND	00	3537 Oil
Rocky Mountain Home Workgage	THE REPORT OF THE PROPERTY OF	1331		ď)	3537 Office
BY THE BAY OF COLORADO LLC	CARL'S JR RESTAURANT	1340	S	Ø,	80537 Fast Food
1st Real Estate Service		1349	CLEVELAN	Ö	3537 Office
WEATHER I. JACK		1351		ά	80537
THOMPSON VALLEY CHIROPRACTIC		, 355 135 135 135 135 135 135 135 135 135	N CLEVELAND AVE	œ.	80537 Medical
Mister Money		1413	N CLEVELAND AVE	æ	80537 Pawn shoo
Forgiven, LLC		1413	N OLEVELAND AVE	8	0537
Trenct Saion & Day Spa		1415	N OLEVELAND AVE	ā	Dayy Bosidy cropling

	2	EIN S	Dir Street	5	d:7)	Activity
given, LLC		1421	N CLEVELAND AVE	- 1	8053	· · · · · · · · · · · · · · · · · · ·
Builders	The second secon	1435	N CLEVELAND AVE	Commence of the American Commence of the Comme	8053	30538 Realty
WMPD, LLC	A SANTANA CONTRACTOR AND A CONTROLLED OF FRANCE FOR THE POST OF PROPERTY CONTRACTOR OF A CONTROLLED ON THE CONTROLLED ON THE CONTROLLED ON THE CONTROL OF A CONTR	501	N C IN IN AVI	The state of the s	8053	4. Office
INLAND HOMES, INC.	American in the control of the contr	1505	N CLEVELAND AVE		8053	3 Office
Y P&R CEMETERY SHOP WA	esta di una massa della compressione della compress	(702	N CLEVELAND AVE	CHO		80538 Comotary
D'ADAMO, RAY/TINA	and the second s	103	S CLEVELAND AVE	and the second s	1	The second secon
NEWWAN, JANET	an elektrik terminister en en state de service de servi	123	S CLEVELAND AVE		80537	
The state of the s	A STATE OF THE STA	124	S CLEVELAND AVE		8053	Construction
The state of the s	er de	126	S CLEVELAND AVE		8053	
	AND	126	S CLEVELAND AVE		8053	7
	the contraction of the contracti	128	S CLEVELAND AVE	#Q#	8053	
Michaels, Jeines		128	S CLEVELAND AVE	₩ ₩	80537	7
DEHART, RYAN L	DBAMONSTER INK	129	S CLEVELAND AVE		8053	7 Tattoc
用, 含分形大		130	S CLEVELAND AVE		8053	;
BRONZE SERVICES OF LOVELAND	Administration of the contract	205	S CLEVELAND AVE	The state of the s	80537	Ast
ORINGA, BRAD	The second state of the se	240	S CLEVELAND AVE		8053	
DKARDT, DAVID/CINDY		246	S CLEVELAND AVE		8053	
ONPSON R2J SCHOOL DIST	TO THE TO THE TOTAL THE TAXABLE TO THE PROPERTY OF THE PROPERT	255	S CLEVELAND AVE		80537	School
REETT AUTO BROKERS	er er i kalled i de kommer er e	310	S OF EVELAND AVE	Control and the control of the contr	8053	Anto
HAN, ORVILE	The second secon	400	S CLEVELAND AVE	*********	8053	
Y PAR ADATH NINVIEW PARK	e de la composition della comp	405	S CLEVELAND AVE	FAST		7 0354
OITY P&R ADATH 405 S OLEVELAND	e de la desta de la comparta de la desta de la comparta de la desta della dell	405	S CLEVELAND AVE	WEST		Park
7 P&R SOUTH BARNES RESTROOM	and a second of the second	405	S CLEVELAND AVE	RSTR		
7 P&R ADATH BARNES MTC BLDG	e de la composition della comp	405	S CLEVELAND AVE	MOJE	Z	7 Park
7 P&R ADATH BARNES BAT RNGE	ter til en mod i tiller og at en staten mylde eller en ender man en posternormale frameringen i domontalen strongen.	475	S CLEVELAND AVE	American Company of the Company of t	1	7 Park
7 P&R SOUTH BARNES PUMP ST	an denament (s. mystykeniska komisty vytykeniska komisty samenta komisty komisty komisty samenta (s. 1888). Si Sistematika (s. mystykeniska komisty samenta komisty samenta (s. 1888). Sistematika (s. 1888). Sistematika (s.	550	S CLEVELAND AVE	The state of the s	80537	7 Park
SONRAY JOINT VENTURES	e de la martin de la martin de la constitut des species de sense es sense en sense en species de la constitut	1208	S OF EVELAND AVE		80537	
RAY JOINT VENTURES	American in the property of the second of th	1220	S OF EVEL AND AVE	Commence of the second control of the second	2022	
MDT & CHARLE	the experience of the experience of the property of the property of the experience o	1001	S OF EVEL AND AVE		80537	
DVA FIBER PROCESSING LLC	DVA Fiber Processing	1281	S OF EVEL AND AVE		80537	Spin Yarn
ED INSULATION CO	Commentation (Comment Commentation of the property of the prop	1292	S CLEVELAND AVE	Q#	80537	
ED INSULATION CO		1292	S CLEVELAND AVE	Ç#	80537	7.5
ED INSULATION CO	ender for the state of the stat	1292	S CLEVELAND AVE	14 14 14 14 14 14 14 14 14 14 14 14 14 1	80537	
ED INSULATION CO	A MAN CANADA THE RESIDENCE OF THE PROPERTY OF	1292	S CLEVELAND AVE	3#: (∏	80537	
KWAL HOWELS FAINT	and the state of t	1390	S CLEVELAND AVE			Paint
FOMAN WE CLUBHOUSE	Eagle View Cafe	707	CLUBHOUSE DR	Hanto	4 80537	Golf
oulson Excavating		:232		1/2	Ŷ.	Construction
ALSON EXCAVATING		3509	í	SHOP	80538	
COULSON EXCAVATING		3609	i		80538	
NAMAQUA SCHOOL		508	(THE CONTRACTOR CONTRAC	80537	
THOMPSON R2J SCHOOL DIST		720	COLORADO	a color of the condition of the color of the color of the color	80537	
Elters David Edward		775	N COLORADO AVE	SOUTH		
STAIANO, ANTHONY C		37	COLORADO	TLYON		
MENARD, MICHAEL		808	COLORADO	Ω#±	80537	and a few from the second seco
こうしゅう いっぱん いっぱい とくりしょうかい			((((((((((((((((((((***************************************		

Customer_Name		といろ	Ł :	ויייט		ACIVITY
DAVIS, JAMES		000	N COLORADO AVE	A party of the cold statement on special speci	80537	THE REAL PROPERTY OF THE PROPE
DAVIS, LEROY		1107	COLORADO HWY	EMTR2	80537	And the second of the second o
14VIS LEROY		1107	•	. 12.	80537	
NEWCO INC	A second manufactured and commentation of the second secon	1125	COLORADO HWY	and the state of t	80537	Saidding
OVELAND HIGH SCHOOL	enderen datum errenderen gerande in der errende gerande gerande der errende gerande der errende errende errende	2539	CUSTER DR		80538	Gym
THOMPSON R2J SCHOOL DIST	and the second s	915	DEBORAH DR	47.70	80537	School
CITY P&R SOUTH SHERRI WAR IRRI	makani teraka diakabahan di dan kemanan dan atau dan	929	DEBORAH DR		80537	丁 盘/大
CIV PAR Deer Meadow Restroom	THE RESIDENCE AND ASSESSMENT ASSESSMENT OF THE PROPERTY OF THE	959	Deer Neadow	RSTEM	80538	Park
Bimbo Bakeries USA Inc	e de description de la companya de description de la companya del companya de la companya del companya de la companya del la companya de la c	373			80537 E	Bakery
McCarly Wed Farms	om med jakon men, i namberi priminkoj ja rajamin ingamin kan i namen kaj posten, preminal - namen i namen.	375	N DENVER AVE		80537	
Joseph Richard	na na ana mpampana mangalan kada da	379	•		80537	Woodworking
Evans Robin	Contemporary Glass Designs	381	N DENVER AVE	open the same and	80537	
A W Flexing & CO	1	383	N DENVER AVE			Warehouse
PERCHARD	BLOU ORBIT ANT OURS	427	!		1	Storage
BADER DAVID		428	N DENVER AVE		r	
ADVANCED PROFESSIONAL ENGINC	to the second of the second	43.			80537	
	e de la company de la comp	25			r	Art
BALMAN, SCOTT A	The second secon	433	N DENVER AVE		80537	Auto Detailing
ZIMBELMAN, DARELL D		437			80537	
		439	C Z Z		80537	The state of the s
ohnson, Dennis		443		- 1	b.	Vending
Gustafson, Eric D	and the second second and the second	445	, ,	BLDGE	h-	Storage
GAIONI, JOHN MICHAEL	Window Center	445	N DENVER AVE		<u>ا</u> - ا	Window/Doors
Vandenburg Perry L		449		The state of the s	1	Office
Vandenburg, Perry L		451		Comment of the Commen	N	Office
White Light LLC		453	N DENVER AVE		80537	ement and the second and the second of the s
MOUNTAIN VISTA BUILDERS		455			N .	
ENVER AVE CONNERCIAL PARK		457			15-	Sheet metal, woodowrking
Teier Daniel		459		to the second se		Office
HAMILTON LINEN AND UNIFORM		461			~	Uniforms
Owens Coming HomeExperts		463	N DENVER AVE	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	n∖ N. Î	man de gradest de la companya de la constanta
eacon Real Est investors Corp		465			N.	Electronic testing
Beacon Real Est Investors Corp	Primerica	467	i		80537	Drywell
Mark Borgman	Slickworks/Zena	469	N DENVER AVE	de la company de	P~ :	Wolded Plasfic cones
DENVER AVE COMM PARK LLC		47.4	- 2	Vacant	80537	the second section is a second section of the second section of the second section of the section of the second section of the section of the second section of the second section of the section of the section of the section of the second section of the section
Bacon, Deóra	Futura Stone of Colo	473				Warehouse
Preferred Honsecare		475	N DENVER AVE		I ~	Medical equipment
EXCEL Mess;	AND THE PROPERTY OF THE PROPER	477				Construction
DENVER AVE COMM PARK LLC		477	N DENVER AVE	ar Dea	١.,	
ARMON HOMES		480.7	N DENVER AVE			Realty
BLUE DIAMOND MORTGAGE		483	N DENVER AVE		80537	Office
ILB Company Inc	A4S Technologies	485	N DENVER AVE		80537	Efectronics
A 4 S Technologies		787	N DENVER AVE		80537	Software development
(4 S Technologies		489	N DENVER AVE	The same of the sa	80537	Software development
The second secon		× 0.			10000	Office

€ 3

ш
COOK
defined by
a 38
ommerci
Ö
Pretreatment
ģ
of Loveland
<u> </u>

Greeley Lwd ringation GOOD DAY PHARWACY GOOD DAY PHARWACY DENVER AVE COMM PARK LLC MAZUR, PHIL B WAZUR, PHIL B Shelter Insurance Co Seweetheart Quilt Shoppe Sweetheart Quilt Shoppe ALBRECHT, DUANE E KLEN EDWARD MIELKE, DANIEL M PINKEE'S ROD SHOP INC	Westen States Land Services	493 495	zz	DENVER AVE		80537 80537	Office
	1 5	495		מניוו מם מויוו		80537	Office
	3 S	***************************************		リング・ゴンジン		The second second second second	
	d S	497		JENVER AVE	٠	80537	
	S S	497		ENVER AVE	BLOGB		
	· · · · · · · · · · · · · · · · · · ·	505	1	ENVER AVE		.,	Corsulting
		505	6	JENVER AVE	EMTR2	80537	
		513	,	ENVER AVE	and the second s	80537	80537 Insurance
	***************************************	₩.	1	JENVER AVE		80537	Retail
		517		FNVER AVE	EMTR2	80537	Refail
	Albrecht insurance	525	ì	PENVER AVE	According to the second of the second	80537	Insurance
		525	-	ENVER AVE	BLDGC	80537	A CONTRACTOR OF THE PROPERTY O
	Interior Concepts	535	2	ENVER AVE		80537	Office
		539	•	ENVER AVE	Vecari		
	edition of the first of the design of the first of the fi	543	z	ENVER AVE	Vacant	80537	The second of th
unfeit, Nancy/Robert	Salutos vinitas de la companya de la	547	ł	ENVER AVE		80537	Wodel RR products
		555	:	ENVER AVE	Control of Faces of Private Confession on Service Confession	80537	Att
Hope Springs Community Church		559		ENVER AVE		80537	Church
ope Springs Community Church		563	8	ENVER AVE	***************************************	80537	Ohurch
Hofstein Self Storage LLC	UC UC	567	į.	ENVER AVE		80537	Entertainment
		57.0		ENVER AVE		80537	
Holstein Self Storage LLC	uc	575		ENVER AVE		80537	Entertainment
	40	573		ENVER AVE		80537	Entertainment
LEN, EDWARD		579		ENVER AVE	BLDGA	80537	
OMMERCIAL SERVICE INC		591		ENVER AVE	EMTR2		HVAC
cCarty Land & Wajer		591		ENVER AVE		80537	Office
JULTIS SALES AGENCY INC		595		ENVER AVE		80537	Office
INNOVATIVE TEST SOLUTIONS INC		566		ENVER AVE		80537	Software
ope Springs Community Church		915		ENVER AVE		80537	Church
obe Springs Community Church		615		ENVER AVE	EMTR2		Church
Colorado Dairy Service		623		ENVER AVE	EMTR2		Dairy
IEN, EDWARD		623		ENVER AVE	BLDGB		
Colorado Daiy Service		623		ENVER AVE		80537	
		633		ENVER AVE		80537	Office
Broadway Bound Dance Academy	e en synthetis om e stigment som en etter som en stigment en	637	z	DENVER AVE		80537	Training
cadway Bound Dance Academy		641		ENVER AVE		80537	Training
		645	c z	ENVER AVE		80537	Taining
OOD DAY PHARMACY		653		ENVER AVE		80537	Office
GOOD DAY PHARMACY		653	ì	ENVER AVE	EMTR2	80537	Office
KLEN, EDWARD		653	z Z	ENVER AVE	BLDGD	80537	
ORIENTAL MOOLDO SCHOOL		697		ENVER AVE		80537	Office
Amerigas LLP		669		ENVER AVE		80537	Propane
ALLWEATHER WOOD PRODUCTS, INC		715	Z	ENVER AVE	And the second of the second o		
	and demonstrated and and and and and and and and and an	7.15		ENVER AVE	EMTR2	4	
	Addresses 750-798	798	2	ENVER AVE		1	Smail engine
The second with the second	CO	250	į.	FNVER AVE	And the confession of the conf	80537	i

Customer_Name	NOTE	SO_NUM	Dir Street	- E	Zip (Acilvity	
OLEN DIX. INC	Mister Ice	850	N DENVER AVE	# 2	80537 Ice	
GLEN DIX. INC	Alistoria io de la company de	053	DENVER	EMTR2	80537 Ice	
GLEN DIX. INC.	en e	රසින	N DENVER AVE		80537 Ice	
GRIESS, OLEN E	Rocky With Sharp Shop	1054	DENVER		80537 Sharpen equip	
ORIESS, GUEN	Rocky With Sharp Shop	1054	DENVER	() #		
ORIESS, OLEN	Rocky Min Sharp Shop	1054	ŧ .	£ 14 14	80537 Sharpen equip	
THEATRE SPECIALTY CO INC	POWERPLAY MOTOR SPORTS	1080			·	
THEATRE SPECIALTY CO INC	1	1082	DENVER AV		80537 Carper cleaning	
Sherba, Michael	Hough Six	1122	1		i n	
That Cabinet Company	en entre nomme e menomento. To commente constituente en profession entre por la principal de la commente del commente de la commente de la commente de la commente del commente de la commente del la commente de commente della commente della commente della commente della commente della comme	1246	2	EMTR2	80537 Cabinets	
THARP CABINET COMPANY	The control of the co	1246		Approximation of the state of t	11-	
WAL-MART STORES, INC #01-0953	is noticed and a particular construction of the particular con	1325	N DENVER AVE	and the same of th	7-	The second secon
Germin Homes LLC	e song per dina kalangan mengan kangan sengan perdapan perdapan perdapan dan dan dan dan dan dan kangan senan d Basa dan perdapan dan bermanan bermanan dan bermanan dan perdapan bermanan dan dan bermanan dan bermanan dan b	1380	1	and the second second second second second second	80537	
Pacia IXDIess	and developed the second of the second of the second operators and developed by second operators of the second	1391	1		80538 Fast Food	
Parker, Elizabeth	Earle's Floral & Giffs	3,4	ì		80538 Flowers	
Parker Rizabeth	Earle's Floral & Giffs	1419	N DENVER AVE		538	
Out Maya, E.C.	A CALLERY OF THE CALL AND A CALL	421			533	
Moulton Nancy	Curves for Women	1423	1	And the second s	80538 Gym	
Brock James	Wintage Clock & Renair	1425		and the second contract of the second contrac	80538 Jewelry	
COLRED INC	The second secon	1427			?	
Cold Character Control of Control	Sand Granding lime's Chocolates	\$423			A	A THE RESERVE AS A PROPERTY OF PERSONS AS A
College 1 (1977) 1975 1975 1975 1975 1975 1975 1975 1975		\$ E P >	N DENVER AVE			
CONTINUE AND	complete and the second of the) (C) (C) (C) (C) (C) (C) (C) (C) (C) (C		The same and the s	SOANS Hair rure	**************************************
	montande francosta intera canada finim versinate de la francosta de la francos		N. OHNKUD KVE	The state of the s		
S cagles fixed prises	2010 0 10	000	2. 2012.40		A 55.00	
Slugio 34	er den de la company de la com	202	•		world to a	
D & D Inc	big City Buffio	44.	N OFINCER AVE	(000	
RTB Loveland LLC #29415	L&LSubway	1445	- 1	9	80538 Fast Food	and a second sec
Mobility & Moore	the second second description of the second	1447				η{
Matress King		1449	N DENVER AVE		80538 Mattress	Street and the street of the
Beauty Alliance		1451			80538 Beauty supplies	
Checker Auto Parts		1450 650				
CSK Auto inc. #4274		1455			80538 Auto Parts	
34 Marke(Place LLC		1465		<u></u>		
ADVANTAGE BANK		1475			80538 Bank	,
SCOTT, GINA G		1491		#10		2000
McDonald Homes		1491		#102	80538 Office	
SCOTT GINA G	Neok, Back & More	1401	ì	#1018	80538 Office	
S B PROFESSIONAL MARKETPLACE	ender de la companyation de la comp	1491	,		80538	
MDVARD BOSIN	AND THE PROPERTY OF THE PROPER	1481	N DENVER AVE	#201	80538	
ANDERSON, J		1610	E C	, 11 Lag.	80538	
Tri-County L.C.	Manual Property and the Community of the	908	CE		80537	
Carlson Systems	, de mais a mais estados de la maisma de maism	937	DES		80537	
PRAXAIR INC	a para para para para para para para pa	950	CES	WINTRY	80537	
PRAXAIR, INC.	ray a design of the state of th	950	1	WMTR2	80537 O2 gas	
1028 International Control of Con	化二甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	ruc	u C		1000	

ü	
ã.	
\Box	
Š	
Ö,	
Ë	
Prefreetinent Commercial as defined by ODPHE	
ŝ	
ñ	
Ξ	
ä	
Ē	
ပိ	
Œ	
38	
ĕ	
21.6	
ů.	
,	
ĕ	
City of Loveland	
á	
Ö	
:-	
()	

Where I are done to the control of t	שורטא	٤.			Activity
Warostica, Don W	and the second s	N 166			
Marostica, Don W			DES MOINES AVE	EMTR2 80537	70
Marcsitca, Don		Z	DES MOINES AVE	Vacant 805	37
SCHRIOT, RANDY		1023 N	DES MOINES AVE	:	37 Contractor
CHWIDT, RANDY	The second secon	Z	DES MOINES AVE		37 Contractor
BUT ER SCOTT A		Z	DES MOINES AVE	EAST 80537	37 Contractor
JHLER, SCOTT A		Z	DES MOINES AVE	ŧ	37 Contractor
HAROLD MARK		Z IO	DES MOINES AVE		27
LPR CONSTRUCTION		Z.	DES MOINES AVE	8053	i.
PR CONSTRUCTION		Z	DES MOINES AVE	EMTR2 8053	1
PR CONSTRUCTION		N 1711	DES MOINES AVE	• • • • • •	115
ROCKY MTN PEST CONTROL, INC			DES MOINES AVE	8053	1
lernal Combustion Tech		Z	DES MOINES AVE	8053	ir.
OVELAND DRYWALL SUPPLY, INC		1227 N	DES MOINES AVE	80537	Drywall
OVELAND ORYWALL SUPPLY, INC	BEKK Tech CLC	è	DES MOINES AVE	80537	7
LOVELAND DRYWALL SUPPLY, INC.		1247 N	DES MOINES AVE	80537	37 Drywail
HEDRENS WORKSHOP		1425	DIANADR	80537	80537 Child Care
O BOB'S INC	The state of the s	1440	DIANA DR	808	37 Restaurant
TY P&R SOUTH MAINT SHOP			DOTSERO AVE	805	37 Park
ANGELICAL CHURCH		S	DOTSERO AVE	CHRCH 80537	37 Church
ALS ON WHEELS/CHEW/N CLAT		Z	DOUGLAS AVE		l.
IOMPSON R2J SCHOOL DIST			DOUGLAS AVE	EMTR2 8053	i
OOREHEAD, BOB (BFT.)	The second secon	Z	DOUGLAS AVE		~ C
THOMPSON R2.1 SOHOOL DIST		Z	DOUGLAS AVE	805	38 School
下下のエロン			DOUGLAS AVE	305	37 School
OMPSON R2J SCHOOL DIST			DOUGLAS AVE	EMTRZ 805	37 School
TRINITY LU"HERAN CHURCH			DUFFIELD AVE	208	38 Church
Loveland Baptist Church	mental and the state of the sta	4044 N	DUFFIELD AVE	80538	35 Church
A LIVING ONTRS/SIERRA VISTA			DUFFIELD CT	EWWT1 805.	37 Elderly Care
A LIVING CNTRS:SIERRA VISTA		Z	DUFFIELD CT	N	3 pm
A LIVING CNTRS/SIERRA VISTA		z	DUFFIELD CT	EWTR3 8053	37 Elderly Care
FT CARLISLE LLC			Eagle Dr	308	
COLORADO COMMUNITY BANK OF LV	The second secon	1050	EAGLE OR	80537	37 Bank
WARD DJONES & CO		1051	EAGLE DR	180637	37 Office
OMPSON VALLEY MGINT LLC		1075	EAGLE DR	80537	37 Office
OCKBUSTER VIDEO 08126		1107	EAGLE DR	805	37 Entertainment
WASHINGTON MUTUAL BANK		<u>, </u>	\sim	80537	37 Bank
EMIER FAMILY EYECARE		1123	EAGLE DR	80537	37 Medical
Regis Corporation	COST CUTTERS	1127	EAGLE DR	80537	37 Har care
PA MURPHY'S PIZZA OF LVLD		1131	EAGLE DR	80537	
MAKER, ROBERT		1,35	113	80537	
FT CARUSLE LLC		1139	EAGLE DR	BLDCD 80537	7 Office
FT CARLISLE LLC		1139	EAGLE DR	80537	37 Retail
BURKE CLEANERS, LLC	5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.47	EAGLE DR	805	37 Re:as
Tarian Hoterorisan	IJDS Since	۲. ۲.	11 20 TO	CHCC	ì

31105 101106	2	ے	Dir Stree	Š	CID ACIVITY
HEUSINKVELD, KENT D	TASTE OF CLASS	·			80537 :Retail
LOVE PIZZA INC	DBA: DOMINO'S PIZZA	1163	EAGLE DR		80537 Fast Food
Value Folly	Bronzes by Felix	100	Eagle Or	101	80537
NINON DAVID RIMAN	Paccino's Ice Creent	121	EAGLEDR		80537 Fast Food
Lie Thanh Phiopa	NAT CAND TAN	6211	EAGLE DR		2
		1195	EAGLE DR		
DAYN CARD NHOP INC	ere i de la composition della	1159	EAGLE DR	and the second s	
NOYS RESTAURANT		1200	EAGLE DR		80537 Fast Food
KING SOOPERS 62000074	-i	1275	EAGLE DR	to a device of company of the same of the	80537 Grocery
ARBUCKS CORPORATION #06382	and the second s	1317	EAGLE DR	and the second s	80537 Coffee
AN CAFE & GRILL	en der eine der der der der der der der der der de	1323	EAGLE DR	AND	80537 Fast Food
Nice 1st Real Estate	Fitness for Families	1325	EAGLE DR		80537 Office
THE PAISLEY POT		1327	EAGLE DR		80537 Pottery
E PETTIE CAFE	Cactus Grille	1329	EAGLE DR		80537 Restaurent
F PETTE CAFE	Cacius Orlie	1331	2113		
	The second second as the second secon	1000	EAGLE DR	BLDGA	80537 Office
JOSON STONE	FORM	1385	EAG: E OR		80537 Grocery
25	-	1669	EAGLE DR	SCHOL	80537 School
THOMPSON R2 SCHOOL DIST		1869	EAGLE DR	MANH	80537 School
WAL ORFENS #55.45		205			80537, Pharmacy
	and the second s	300	EISENHOWER	P. B	
S Plus	ere	400	•		80537 Pels
Adologist Renals	er i desembre de como de porto de la compansión de la compansión de la compansión de compansión de la compan	401	:		80537 Ski shop
Pats Plus	A COMPANY AND A CONTRACTOR CONTRACTOR PROPERTY OF THE PROPERTY	404			80537 Office
All Slar Windows & Sicina	the state of the s	410			80537 Office
Tang, Khuong	GATEWAY MOTEL	The second of th	E EISENHOWER BLVD	HOUSE	D
	1	417		MOTEL	N
stiny Lending LLC	3	425			80537 Office
E. SONNA L	market de la market de la market de la constitución de la market de market de la market de la market de la mark	430		\ <u>\</u>	~
E. DONNA L	AND THE PROPERTY OF THE PROPER	430		,	80537 Chriconactic
RYE DONNA L	AND	430		Ę	80537 Chricpractic
ami, Mahmood	Rocky Mountain Motors	502		ENTR	37
One Hour Photo Express	A CAMPAGE AND A	630			80537 Photo develop
Rocky Mountain Communication	AND THE PROPERTY OF THE PROPER	531			
MORGAN BROTHERS RENTALS LLC	and the same of the same and the	533			80537 Fast Food
Rocky Mountain Rocks & Guillers	والمستواعة المراجع المراجع والمراجع والمستواط والمستواط والمستواط والمستواط والمستواط والمراجع والمستواط والمستول والمستواط والمستواط والمستوط والمستواط والمستواط والمستواط والمستواط والمستواط والمستواط وال	929			80537 Office
TAFT AVENUE LAND	richinaria e maramana manamata i yani ingan maramata di maramata maramata manamatan manamata manamata i katama	909			80537 Office
er en er er ogsødende fra med en er en	Loveland Model	150		MOTEL	80537 Motel
RELIGIOUS DE LA PROPERTIE DE L	Loveland Morel	758		1004	80537 [Pool
FSTONE SOLIARE	and design the second of the second s	640			١.
RSTONE SOLVER	A CONTRACTOR CONTRACTOR OF THE CONTRACTOR CO	640		1/2	1~
TO OUT ON OUT ABOUT		640		## CD	
FSTONE SOUPER	to design the second	040	EISENHOWER BL	#£	١.
SE HATORD SOLVER	e description of the state of t	640	EISENHOWER B	4	80537 Office
				the state of the same of the same of the same of	The second secon

יאיניים נאפינים	NO.	NUM IS	r Street	żi Czi	Zip Activity
Rose Sud Motel		099	EISENHOWER	EMTR2	80537 Mofei
>\		980	:		80537 Ciothina
ADVANCED DIRECT MARKETING INC	TO THE PARTY OF TH	7.12	FISHNHOWER		
IOMPSON R2J SCHOOL DIST		804	E DISENHOWER BLVD	A deal of the section problems in the section of th	
FOMPSON R2J SCHOOL DIST		804	2	EMTR2	80537 School
THOMPSON R2J SCHOOL DIST		804	E EISENHOWER BLVD	EMTR3	
THOMPSON R2J SCHOOL DIST		808	EISENHOWER		7
LOVELAND LUMBER		006	EISENHOWER		
Lindcare inc		806	E EISENHOWER BLVD	#102	80537 Hearing Aid
HNSON, JEFF E	₹ 0	606		#101	
JOHNSON, JEHN RI	Audiology & Pearing Aid Center	909			80537 Medical
d's Gym		940	:		4
GOODWILL INDUSTRIES OF DENVER		935	E EISENHOWER BLVD		80537 Clothing
Regency Centers	SUKC Enterprises LLC (Golds Gym)	950	E EISENHOWER BLVD		15.
		000	: .		
KNAPP, ROXANNE	WDOW MCCOY	:01:			80537 Restaurant
NAY KOTEL		1027	E SISENHOWER BLVD		λ.
SKEEP LAVERNE		1117	,	EMTR1	
RAMSEY IMPORT AUTO SERVICE INC		1117	;	EMTR2	80537
RAMSEY IMPORT AUTO SERVICE INC		1112	;		80537
Luke, Connie/Sary	High Impact Signs	1121	1	MANH	80537 Signs
ERLESS TYRE CO	U-Pump-it	1125	E EISENHOWER BLVD		80537 Tires
ERLESS TYRE CO	A CONTRACTOR FRANCISCO CONTRACTOR OF THE PROPERTY OF THE PROPE	1125	ē	SHED	£
SAM'S WHO_ESALE CLUB	and the control of th	1200			80537 Grocery
WIS WHOLESALE CLUB		1200	,	MTR#2	80537 Grocery
LIQUOR	destructions and destructions and making the management of the process of the contract of the	1205			1
-11 STORE	A THE RESERVE THE RESERVE THE PARTY OF THE P	1245			
CMStoom Inc	FLOWERAMA	1300		e. Alan to the second second to the second second	
PELOTON CYCLES, INC	ere de la composition	1310	VER		80537 Bikes
ALBERTSONS INC STORE 838	THE STATE OF THE PROPERTY OF T	1325			
E STOP INSURANCE Agency	AND THE PROPERTY OF THE PROPER	1340	DEN GOOD		1
HOME STATE BANK		1355	EISENHOWER	And a figure of the second sec	· 1
		1360	EISENHO	EMTR2	80537 Restaurant
Annapurna		1360	HISENED		5.
MOEN, DONKELLY	entered (commenced and commenced to the	1400	SISENHO		í
EN DON'KELLY		1406	CHNESIE		80537
ALL ABOUT FLOORS INC		214	EISENHO		80537
DON RAY GLASS COMPANY		1416	EISENHO	The same of the sa	80537 Auto glass
WAFFLE HOUSE INC #1488		1421		And the second s	80537 Restaurant
Gold Roofing Inc	and the second second second is a second of the second of the second second second second second second second	1424	EISENHOWER		· N
OFFICE MAX, INC.		1453	EISENHOWER		
LOWEN CORP	THE PAPER WAREHOUSE	1481	EISENHOWER	-	80537: Party supplies
Dierenfield, Dennis	Shops at Leveland	1465	HINDENHOW THE	a de la companya de l	
DOLLAR FINANCIAL GROUP INC	en de la companya de La companya de la comp	265 000	HOWER BL		80537
5.50 States 5.5			***************************************	***************************************	The first again the state of the second of t

			١ :	ž S	(ZID ACIIVITY
Dierensfeld, Dennis		1477	E EISENHOWER BLVD	2000	
SOUPER SALAD #144		1477			80537 Food
Lightor (Max	The second secon	1497			80537 Liquor
First Hand Warmet LLC	modernica finisher marakhaman kanadahaman spirit, chan illa ne refereben in transis and spirits in the contract	1509		projectiva in remarka considera por residencia.	80537 Gas
First Hand Month 1.1.0		1509		SHED	1-
LV SIGNS	The second section of the second second section is the second sec	1518			80537
KELLYSIGKS	en en de la la companya de la compa	1520			80537
XER SELUTION	AND A TEXT PARK TOWN THE TOWN	1538			80537 Welding
SEALS, MARLON C	ANCHOR AUTO GLASS	1600		ណ្ឌ ណ្ឌ	80537 Auto glass
EDIN, KEN	seems are a second or a second or a second of the second of the second or a second or a second or a second or a	1601			N.
BARNEVELDT INC	MCGRAFFIS RESTAURANT	1602	E EISENHOWER BLVD		80537 Restaurant
BYS ROAST BEEF	Tradestration of the contract	1617			
LIDAY INN EXPRESS		1639			80537 Hotel
1		1655			80537 Hofei
Lowes HW	one and a service of the first of the order of the service of the	2650			80537 Hardware
GUCK, VINCEN A	de de la companya de	2701			80537
GREELEY WATER DEPARTMENT	The second section of the second seco	316		e de la companya de l	80537 Water Plant
reland Essential Group, LLC	Loveland RV Village	4469			80537 Bar
THRETY IN MOTEL	density of the second contract of the second	4503			80537 Male!
ADERS NETWORK INC	the first control of the control of	504		-	80537
LOVELAND SECURITY AND PATROL		530	W EISENHOWER BLVD		
Reflux First Associates Inc		750	W EISENHOWER BLVD		80537 Realty
BIG THOMPSON FOOT & ANKIE	ANNAL I CONTRACTORIO DE LO COMPONIO DE LA COMPONIO DEL COMPONIO DE LA COMPONIO DELICACIONE DEL COMPONIO DEL COMPONIO DEL COMPONIO DEL COMPONIO DELICACIO DEL COMPONIO DELICACIO DEL COMPONIO DELICACIONE DELIC	762	W EISENHOWER BLVD		80537 Medical
NELSON, SHELLYRANDY	Biue Tree Really	832	W EISENHOWER BLVD		80537 Office
Aarocare	To the proposal of absence and the control of the c	1205	W EISENHOWER BLVD		80537 Medical equipment
Van's Eyecare	a destructiva de la companya de la c	1209	W EISENHOWER BLVD		80537 Eyewear
KENNETH VAN AMERONGEN OU PC		1211	W EISENHOWER BLVD		7
Miller, Matthew L		1213	W EISENHOWER BLVD		80537
SHANNON, DONALD J		12,2	W EISENHOWER BLVD		80537
ompson Soccer Assoc		1217	W EISENHOWER BLVD		80537 Office
r & Associates inc	Rocky Min Pro Uniforms	1221	W EISENHOWER BLVD		80537 Ciething
r & Associates inc	Rocky Win Pro Uniforms	1223	W EISENHOWER BLVD		80537 Cicthing
VILLAGEINN		1225	W EISENHOWER BLVD		80537 Restaurent
Western Convenience Stores		1331	W EISENHOWER BLVD	EMTR1	80537 Gas
FIRS" BANK OF NORTHERN COLO		1352	W EISENHOWER BLVD		80537 Bank
NX ONE #512549		1402	W EISENHOWER BLVD		Α.
BANO ONE #512547	and the state of t	1402	W EISENHOWER BLVD	ന #:	١.
ii Hoigersen	Stage Western Family Clothing	1420	W EISENHOWER BLVD		80537 Retail
control and the second control control control and con		1421	W EISENHOWER BLVD		
Flexible Real Estate Loveland	e mengana salah banda pengangan pengangan pengangan pengangan pengangan pengangan pengangan pengangan pengangan Pengangan pengangan	1421	W EISENHOWER BLVD		
Great Plains Specially Finance	Check'N Go	1425	W EISENHOWER BLVD		80537
TRI OITY PAINT	The second secon	1430	W EISENHOWER BLVD		80537 Paint
Paul Holgorsen	Stage Western Family Clothing	1430	W EISENHOWER BLVD	To the first deposit the finding of the latest	80537 Retail
ALBERTSON'S INC STORE #804		1451	W EISENHOWER BLVD		80537 Grocery
		The second secon			かく かくかい かく かいかく かんかん かんかん かんかん かんかん かんかん

Customer wame	NOTE	St Num	Dir Street	Chit	Zip Activity
Glenn Donaldson	Game Factor	1459	W EISENHOWER BLVD	۵	Retail
SALLY BEAUTY SUPPLY #1800		1463	W EISENHOWER BLVD	es es	0537 Beauty Salon
NAPOLETANI INC	PULCINELLA PIZZERIA	1467	W EISENHOWER BLVD	100	Food
Westake Plaza		1471	W EISENHOWER BLVD	#A 8	
THE NAILS SPA II		1483	W EISENHOWER BLVD	8	80537 Beauty Salon
LITCHFIELD INVESTMENTS, LLC		1487	W EISENHOWER BLVD		
NAVARRO, ALVARO	EL PUEBLITO	1495	W EISENHOWER BLVD	8	80537 Food
Westlake Plaza	The state of the s	1499	W EISENHOWER BLVD	80	80537 Food
STARBJOKS	med to be a marked of the property of the prop	1510		(A)	
ENDY'S RESTAURANT	A service of the serv	1519	W EISENHOWER BLVD	0	ir.
EISENHOWER EYECARE	entropy of the section of the sectio	1524	4	-	15
MCGUINN, DAVID L	emper - American designation of the company of the second of the company of the c	1524) (C)	80537
Warren Green Family Trust	the first contract of the second of the seco	1524	W EISENHOWER BLVD		80537
ARREN GREEN FAMILY TRUST	the states and the second of the state of the states of th	1524	W EISENHOWER BLVD		80537
REAT WALL BUFFET	ter de designate estadol galdamento i mais extende para termando mandamento como copos de como co procesa do cambio.	1535	W EISENHOWER BLVD	WATER 3	
SEAT WALL BUFFET	A magazinat framework for the fact which the figure may an extensive property of the contract	1535	W EISENHOWER BLVD		80537 Restauran
Air Talk Communications LLC	e de la composition della comp	1539	W EISENHOWER BLVD	co	
ROTH, DONNA	CLASSY PUP GROOMING SALON	1540	W EISENHOWER BLVD		
KITCHENS, ASTRID U		1542	W EISENHOWER BLVD		
SMITH SEAN KKELLY	et familier dende in der felde i dem det betrette dem kommen den dem dem en mandeligen betrette det betrette d	1546	W EISENHOWER BLVD	60	
HIGH FASHION CUSTOM TAILOR	en de la companya de El companya de la companya del companya de la companya del companya de la companya del la companya de la	1548	W EISENHOWER BLVD	000	
OLSON, DENNIS JOHN	eri et i en l'ambi desir compressione desire constitue de l'ambignation de l'ambignation de l'ambignation de l	1552	W EISENHOWER BLVD	0.00	
Graves, Troy	AND CONTRACTOR CONTRAC	1554	W EISENHOWER BLVD	0	80537 Office
Barlow's Grill	en e	909)	W ESENHOWER BLVD	(0)	80537 Fast Food
PRESSCO, INC DBA QUIZNO'S SUBS		1611	W EISENHOWER BLVD	ω	80537 Fast Food
Wester, James	s transference when we have a management of the	1705	W EISENHOWER BLVD	8	80538
JSBECK MERLEDR		1706	W EISENHOWER BLVD	OFFIC 8	0537 Pel care
RTB Loveland LLC#5100	L&LSUBWAY	1709	W EISENHOWER BLVD	:	80538 Fast Food
Hair & Nail Solutions	TO A COMMISSION OF THE PROPERTY OF THE PROPERT	1710	W EISENHOWER BLVD	0,4	80537 Beauty Saior
CERO, RALPH	And the first of t	1710	W EISENHOWER BLVD		80537 Hair care
Diana's Drop-off Laundry Service	man in a constitue de la const	1710	W EISENHOWER BLVD		80537 Laundry
1710 W Eisenhower Blvd LLC		1710	W EISENHOWER BLVD		80537 Office
SHERWIN WILLIAMS	er de la companya de	1710	W EISENHOWER BLVD	2	80537 Paint
THE OFFICE LOUNGE	Office Lounge	1710	W EISENHOWER BLVD		
SHANKUN CAMERA REPAIR	o describitativo describitativo de la secono representativo en compresa de la compresa del compresa de la compresa del compresa de la compresa del la compresa de la compresa de la compresa de la compresa de la compresa del la compresa del la co	1710	W EISENHOWER BLVD		Seese.
anne's Boulque		1710	W EISENHOWER BLVD	1	
SOHROEDER, STEVE		1710	W EISENHOWER BLVD		80537 Retail
KING, TERI		1710	W EISENHOWER BLVD	1	
EMERSON PLUMBING	The second section is a second section of the second section of the second section is a second section of the second section of the second section sec	1718	W EISENHOWER BLVD		9000
RAT, FREDERIC P		1718	W EISENHOWER BLVD	EWMT2 8	80537 Retail
LOPEZ, LUIS M	SUN VALLEY CARPETS	1718	W EISENHOWER BLVD		(th
Louis Lopez	Sun Valley Caroets	1718	W EISENHOWER BLVD	EMTR4 8	
HAFFY VILLARU	the second control of	1720	W EISENHOWER BLVD	Sec. 11.	
BARAT, FREDERIC P		1730	W EISENHOWER BLVD	Ø	
The second secon	**************************************		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	the same and the s	1

		E32 77	į	1	
The state of the s	Bloedern Lumber	1810	K	EMTR2	80537 Lumber
Loveland Lumber	Bioedorn Lumber	1810	VER		80537 Lumber
JORGENSEN LAB	des data de la compressión de la desida pareçamente de la compressión de la compressión de la compressión de l La compressión de la	1821	民		80537. Veternary instrumen
SHOWTIME USA		1821	W EISENHOWER BLVD	*#±	80537 Videos
& UNC	aderes de la companya	1888	VER		80537 Auto
Rod Dee	Rod's LIQUOR/Justine's Pizza	1904	W EISENHOWER BLVD		
BANK ONE #612649	!	1905	EISENHOV		
USTINES FIZZA	Annua i kuman sa denangan sakan kanganganya katala, sakan kangan ingan manuan, sepadahan kangan sa sabapangan kangan	1906			80537 Fast Food
ROD DEE DBA ROD'S LIQUOR	Rod's Liquor	1908	W EISENHOWER BLVD		
RTISTRY SALON	THE REPORT OF THE PROPERTY OF	1910	ű,		
LONGLAND CORP	NAPA AUTO PARTS	2013	SER		80537 Auto Parts
Gleditsch, Anne		2017	EISENHOWER BL		
AVRA STEPHEN VINCENT	Festive Moments	2020	W EISENHOWER BLVD		30537 Retail
7-11STORE	entre de la company de la comp	2081	W EISENHOWER BLVD	1	30538 Gas
NDV DIXENSIONS	en en journale de contrata des contratas de presenta de que de presenta en la presenta de caracteria de productiva de presenta de caracteria de presenta de presen	2108	W EISENHOWER BLVD	SHOP	30537
ARISER ON IR FOR MENTAL TEALTH		2154	W EISENHOWER BLVD		30537 County
LARIMER CNTR FOR MENTAL FEALTH	mander out the Martin out of the property sealing of the property of the season of the	2158	W EISENHOWER BLVD		
Victory Baptist Church	THE REPORT OF THE PROPERTY OF	2162	W EISENHOWER BLVD		80538 Church
DAVIS, DONALD D		2180	W EISENHOWER BLVD		30537 Office
senhower Estrella LLC	TV Chiropradic	2188	W EISENHOWER BLVD		80537 Chiroprador
WOUNTAIN VIEW PIZZA LLO	PizaHut	2188	W EISENHOWER BLVD		
PERKINS RESTAURANT	mander of man i versionales i energy i energy in energy in the state and a second of the state of the state of	2222	W EISENHOWER BLVD		
HUSBIAN, ROBERT	e de la companya de l	2225	W EISENHOWER BLVD		
TLR INVESTMENTS LLC	0000	2225	W BISENHOWER BLVD	#812	
quor One of Loveland		2231	W EISENHOWER BLVD	1	
SUPERCUTS #9841		2235	W EISENHOWER BLVD	3G#	80537 Hair care
Bicycle Shop L.C.		2237	W EISENHOWER BLVD		
Express Check Advance of Colo		2239	W EISENHOWER BLVD	[
DWARD DJONES & CO		2243	W EISENHOWER BLVD	- }	30537 Office
Jsman, Robert		2245	W EISENHOWER BLVD	- }	30538 Retail
FAMILY EYECARE INC		2247	W EISENHOWER BLVD		80537 Medical
AMILY EYECARE INC		2249	W EISENHOWER BLVD	- 1	80537 Medical
Roxeiry Inc	Daddy O's Green Onion Inc	2277		A10-2	80537 Fast Food
PUTLACK, RON/JOAN	Workout Express	2283	W EISENHOWER BLVD	- 1	30537 Gyn1
AIN MOON CHINESE KITCHEN		2285	ũ,	1	25. Í
LIBERTY TAX SERVICE		2287	W EISENHOWER BLVD	;	80537 Taxes
Hopper, Kathryn A	All Pers Grooming Salon	2289	ü	i i	t. i
Caufield, James A		2291	EISENHOWER	3	Page 1
PURNAN, HARVEY M	Custon Frame & Gallery	2293	W EISENHOWER BLVD	1	80537 Eyewere
COLUMBINE DRUG		2295	EISENHOWER		80537 Pharmecy
HUSMAN, ROBERT		2295	FISENHOWER		1
USMAN, ROBERT		2295		OHO CHO CHO CHO CHO CHO CHO CHO CHO CHO	15.
USMAN, ROBERT		2295	SENHOWER	-	r.
Willennium Group	Vacari	2300	W EISENHOWER BLVD		80537 Service
the second second second property is a second commence of the second second second second second second second	THE REPORT OF THE PERSON OF TH	CYCC			20.0000

CONTROL OF THE PROPERTY OF THE		CINCIN	Dir Street	ב ב	ZIP (ACIVITY
AFEWAY STORES INC #20914	e de la completa del la completa de la completa de a completa della completa della completa della della completa della completa della completa della completa della	2321	W EISENHOWER BLVD		80537 Grocery
Wajgreens 6564		2370	W EISENHOWER BLVD		
cedon II L.C	Burger King	2393	W EISENHOWER BLVD	es parente en respectato de la composição de la composiçã	80537 Fast Food
DIAMOND SHAMROCK		2500	W EISENHOWER BLVD	EMTR2	80537 Gas
-MART STORE #7329		2665	W EISENHOWER BLVD		Ι.
MART STORE #7329		2965	W EISENHOWER BLVD	WTR2	. N
HOME STATE BANK	MATERIAL TO A TO	2695	W EISENHOWER BLVD	-	
OME STATE BANK		2685	W EISENHOWER BLVD	#100	80537 Bank
ONITIONALE BANK		2695	W EISENHOWER BLVD	#120	
OME STATE BANK		2962	W EISENHOWER BLVD	#200	80537 Bank
OME STATE BANK	The second secon	2665	W EISENHOWER BLVD	#220	
OULD PROPERTIES		2702	W EISENHOWER BLVD		80537 Retail
OGAN, SHIRLEY		2707	W EISENHOWER BLVD	,±	80537 Retail
OGAN, SHIRLEY		2707	W EISENHOWER BLVD	41:	80537 Retail
OGAN, SHIRLEY		2707	W EISENHOWER BLVD	#8	80537 Retail
OGAN, SHRLEY		2707	W EISENHOWER BLVD		
HOGAN, SHIRLEY		2707	W EISENHOWER BLVD	*	
HOGAN, SHIRLEY		2707	W EISENHOWER BLVD	#2	80537 Retail
NG OF THE MOUNTAIN, INC		2709	W EISENHOWER BLVD		80537 Retail
BLUE SKY ANIMAL CLINIC		2713	W EISENHOWER BLVD		80537 Pet care
CHARLES, JEANINE L	LADY OF THE LAKE TATTOOS	2803	W EISENHOWER BLVD		80537 Office
COLBERT, LYNNGANNA		2816	W EISENHOWER BLVD		80537 Retail
One Love	A CONTRACTOR CONTRACTOR AND	2818	W EISENHOWER BLVD		80537 Relail
BLAKE JEWELRY COMPANY		3070	W EISENHOWER BLVD		80537 Jeweiry
EMBKE, MICHAEL R	Dairy Delite	3080	W EISENHOWER BLVD	. 1270	80537 Fast Food
Coffin, Anita M	THE CLIPPER	3104	W EISENHOWER BLVD		80537 Hair care
Fed/Rite Ginther (B-Business)	Partitions of A. Champada. And a champada madapaga Andapaga and pagaba magas and pagaba. Andapaga and and pagaba again	3106	W EISENHOWER BLVD		80537 Doors
WILSON, OZZIE A		3109	W EISENHOWER BLVD		
VOGEL, MARGIE C	NORTH FORK ANTIQUES	3121	W EISENHOWER BLVD		80537
Fod Namaqua Liquors, LLC	ствандск 7 mm в ² . Выпаванующей провинает «Сондава» (подерава» пределення сондерей проведення подерення выпавания выпа	3129	W EISENHOWER BLVD		
SEV/*s	er ben mer ben av det en	3208	W EISENHOWER BLVD		
MCMANIGAL SONNY	e de la companya del companya de la companya del companya de la companya del la companya de la c	3216	W EISENHOWER BLVD		
JULD PROPERTIES	JADE INN	3300	W EISENHOWER BLVD		80537 Motel
First Care Physicians LLP		3320	W EISENHOWER BLVD		80537 Medical
BIG H DARTNERS, LLC	the section of the se	3419	W EISENHOWER BLVD		80537
SORKS, KEITHOANS	THE REPORT OF THE PARTY OF THE	3520	W EISENHOWER BLVD		80537
ANDMARK ENGINEERING LTD	The state of the s	3521	W EISENHOWER BLVD		80537 Office
ROCKY MOUNTAIN ANTIQUES		3616	W EISENHOWER BLVD		80537 Antiques
HAPPELL, JOLYNN R	en en bestelle en	3904	W EISENHOWER BLVD		
U S FUEL & FOOD CORP	a de la companya	2012			80537
MERRIOK, HIS	ment of the policy of the first transformation and seminated by trade of the semination and in manufacture of the seminated o	4113			80537
NVESTAINTS L.C	ti. Akkiti berajah di Apatopa bertiak terahapan berati ah Kapana sebasa i terahapatan pentit beberapakan di ti	-221	W EISENHOWER BLVD		80537
GARCIA, SAMISALLY	te i i delte gegelege i gelleg i lengtisch i Newstein geweite i der eine der der der der det egenetis geweite	4229	W EISENHOWER BLVD		80537
P PROPERTIES (LC	te inquie. Manie i empresso de product emple se a coma i plemajojojos syste i injusticados i inicial proprior in a contra estados esta	£233	W EISENHOWER BLVD		80537
ALMONIT DAN II		4321	FINACMER		C 47 17 1 10 CO

of the state of th	SO SER AS SOURCE STORY				
	-	U ! (10 10 10 10 10 10 10 10 10 10 10 10 10 1		1
CUSIO-HEL Marine		11 5	0 Scii		3
The second section of the sect	THE PERSONNEL PROPERTY OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON OF THE PERS	where the court is a second or product the contract of the con	THE PARTY OF THE P		
U. A. C. H. C. C.			C/ / に	<u>ر</u> .	

ALERACHT, DAN E RUTLEDGE, WARVIN D ALLSTATE INSURANCE COMPANY Smith Management ALLEN, THOMAS JMD SANDRA HANNA & ASSOC PC SANDRA HANNA & ASSOC PC SCHERLONG, ROBERT ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS CONTENT MARKEIPIACE Prop II Centerra Markeipiace Prop II C	4401 W 4412 W 223 233 234 234 234 234 233 8 233 8 233 8 233 8 233 8 233 8 233 8 1505 1 150 1 150		BIR49500 BIR4950 BIR4950	80537 HVAC 80537 Office 80538 Office 80538 Office 80538 Office 80538 Office 80538 Eiderly Care 80538 Eiderly Care 80538 Restaurant 80538 Coffice
RUTLEDGE, MARVN D ALLS TATE INSURANCE COMPANY Smith Management ALLES THE INSURANCE COMPANY Smith Management ALLES THE INSURANCE COMPANY SANDRA HANNA & ASSOC PC SANDRA HANNA & ASSOC PC SANDRA HANNA & ASSOC PC SCHERLONG, ROBERT ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS CONDUCT ALL ELECTRIC COURTYARD CONTOUR PEAK CREDIT UNION Mimis Cafe Centerra Markelplace Prop II Oversierra Markelplace Prop II Oversierra Markelplace Prop II Centerra Marke	22.8 22.8 22.8 23.0 23.4 23.4 23.4 150.5 N 150.6 N 150.6 N 155.0 155.0 155.0 156.9 156.9 156.9 156.9	0	BIGG500 BI	1537 Office 1538 Office 1538 Office 1538 Office 1538 Office 1538 Office 1538 Elderly Care 1538 Retail 1538 Restaurant 1538 Retail 1538 Retail 1538 Retail 1538 Retail
ALLSTATE INSURANCE COMPANY Smith Management ALLEN THOMAS JMD SANDRA HANNA & ASSOC PC SANDRA HANNA & ASSOC PC SANDRA HANNA & ASSOC PC SCHERLONG, RCBERT ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS LONGS PEAK CREDIT UNION Mimits Cafe Centerra Marketplace Prop II Panem Bread Centerra Marketplace Prop II	222 230 230 234 234 234 234 233 N 1505 N 1506 N 1550 N 1550 N 1550 1550 1569 1569 1569		BIGG500 88 88 88 88 88 88 88 88 88 88 88 88 8	1538 Office 1538 Office 1538 Office 1538 Office 1538 Office 1538 Elderly Care 1538 Retail 1538 Restaurant 1538 Retail 1538 Retail 1538 Retail 1538 Retail
Smith Management ALLEN THOMAS J MD SANDRA HANNA & ASSOC PC SCHERLONG ROSER! ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & J INVESTMENTS LONGS PEAK CREDIT UNION Mimi's Cafe Centerra Marketplace Prop II Saxby S Coffee The Wise Group. LLC Centerra Marketplace Prop II Saxby S Coffee Centerra Marketplace Prop II	230 234 234 234 233 233 N 1505 N 1504 N 1661 N 1550 1550 1550 1569 1569 1569		BIGG500 88 88 88 88 88 88 88 88 88 88 88 88 8	7538 Office 7538 Office 7538 Office 7538 Office 7538 Elderly Care 7538 Retail 7538 Retail 7538 Retail 7538 Retail 7538 Retail 7538 Retail
ALLEN, THOMAS J MD SANDRA HANNA & ASSOC PC SANDRA HANNA & ASSOC PC SCHERLONG, ROBER I ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS LONGS PEAK CREDIT UNION Mimi's Cafe Centerra Marketplace Prop II Saxby's Coffee The Wise Group, LLC Centerra Marketplace Prop II Saxby's Coffee Centerra Marketplace Prop II	234 234 234 233 1505 N 1504 N 150 1550 1550 1550 1550 1550 1550 155		BIGG500 BR	1538 Office 1538 Office 1538 Office 1538 Elderly Care 1538 Retail 1538 Restaurant 1538 Office 1538 Retail 1538 Retail 1538 Retail 1538 Retail 1538 Coffee
SANDRA HANNA & ASSOC PC SANDRA HANNA & ASSOC PC SCHERLONG, RCEERT ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESIMENTS LONGS PEAK CREDIT UNION Mimis Cafe Centerra Marketplace Prop II	234 233 233 1505 N 2895 N 1504 N 150 150 1550 1550 1550 1550 1550 1550		BIG9500 110 120 88 129 88 129 88 129 88 129 88 153 88 153 88 88 153 88 88 88 88 88 88 88 88 88 88 88 88 88	1538 Office 1538 Office 1538 Office 1538 Elderly Care 1538 Restaurant 1538 Restaurant 1538 Office 1538 Restaurant 1538 Restaurant 1538 Restaurant 1538 Restaurant 1538 Restaurant 1538 Restaurant 1538 Collee
SANDRA HANNA & ASSOC PC SCHERLONG, ROBERT ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS LONGS PEAK CREDIT UNION Mmis Cafe Centerra Marketplace Prop II Saxby's Coffee The Wise Group. LLC Centerra Marketplace Prop II	233 1505 N 2895 N 2895 N 1504 N 150 1550 1550 1550 1550 1550 1550 1550		150 150	1538 Office 1538 Elderly Care 1538 Elderly Care 1538 Retail 1538 Restaurant 1538 Office 1538 Retail 1538 Retail 1538 Retail 1558 Retail 1558 Coffee
SCHERLONG, RÖBERT ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS LONGS PEAK CREDIT UNION Mimis Cafe Centerra Marketplace Prop II Saxby's Coffee The Wise Group. LLC Centerra Marketplace Prop II	1505 N 2895 N 2895 N 1504 N 1450 N 1550 1550 N 1550 1550 N 1550 N		150 88 150	1538 1538 1538 1538 1538 1538 1538 1538
ALTERRA HEALTHCARE CORP CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS LONGS PEAK CREDIT UNION Mimi's Cafe Centerra Marketplace Prop II Saxby's Coffee The Wise Group. LLC Centerra Marketplace Prop II	2895 N 2895 N 2900 N 1504 N 1961 N N 1961 N N 1961 N N 1961 N N N N N N N N N N N N N N N N N N N		Bid9500 Bid	5538 Elderly Care 5538 Refail 5538 Restaurant 5538 Restaurant 5538 Office 5538 Office 5538 Retail 5538 Retail 5538 Retail 5538 Retail 5538 Coffee 5538 Coffee
CONDUCT ALL ELECTRIC COURTYARD S & JINVESTMENTS LONGS PEAK CREDIT UNION Mimi's Cafe Centerra Marketplace Prop II Saxby's Coffee The Wise Group, LLC Centerra Marketplace Prop II	2900 N 1504 N 1961 N 1450 1450 N 1550 1550 1550 1550 1550 1550 1550 1550		150 88 81 150 88 81 150 88 81 150 88 81 150 88 81 150 88 81 150 88 81 150 88 81 150 81	1538 Retail 1538 Bank 1538 Bank 1538 Restaurant 1538 Office 1538 Retail 1538 Retail 1538 Retail 1538 Retail 1538 Retail
S & JINVESTMENTS LONGS PEAK CREDIT UNION Mimi's Cafe Centerra Marketplace Prop II Saxby's Coffee The Wise Group, LLC Centerra Marketplace Prop II	1504 N 1961 N 1450 N 1550 1550 1550 1550 1550 1550 1550 1550		Bl(9500 R R R R R R R R R	5538 Retail 5538 Bank 5538 Restaurant 5538 Office 5538 Retail 5538 Retail 5538 Retail 5538 Retail 5538 Retail
LONGS PEAK CREDIT UNION Mimi's Cafe Centerra Marketplace Prop II Banera Bread Centerra Marketplace Prop II Saxby's Coffee The Wise Group. LLC Centerra Marketplace Prop II	1961 X 1450 1450 1550 1550 1550 1550 1550 1550		110 88 17	1538 Bank 1538 Restaurant 1538 Office 1538 Retail 1538 Retail 1538 Retail 1538 Retail 1538 Coffee
Mimi's Cafe Centerra Marketplace Prop II Panera Bread Centerra Marketplace Prop II Saxby's Coffee The Wise Group, LLC Chierra Marketplace Prop II Centerra Marketplace Prop II	1450 1550 1550 1550 1550 1550 1569 1569 1569		BIG9500 88 110 88 170 88 170 88 129 88 153 88	5536 Restaurant 5538 Office 5538 Office 5538 Restaurant 5538 Resal 5538 Resal 5538 Resal 5538 Collee 5538 Collee 5538 Collee
Centerra Marketplace Prop II Panera Bread Centerra Marketplace Prop II Centerra Marketplace Prop II Centerra Marketplace Prop II Centerra Marketplace Prop II Saxby's Coffee The Wise Group, LLC Centerra Marketplace Prop II	1550 1550 1550 1550 1550 1550 1550 1550		Bldg500 80 110 80 120 80 120 80 150 80 120 80 150 80 80 80 80 80 80 80)538 Office)538 Restaurant)536 Retail)538 Retail)538 Retail)538 Coffee
Panera Bread Centerra Marketplace Prop II Centerra Marketplace Prop II Centerra Marketplace Prop II Centerra Marketplace Prop II Saxbys Coffee The Wise Group, LLC Centerra Marketplace Prop II Centerra Marketplace Prop II Owesi Centerra Marketplace Prop II	1550 1550 1550 1550 1569 1569 1569		110 150 170 180 153 88 88 153 88 88 88 88 88 88 88 88 88 88 88 88 88)538 Resteurant)538 Retail)538 Retail)538 Retail)538 Coffee
Centerra Marketplace Prop II Centerra Marketplace Prop II Centerra Marketplace Prop II Centerra Marketplace Prop II Saxbys Coffee The Wise Group, LLC Chiporle Mexican Gull Inc Centerra Marketplace Prop II Owesi Centerra Marketplace Prop II	1550 1550 1550 1550 1560 1560 1560		150 160 170 180 153 88)536 Retail)538 Retail)538 Retail)538 Retail)538 Coffee
Centerra Marketplace Prop II Centerra Marketplace Prop II Saxbys Coffee The Wise Group, LLC Chiporle Mexican Gull Inc Centerra Marketplace Prop II Owesi Centerra Marketplace Prop II	1550 1569 1569 1569 1569	RIVER OR RIVER OR RIVER OR RIVER OR	150 170 129 80 80 80 80 80 80 80 80 80 80 80 80 80)538 Retail)538 Retail)538 Retail)538 Coffee
Centerra Marketplace Prop II Centerra Marketplace Prop II Saxbys Coffee The Wise Group, LLC Chiporle Mexican Gulf Inc Centerra Marketplace Prop II Owes! Centerra Marketplace Prop II	1550 1560 1569 1569 1569	RIVER DR RIVER DR RIVER DR RIVER DR	170 128 8 8 8 8)538 Retail)538 Retail)538 Collee
Centerra Marketplace Prop II Saxbys Coffee The Wise Group, LLC Chiporle Mexican Gulf Inc Centerra Marketplace Prop II Owest Centerra Marketplace Prop II	1550 1569 1569 1569 1569	RIVER DR RIVER DR RIVER DR	159 8 153 8)538 Retail)538 Coffee n538 Fast Food
Saxbys Coffee The Wise Group, LLC Chipotle Mexican Gulf Inc Centerra Marketplace Prop II Owes! Centerra Marketplace Prop II	1569 1569 1569 1589	RIVER OR RIVER OR	129 80	Coffee
The Wise Group, LLC Chipotle Mexican Gull Inc Centerra Marketplace Prop II Owes! Centerra Marketplace Prop II	1569 1569 1589	RIVER OR	153	1001
Chipote Mexican Gull Inc Centerra Marketpiace Prop II Owest Centerra Marketpiace Prop II	1558		20 40 4	õ
Centerra Marketpiace Prop II Owest Centerra Marketpiace Prop II	1569	RIVER DR	700	0538 Food
Owest Centerra Marketpiace Prop II		RIVER DR	BI55600 80	0538 Office
Cenferra Markelpiace Prop II Cenferra Markelpiace Prop II Centerra Markelpiace Prop II Centerra Markelpiace Prop II Centerra Markelpiace Prop II	and the second contract of the second contrac		193 80	OSS Reis
Centerra Marketplace Prop II Centerra Marketplace Prop II Centerra Marketplace Prop II Jo-Ann Fabric Store Inc	1268	RIVER DR	145 86	80528 Retail
Centerra Marketplace Prop II Centerra Marketplace Prop II Jo-Ann Fabric Store Inc	0000	***************************************	161 80	
Centerra Marketplace Prop II Jo-Ann Fabric Store Inc	1553	RIVER DR	169 80	0538 Relait
Jo-Ann Fabric Store Inc	1589			80538 Retail
The second statement of the second se	1607			0538 Refail
med mass & most as	1800		110 80	0538 Refell
Activities and an activities and the control of the	CO		1	0538 Refeii
And Brush	229	FALL RIVER DR		80538 Retail
Od Navy	1629		86	0538 Retail
Shoe Carnival		. ,	220 80	80538 Retail
Centerra Marketojace Prop II	1629	FALL RIVER DR	6)	80538 Retail
CONTRACTOR OF THE PROPERTY OF	1633	FALL RIVER DR	i	80538 Retail
Centerra Marketolace Prop II	and the second control of the second control	FALL RIVER DR	House 8	80538 Retail
en en en en de des de l'amplique de l'amplique de l'amplique de l'amplique de l'amplique de l'amplique de la c	Approximate the control of the contr		1	0538 Retail
Centering Marketolace/Other	1649	FALL RIVER DR	4	0538 Re(all
CHARTER HOVES		FOOTHILLS OR	හි	0537
ASPEN FOOD SERVICE INC. MCDONALD'S REST	TAURANT 1620	FOXTRAIL DR	98	80538 Fast Food
	1650	FOXTRAIL DR	36	80538 Fast Food
FARFELD INN	1710	FOXTRAIL DR	ŏ	80538 Hotel
por información processores en consecuentes de consecuentes de consecuentes de consecuentes de consecuentes de Colorado Cristán Universado de Colorado Consecuentes de consecu	1750	FOXTRAIL DR	જ	0538 Church
Cipvariest Rennel City	2527 NW	age R	38	0538 Racing/ Food

The second management of the second management of the second seco	TO CE	1132 0		5	
PETERSON'S SPECIALTY PRODUCTS		288		£33	80537; Vet medicine
PETERSON'S SPECIAL TY PRODUCTS		288		#2	80537 Vet medicine
PETERSON'S SPECIALTY PRODUCTS		288		**	80537 Vet medicine
PETERSON'S SPECIAL TY PRODUCTS	TOTAL TOTAL PROPERTY AND A CONTRACT OF THE PROPERTY OF THE PRO	208		44	80537 Vet medicine
SITY FOMAN GARFIELD LEASE		318		An interest to the state of the	80537 Office
HE HOB NOB		409		American de la companya della compan	80537 Restaurant
THE HOB NOB			N GARFIELD AVE	**************************************	80537 Restaurant
HE HOB NOB		4.1		A TO	
HOBBS, ALAN D		428			80537
Meais on Wheels	The state of the s	437		riter and the state of the stat	80537 Food
Piper, Jennifer D		446			80537 Child Care
GATEWAY FEED	ter en	530		WHSE	80537 Gard
SATEWAY COAL CO	Feed & Seed	530			80537 Grain
ITTS WILLAW T	Water Consult	900			80537 Office
ITTS, WILLAW T	and described to the country of the	900		BSMT	80537 Office
ORENS AUTO PARTS		618			80537 Woodworking
ORENS AUTO PARTS		618			80537 Woodworking
ORENS AUTO PARTS		622			
eading Olinic		900			
RNE'S JV NC		812			80537 TV repair
Pacto De Amor	The state of the s	1208			
TIVEW PRESIDENCE		7200			~
		2755			80538 Child Care
ATEWAY CHIROPRACTIC		2885			80538 Medical
GATEWAY CHIROPRACTIC	And appropriate the second section of the second section of the second section of the second section s	5888			80538 Medical
JOHNSON PROPERTIES		2893			80538
ROCKY MOUNTAIN BATTERY		6262		<(7£	80538 Recycling
OCKY MOUNTAIN BATTERY		2929		က္	80538 Recycling
ROCKY MOUNTAIN BATTERY		2629		Q#:	80538 Recycling
Fforizon Banks		2950		The state of the s	80538 Bank
REENBACKS ALL A DOLLAR		2979			Retail
SparkD Rentals	Aaron Sales & Lease	2983			
uesday Moming Inc		2985			Retail
MILLER'S CROSSING BAR & GRILL		3021			
ostampour, Rabim		3027			80538 VACANT
BLOCKBUSTER ENTERTAINMENT GROU	(Miller's Crossing)	3033			80538 Entertainment
iness 19		3121			
Supper Made Simple		3123			80538 Food
Diva Nafis		3125			
EZ Money	*	3127			Sank
ig Lets		3131			80538 Department Store
GARFIELD HOLDINGS LLC	er for the first of the second of the first of the second	3133			* ******
OBLOBILTO PARTNERSHIP	te de constitue de la constitu		GARFIELD	and the same of th	80538 Retail
entendial Bank of the West	manum spelled at the manufacture and in the demander of manufacture and in the defect of the second and the sec	3151	ARFIELD	And the state of t	80538 Bank
Caco Enterprises inc	Orloke:		SARFIELD		80538 Retail

Customer Name	NOTE	Enz 35	Dir Street	:E	Zip Activity
Sinke Cleaners I.C.	ness figures and seasons are the sections of present an expension of the contrast contrast of the contrast of	3,55	GARFIELD		80538 Cleaners
ted Hotels I.C.	Slarbicks	3157	GARFIELD		80538 Bank
ELTE ALTO DE ACO DE ET COLLINA	The second secon	3204	GARFIELD	The second state of the second	80538 Aug glass
DIAMOND VOGET DAINT	months and the contract of the section of the secti	3206	GARFIELD		80538
ALTODOM MAN HOUSE		3310	GARFIFI		80538 Auto Parts
Action of the state of the stat	the second secon	33.7	N GARFIELD AVE	The same of the sa	80538
STON DAI ACE SOF	Coake Minachi	3320	GARFIELD		80538 Restaurant
	The second secon	3325	GARFIELD		80538 Per care
OK 1500 Blie Rive SKY 100 100	Spirite manufacture and control of the second control of the second control of the second control of the second	3329	GARFIELD		80538 Bar
	The second secon	3400	GARFIELD		80538 Octhing
	and the contraction of the contr	3400	GARFIELD	#2	80538 Clothing
Indian Double	the state of the s	3408	GARFIELD		80538 Rent Equipment
	The management of the second o	3409			80538
	The second secon	2/12	C THE CALC	contrate the second sec	80638
OOTH, OALS V	Which will design a separate and the design behavior as a second of the design of the second of the	3 600		AND THE PERSON NAMED OF PERSONS ASSESSED.	000000
	The second of th	200		× (1-) * (-)	
	en e de la em quempa y e for o o o o o o o o o o o o o o o o o o	3511	GARFIELD		80538 Xeiail
	World Beverage	3965	GARFIELD		80538 Liquor
		3690	GARFIELD		80538 Pharmacy
CHERKANDE NORTH DROPERTIES I C	e partico de partico de como esta de como de partico de partico de partico de partico de como de partico de co	3780	GARFIELD		80538
これ こうがん しつぶつかい コージングログラング アンスローン 次次 かか しつぶつ アンスログン		3915	GARFIELD		80538 Lumber
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	The second of th	4100	CARFIELD	SHOP	80538
0 × × 00000000000000000000000000000000	ACAL ANOMAR ANOTHER AND TORY	7101	N GARFIELD AVE	a to be a few management of the state of the	80538 Auto
MODELLA CONTRACTOR OF THE STATE	1	4109	GARFELD		80538
A A A VACOL C TAIL OF A A A A A A A A A A A A A A A A A A	and the continuation of the property interesting in the continuation of the continuati	4118	G FIFE D		30538 :
AVICEL, MICHALLE O	market final from the country of Company and Comments and the first market special section of the first market mar	OOF	CHREAC		80538 [20]
COCCUPATION OF THE PROPERTY OF	to the second se	7.50	CARFIELD	C	80538 8000
CONTROL CIVING OF TOOL OFFI		0077		‡ :	80538 Detail
ららればいいでは、ことになっている。	TO THE THE PARTY OF THE PARTY O	0000) <	000000
OGRESSIVE IVING STRUCTURES	many and experience of the experience of the control of the experience of the experi	25. 4 25. 1	ではいいにはいい	¥.	00000 Neigh
nsiteam GS, LLC	e e company e de la participa de la company de la participa de la participa de la participa de company de la participa del la participa del la participa de la participa del a participa	4194	GARFIELD AV	a contra a prima terrativativativativativativativativativativ	80538 Office
NAMES AND NUMBERS		4195	GARFIELD AV		80538 Advertising
Republic Modasae of CO		4193	GARFIELD AV	~	80538 Retail
		4200	GARFIELD AV		80538 Office
WE & TRAVEL INC		4202	GARFIELD AV		80538 Retail
England who made where the second and the second se	Ouslity Mortgage Solutions	4204			80538 Office
1. CAR ()	The second secon	4206	GARFIELD AV		80538 Insurance
ATTER DIRECTOR & THATER OF ST	and the second second section is a second section of the second meaning of the second deposition of the second meaning of the second section of the second s	4208	GARFEID AV		80538 Piumbino
2010 TO COMO STATE TO	to the state of the property of the state of	4208	GARRETT DAV	And the second s	
SACIONAL MANAGEMENT CONTRACTOR CO	A DESCRIPTION OF THE PROPERTY	4212	CARFIELD AV	A hand depart to good a pool about a second on second	80538 Per care
	A STATE OF THE PROPERTY OF THE	3707	CADERT D AV	C01281	00
として元をし、とはいるという。		0. At	CADDE CEO AV	3	1
エミナー こうこのの		00001		CATATE	00200
LIANO & PATHER CONST. INC	Valid associated de passine as finalists tourist and the demonstrator is compressed extension included and in their	4000	いていいによいい	721000	
POESCH! DON		4520	GARFIELD AV	COHO	80238
CITY P&R NORTH KROH PARK WATER		2002	GARFIELD	WATER	80538
Y D&R NORTH KROH MAINT SHOP		5200	GARFIELD AV	NINTC	80538 Park
The second of th		C 11 C 1	NY CHUUCKC	•	Secure Concess

		a Num	Cr. Vreet	משונ לכים	≿
NEW WOON Enterprises		5400		80538 Bar	
		 		80537 Cond	rete
PROFORMANCE MFG INC	AND THE PROPERTY OF THE PROPER	: 125	•	80537 Diese	
Delaney, Karn L		1319	!	80537 Tables	Ş
NNEY, KARIN L		1323	į.	80537 Posters	SrS
CO PLUMBING & HEATING INC		(327	3	80537	a . T
SANCO PLUMBING & HEATING INC		1331	S GARFIELD AVE	80537	
TEL TECHNOLOGY INC	Acceptable to the first property of the first property of the property of the property of the first property o	1335	:	80537	
TA ENVIRONMENTAL CONSULTANT	AND THE PARTY OF A TAX COMMENT OF A TAX	1343	;	80537	
MITVIEW COMMONITY CHURCH	TO THE PARTY OF TH	1347	!	80537 Church	t;
Shepard, Wills R		1351		80537	
ng/Surfaces		1355	1	80537	
WITACCA, BRYAN		1359	ž.	:80537	
PROSCI		1363	*	80537	
OUALITY LEADERSHIP CNTR INC	PROSC	1367			an l
THE ROOK CHURCH		1371		80537 Church	tš
CONTROLS ENGINEERING & SERVICE		1375	-	80537	
TROLS ENGINEERING & SERVICE		1383		80537	
ATRIC SRVCS OF AMERICA	PSA HEAL THOARE	1387	?	80537	
NSCHUSTER STEPHAN		1391	1	80537	
M STRUCTURAL ENGINEERING		1385	, ,	80537	
SOUTHWEST BUSINESS PARK ASSOC		1388		80537	
Drake, Lawrence/Teresa	Teal International Corp.	380	1 .	80537	
SOUTHWEST BUSINESS PARK ASSOC		1380		80537	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
DSAMARITAN		2161			ly Care
OSAWARITAN	Kitchen	2101	. ;	HOUSE 80537 Elder	iy Care
GOOD SAMARITAN		2101		80537 Elder	ly Care
RICHMOND AMERICAN HOMES	erne er	1750	SEORGETOWN CT	80538	
CECIL JENNIFOR		2904	SINNALA DR	80538	
L JENNER	A MANAGER A MANAGER WAS A MANAGER AND A MANA	2906	GINNALA DR	80538	
		2910	SINNALA DR	80538	
CEOIL, JENNIFER		2912	GINNALA DR	80538	
JMC-HEAL TH SOUTH LLP	TO THE TAX THE	2923	GINNALA DR	80538	
BMALOVELAND		2940	SINNALA DR	80538	
ills The apy inv LLC		2964	GINNALA DR	80538 Medica	, in
als Therapy invite		2964	SINNALA DR		
Osisu Dr Timothy		2980	SINNALA DR	80538 Eyecare	916
Dr Timothy/Elizabeth	enderly a first control of the contr	2980	SINNALA DR	80538 Eyecare	9.00
h South Rehad	de production de la companyación de description (a companyación de la	2988	GINNALA DR		ds
NOK INVESTIVENTS, LLC	e de la companya del companya de la companya del companya de la companya del la companya de la c	2982	GINNALA DR	80538	
D E BURNS CONSTRUCTION		2996	SINNALA DR	#102 80538	
EBS INC		1209		80537 Roof tru	เพรระธ
SUNG GONG PROPERTIES, LLC		5010	SRANITE ST	80537 Office	A1
ERSON, KIM	FOUNDATION ENGINEERING	5110	ш	80537 Office	
500460 952040:R9	THE PARTY OF THE P	000	FO 01:22 C	TOUCK.	¥ = '

COSTORING Nation				5	Constant of the Constant of th
IST CHURCH OF CHRIST SOIE		409		-	0537 Church
1ST CHURCH OF CHRIST SOIE	and the same of th	408	;		80537 Church
IST UNITED METHODIST CHURCH		533	N GRANT AVE		80537 Church
1ST UNITED METHODIST CHURCH	The second secon	533		WWTR2 8	80537 Church
THOMPSON R2J SCHOOL DIST		637			0537 School
NEW HORIZONS TRAVEL		3701	N GRANT AVE		80538 Travel
LAND TITLE GUARANTEE COMPANY	e de la comprese del la comprese de la comprese de la comprese de la comprese della comprese de la comprese della comprese della comprese d	3705	, ,		0538 Office
SORWING BANKIVILLS FARGO	TO THE PROPERTY OF THE PROPERT	3710			30538 Bank
Rocky Wountain Othopedic		3810	N GRANT AVE		0538 Office
ALPINE EAR, NOSE & THROAT, INC	t	3820	•		0538 Office
SUNDANCE PROFESSIONAL BLDG LLC		3830	N GRANTAVE		80538 Office
COMPREHENSIVE SPINE & REHAB	and the second s	3830	7 1		0538 Office
DECKER PROPERTIES	e de la companya	3850		ì	80538 Office
	a de la companya de la major de la productiva de secretario de la companya de la companya de major de major de	3850	N GRANT AVE	#210	0538 Office
HOXER PROPERTIES	entended to the control of the contr	3850			0538 Office
A CONTRACTOR OF THE PROPERTY O		3850		EMTR2	30538 Office
MECKER PROPERTIES	AND THE RESERVE OF THE PROPERTY OF THE PROPERT	0886		i	10538 Office
		3880	N GRANTAVE	#100	10538 Office
S N PROPERTIES		4006			80538
Cadoka LUP		1218			10537 Design, test, assemble
LOOMIS STORAGE		1225	S GRANT AVE		80537
schmidt Custom Floors	e e e e e e e e e e e e e e e e e e e	1264	- 1		0537 Flooring
Citadei CO warehouse invest II		1268		2	80537
lowen, Devid M	A SAME TO THE REAL PROPERTY AND THE PRO	1272	S GRANT AVE	and the same of th	80537
secon, Debra		1276	S GRANT AVE	Y	
J Bar R Woodworking		1280	S GRANT AVE		
1		1284	S GRANT AVE	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	80537 Consulting
SPRINGFIELD, CWCO		1284		BLDGA (
Wells Fargo Bank		1412	HAHNS PEAK DR		œ
		5100	HAHNS PEAK DR	3	
í		5200	HAHNS PEAK DR		80538 Office
DO OFFICE II LLC	Kroll Factual Data	5250	HAHNS PEAK DR		
THOMPSON R2J SCHOOL DIST		248	N HARRISON AVE		80537 School
DYKES. NEIL		1841	HILLARY DR		
MEANUEL LUTHERAN CHURCH		Ö	HILTOP DR		· ·
IMMANUEL LUTHERAN CHURCH			HILLTOP DR	CHRHZ	h i
MANUEL LUTHERAN CHURCH		101	HILTOP DR		80537 Church
XOCH, LLC		1632	HOFFWAN DR	1	80538
XCCH, LLC		1632	HOFFMAN DR	#¥	80538
XCCH, LLC		1632	HOFFWAN DR		80538
Soeding, Marvin A	Simply Massage LC	1762	HOFFWAN DR		80538 Massage
LINESTEN, R. KRINE		2204	HOFFWAN DR	,	80538 Medicaí
ENGLERT, TEORES		2216	HOFFWAN DR	4	80538 Medical
CRYOGAM COLORADO INC		2216	HOFFWAN DR		80538
SUPPLICATION OF THE PROPERTY O	The second secon	4995	HORNBEIGN CT		(0528)

IJ	
ŭ,	
COPER	
_	
Ď.	
as defined by	
1	
Ö	•
મો તક હેલ	
ū	
erc	
Ē	
ä	
il Commercia	
treatment	
Ē	
8	
Ö	
α.	
ά	
1800	
8	
8	
Loveland	
ੋਂ	
ਹ ≿	

Cos(Circle Note 12	mentioners etimo estamana estamana communica anamana compressiona em professorios.	S NOW	Dir Street	ie S	Zip Activity
FOGLEMAN DALE L	e Maderi Calaba di Microsoft i da an estado e popula de Sport de Calaba (Calaba Calaba) de desperado a estado de Sport de Calaba (Calaba Calaba) de Calaba (Calaba) d	804	MPERALOT		80537 Office
REOKLING, DANA L		345	- 1		80537
E. I. WEDICAL		348			80537
Cameron, Steve T		340			80537
WHITE, AMY D		419			80537
LINESLEY, R KENT		530			80537 Seif defense
Grey Star Construction		. 250	N JEFFERSON AVE	EMTR2	80537 Laundiny
y Star Construction		. 550		EMTR3	80537 Laundry
S AUTO PAINT & SUPPLY		1410		EMTR2	80538 Paint supplies
ALEY, KENNETH	THE RESERVE OF THE PROPERTY OF	125	•	1/2	80537
LKE, DAMEL M	Company of the first of the fir	205	:		80537
THOMPSON R2J SCHOOL DIST		743	JOCELYN DR	SCHOL	80537 School
VINEYARD		006	JOSEPHINE CT		80537 Church
WARD CONSTRUCTION	CONTRACTOR OF TANKING TO A PART OF THE PAR	006	JOSEPHINE CT	#1/14	80537
WIEGE, DANIEL L/	FORKTORN TAXIDERMY	006	JOSEPHINE CT	È	80537
WARD CONSTRUCTION	makkement, jose josetanie se s kydnomi gominejakonatomi stajeta, postojakominatomi systeksje kanak	006	JOSEPHINE OT	#2612	80537
KAINTZ OOMPANIES, INC	THE REPORT OF THE PROPERTY OF	9	JOSEPHINE OF		80537 Cabinets
Y PIRE SUPPRESSION	the state of the s	251	ANOBOONE DR		
EN LAKES RESERVOIR CO	in the companies of the particle of the companies to the Companies of the	2915	AKE DR	The second secon	80538 Office
WONDERFUL DRAGON INC	the second of th	120	έ.		80537 Restaurant
STEELE, RAYBURN N	received a series of the serie	200	N INCOLN AVE		
Armstrong, Grenv/Robin	AMERICAN PARTICIONAL CONTRACTOR AND	201		A Company of the comp	80537
WHY NOT NOW INC	dens som en bedragen i denskanden betragen i prompter om det skalenden med en prompter op bedragen og den op En skalenden i denskanden betragen en betragen en beskanden en beskanden en beskanden beskanden og den op den	234	5		80537
VBY, JOHN	C	300	•	The second supplies to the transplantation of the property of the second	80537
Thrift Store LLC		315		Company of the second	80537
OTEX ELECTRIC CO	 Open o proposo para de la comprese de comprese de la comprese del la comprese de la comprese de la comprese de la comprese de la comprese de la comprese de la comprese della comprese de la comprese de la comprese de la comprese de la comprese della comprese del	316		1	80537 Supplies
Find Thrift Store	to de la company de la grande de la company de la comp	319			80537 Refail
Find Thrift Store	AND AND THE CONTRACT OF THE CO	321		1	80537 Retail
EASTER ENTERPRISES INC.	The Cove	330	N LINCOLN AVE		80537 Bar
TER, ALICE LYNN	en de la companya de	330			80537 Retail
TER, ALOE LYNN	Manager of the second of the comment	330		Q#	
TER, ALICE LYNN		330			****
TER ENTERPRISES INC	en de commercia de mandra de la compansa de compansa de compansa de la compansa de la compansa de comp	330		, [80537 Retail
TER, AUGE LYNN		330			
PROBASCO, PAUL	mente i mandra del como de terra de la casa de mandra del mandra del casa de mandra de mandra de la casa de la	342			80537 Retail
WEI, CHARLES/DENISE		365		A Company of the Comp	80537 Travel Agency
아 REALTY		405		-	Office
OH, DANSEL G		407			80537 Office
STROH, DANIEL G		407		#104	80537 Office
Skaer, Stephen A		411			80537 Office
DESMOND, BOB		415		7	80537 Office
Heartland Café		420	N LINCOLN AVE	~	
CARLISLE, CLYDE	Maggie's Treasures	426		~~	80537 Retail
THOMPSON VALLEY ART CEAGUE	TOP 10 - COMPANY TO CASE AND	429		3	80537 Office
こくがき はじじその かくべきの ほのた					

Justomer_Name		St. Non	Dir Street	Š	Zp	Activity
THE BLACK STEER (INC.)	The state of the s	436		mw.''	80537	Restaurant
HE BLACK STREE (INC.)		436	N CINCOLN AVE	EWTR2	80537	Restaurant
Independence Gallery		44C	N LINCOLN AVE		80537	An
Schuett, Kimberlee A	Quefico Dreamer LLC	444	N LINCOLN AVE		80537	
HIGGINS & ASSOCIATES LLC		502	N LINCOLN AVE		80537	
HOME STATE BANK		541	N LINCOLN AVE		80537	Валк
SULLIVAN LOVELAND LL.P	Lincoln Place	550			80537	Food
SULLIVAN LOVELAND LL.P		560	N LINCOLN AVE		80537	
IRST NATIONAL BANK		750			30537	ตูลาห์ ร
SHome Resitors L.C.	er e	770	LINCOLN AV		80537	Office
FIRST CONG CHURCH		800	N LINCOLN AVE	management the resident despites and the part of the state of the stat	80537	Church
Jefonseka, Brian		808	1	and the second s	80537	Gas
LACK TIE SALON		832	N LINCOLN AVE		80537	Office
VI. SON, TRACY	THE REPORT OF THE PROPERTY OF	. 840	LINCOLN		80537	Office
BALL VENOETLOR	er e	903	N LINCOLN AVE	}	80537	Office
(andazzo ins Agency		925	LINCOLN		80537	Insurance
Globok, LLC	Kings Court Motel	928	LINCOLN	EVMMT3	80537	Motel
Globok, LLC	Kings Court Motei	928	LINCOLN	WMTR5	80537	Wolei
Jobok, LLC	Kings Court Motel	928	LINCOLN	WMTR6	805	37 Matel
obox, LLO	Kings Court Motel	928	LINCOLN AV	EMTR1	805	Motei
Globek (LC	Kinds Court Motel	928	LINCOLN	EMTR2		Wotel
ANC ONE #512547	and a supplementary of the companies of the property of the companies of t	975	N LINCOLN AVE	WMTR1	80537	Bank
ANO ONE #512547	en en samme de en management que la productiva de la production de la prod	975	1	WMTR2	80537	Bank
100	ra maka makandara produkti na makandara makandara makandara makandara makandara makandara makandara makandara m	1006	LINCOLN	Agental Andreas and the state of the state o	80537	Office
	Main Street & Company	1021	LINCOLN		80537	
	no realise describe a la maine, se un militar information management de la company de la company de la company	1031	N TINCOLN AVE	while the contract of the cont	80537	-
ARIMER COUNTY TITIE COLLC	 The state of the s	1032	LINCOLN	EMTR1	80537	County
Global Markeling Cons L.C	and a separation of the second	1041	LINCOLN AV		80537	interior and a second construction of the second
HOTIS, BRUCE	The second of th	1047	N CINCOLN AVE	OFFIC	80537	The second of the second secon
AO Editorio	a todaya da a	1073			80537	0ff.ce
WALTON, ROBERT/TONIA	AND WAY ON WITHOUT THE PROPERTY OF THE PROPERT	1109]		80537	e de la companya de l
NOTION JUNKY	McKee House (Sweet Rosie's Too)	1120	N LINCOLN AVE		80537	Restaurent
		1135	N LINCOLN AVE	#: (O	80537	Hair care
		1135	N LINCOLN AVE	#2	80537	Insurance
0.520833333	3333	1,35	N LINCOLN AVE	*1:	80537	Massage
xpress Services-Temp & Perm		1135	LINCOLN AV	9#	80537	
SSCLUTE SURVEYING, INC.		1.35		## (C)	80537	
spinoza, Rebecca	Espinoza's Services	1135	: :	4F	80537	
SAGE HOLISTIC HEALTH		1136	Z CINCOLN AVE		80537	
STTEMAN, LINDAK	Ms Altie's Tea room	1140	N LINCOLN AVE		80537	
& JAUTO SERVICE CENTER INC		۸ بارا			80537	Tires
& TIRES		1203	LINCOLN		80537	Tires
SOHMO ENGINEERING		1204	N LINCOLN AVE		80537	
Cheaper Keepers Cars		1243	N LINCOLN AVE		80537	Auio
	The same of the sa			The second secon		The second secon

	: : :
Sefined by CDPHE	•
t Commercial as o	***
d - Pretreatmen	
City of Luvelan	Contract Alas

Customer_Name	NOT TON	Eng io	Dir Street	Unit	(Zip Activity
KUNISCH, ROLAND	THE PROPERTY OF THE PROPERTY O	1259	N LINCOLN AVE	to the second se	
KUNISCH, ROLAND	de de la companya del companya de la companya del companya de la companya del la companya de la companya de la companya de la companya del la company	1263	NCO N AVII	AND THE PROPERTY OF THE PARTY O	20537
VAN BARBN, FRANK	TO AND MOVED OF THE STREET OF	1305	1.	Andrew or managed to make the state of the s	80537
HOPE CHRISTIAN FELLOWSHIP	a de des des des des des de la comparte de la comp	1305	1.	CHRCH	3
FOUNDATION CHIROPRACTIC PC	A MANAGAM MANAGAM AND A CONTROL OF THE STATE	(327	N LINCOLN AVE	EMTR3	80537
PALO ALTO INC (taco Bell)	TACO SELL #1419	1330			80537
THE BAILEY CO	GOOD TIMES	1355			80537 Fast Food
HARMAN-EDIE, INC (KFC)	1	1356		a padamatente esta alemana antique esta carro a canadana antique de la carro d	80537 Fast Food
GENERAL PARTS, INC	DBA: CAR QUEST OF LOVELAND	14:50	N LINCOLN AVE	MTR 2	80538 Auto
State Farm	AN EXPENSION OF THE PROPERTY O	1410	N LINCOLN AVE		80538 Office
State Farm	Tender to the te	1410	N LINCOLN AVE	MTR 1	80538 Office
SORENSON, ARTHUR		1416			80538
FAST VIDEO IMAGES		1420			80538 Videos
LOVELAND TRAVEL KING	(Słackjack Pizza)	1505	N LINCOLN AVE	#	80538 Office
PELLE BECKY	BEDECKO	1505		#22#	80538 Office
HUNTER, CHRISTIE		1505		**	80538 Office
MED POOL PROFESSIONS INC		1505		St	80538 Office
ASPEN HAIR STUDIO		1508	N LINCOLN AVE	and the second second second second second second second second second	.80538 Hair care
PETERSON, JOHN W		1528		in a company of the same of th	80538 Office
LABOR READY INC		1528		#2	80538 Office
A Ace Mirigage Services, L.C.	The state of the s	1528		7.5	80538 Office
B & R CHECK HOLDERS INC		1528		##	80538 Office
The Soul mage	Birthright BP 06-1592, 8:9:06	1528	N LINCOLN AVE	4.	80538 Office
NORBEL CREDIT UNION	i	1531		#3 **	
NORBEL CREDIT UNION	The second of th	1531	N LINCOLN AVE	#	80538 Bank
NORBEL OREDIT UNION		1531	N LINCOLN AVE	#2	80538 Bank
NORBEL CREDIT UNION		1531	N LINCOLN AVE		30538 Bank
Set Frae		1601	N LINCOLN AVE		
FWHT INC	TACO JOHNS OF LOVELAND	1635	N LINCOLN AVE		80538 Fast Food
IST CHRISTIAN CHURCH	The first of the f	2000	ř	EAN H	80538
WOLDNK, GERHARD		2121	N LINCOLN AVE	EMTR1	80538
WULLINK, GERHARD		2121	į.	EMTR2	8053
RUNZA DRIVE INN		2204	N LINCOLN AVE		
NETWORK AUTO SOURCE INC		2205	 }		
PEER_ESS TYRE CO		2216		The state of the s	80538 Tires
MEYER DEAN W	DAVE'S LOCK & SAFE	2316	7	The state of the s	80538 (Retail
SWEETHEART LANES	The second secon	2320	N LINCOLN AVE		
Pitoui Tettoo		2424		The same of the sa	80538 Tattoo
KINKO'S COPIES		2520	5	And the second s	80538 (Copying
THE EGG & LRESTAURANT		2525	N LINCOLN AVE		80538 Restaurant
NORLARCO CREDIT UNION		2529	100	শ্ব:	80538 Benk
NORLARCO CREDIT UNION		2529	N LINCOLN AVE	α¥.	80538 Bank
Oikos Compeny	TOTAL VIOLENCE TO THE STATE OF	2529		Q#	80538 Bank
NORLARCO CREDIT UNION	A TOTAL CONTRACTOR OF THE STATE STAT	2529	N LINCOLN AVE	# #	80538 Office
THE READING OF THIS INC	Reading Clinic	2529	Z LINCOLN AVE	4£	S0538 Teaching

histomer_Name	m TOS	EN 55	Dir Street	- Cari	diZ	Activity
TIMEA		2529	N LINCOLN AVE	윺	80538 C	Office
A CONTRACTOR OF THE PROPERTY O	entral production and a comparation of the comparat	2585	,		80538 L	Lation
and the second of the second s	A SOOT IN WHOMASH CHEMINA	3305		A THE STATE OF A STATE OF THE S	80538 S	Storage
CONTROL TO THE TABLE INC.		3317	LINCOLNA	and and the same of the same of the same of	80538 C	Contractor
inst Street Stops	and you is considered and additionable is equal and a family of the state of the state of the constraint of the constraint.	105	}	en e		Sions
HANDY GLASS	 Control to the control of a section of a section of a section of the control of the	106	S LINCOLN AVE			Glass
	era desperada e aportamiento maio desentación capada consecución como institución con establicación con establicación de esta	106	LINCOLNA	WATER		Glass
CARRION, ARMANDO JR	Antonio's Burilos Pius	1.16			80537 F	Food
imando Carrion Jr.	A TAN AND THE OWNER OF THE PROPERTY OF THE PRO	9	LINCOLN	1/2	80537	Food
ORMANEN INVESTMENTS		112	LINCOUN AV	EMTR2		
STOLTZFUS, GALEN G		137	LINCOLN	The state of the s	80537	e de la desta della dell
R& L Health Care Inc		156			7	Office
STICKLER, DAVID	e de la composition della comp	151			D	Wolei
ALVARY APOSTOLIC U P C		201	S LINCOLN AVE	, tur	80537 C	Church
COENSTON RADIATOR	A CALLANTINA MANAGEMENT AND AND THE WAS A CALLANT OF THE WAS A CALLANT O	212	S LINCOLN AVE	- 11		Waste Haufer
LVED DISCOUNTALVED DESIGN ONTR	entralista destructiones de la company de la	365	S LINCOLN AVE		80537	Household
VED DISCOUNTAVED DESIGN ONTR	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	360		12	·	Household
IVI D DISCOUNTIVED DESIGN ONTR	AND THE PROPERTY OF THE PROPER	360	· · · · · · · · · · · · · · · · · · ·	STORG	80537 F	Household
McVVinney/DKMP2	entered for the factor of the	401	i	WATER	80537	Vacant
WcWhiney/DKMP2	managadi ulba da managadi managada ing dingkang ngang ngang nanagan nanagan na da da managadi na da managada n B	401	S LINCOLN AVE		80537	Vacant
AEXIOAN INN	men en emmane en e	808			80537 F	Restaurant
SONIO DRIVE IN	to make a majoral contraction of the contraction of	857			80537 F	Fast Food
SX AUTO WO. STE #01481	and the first field to de think problem of the commentation and advance of the transfer import the transfer	ရာ တ လ			80537 A	Auto Parts
OWENS, OHRIS	Auto Body, Laundry, Pet Grooming	1000				Various
SABRIELSON, BOS E	1	1015	~	The state of the s	80537 A	Auto
ONES, BRENDA F	Buckhorn Heating/Air	1016			80537 P	HVAC
abrielson, Bob E		1021		**************************************	80537	
SKE ELECTRIC		1023	****		80537	The second secon
AUTGZONE INC #0829		1030	LINCOLN		ii-3	Auto Parts
OTAL PETROLEUM INC		1401			80537 C	Carvash
	Gustom Off Road Performance	1507	S LINCOLN AVE		N. i	Storage
LOVELAND GARDEN CENTER		1801				Plants
US BANK		2845	LINDEN CT			Dank
HOMPSON RZJ SCHOOL DIST	Lucille Erwin	4700	LUCERNE			School
SREAT WESTERN SALVAGE LTD		1000	1	WH101		Railcar repair
WARD CONSTRUCTION		1014	N MADISON AVE			
Genesis Innovations, Inc		1040	N MADISON AVE	angele privinger of page of passing a particular and a second		Cabinels
Genesis Innovations, inc		1040	MADISON	00 #	N	Cabinets
BEROUIST, JOHN		1166	- 1	#1248	80537	
HORRIX, WILLIAM		1392	N MADISON AVE		80537	
SRAYBILL BUCK		1396				A COMMAND AND A COMMAND A COMMAND AND A COMMAND AND A COMMAND AND A COMMAND AND A COMM
JORTH COLO CHRISTIAN BOOKSTORE		1518	N MADISON AVE	্ব শ্বঃ	80538	Books
NORTH COLO CHRISTIAN BOOKSTORE		15(8	N MADISON AVE	Ω Ω	80538	Books
North Madison Properties LLC		1518		BSOOK	80538	Service
THE STREET OF TH	THE RELEASE WATER A MANUAL WATER TO SHE WATER THE PARTY AND THE PARTY AND THE PARTY WATER THE PARTY WATER AND THE PARTY WATER	0 7 11 7	n K KCOCKE S	77	00200	77 C

a design and design of the Conference of the Con		EDZ Jo	らいこ	Street	້ອີ	7. Ö	Activity
SIEWERT, AUDRA	;	(U)	ń. N	MADISON AVE	**	80538	Refail
SIEWERT, AUDRA	der der i den de	1518	1	MADISON AVE	Q#	80538	Relail
North Madison Properties LLC	State of the state of the section of	1518	-	MADISON AVE	4	80538	Retail
North Madison Properties LLC	nearly state is the strain of a material fractionary problems and strain of strains.	1518	N	MADISON AVE	#	80538	Retail
WILLOW RUN PROF PLAZA		1717	5	ADISON AVE	UTIL	80538	Office
MILLOW RUY PROF PLAZA		. 1717	•	MADISON AVE	#2	80538	Office
RANDA KERRY L DC	ereka in den mendenan in Antana menden berakan menden berakan mendenden dan dia dan mendengan mendengan dengan	1717	,	ADISON AVE	#	80538	Office
WILLOW RUY PRO- PLAZA		111		NOISON AVE	C#	80538	Office
AILLOW RUY PROF PLAZA		A L & B	:	ADISON AVE	**	80538	Office
WILLOW RUN PROF PLAZA		1717	?	ADISON AVE	9,4	80538	Office
VILLOW RUY PROF PLAZA	Mortgage Center	1717		ADISON AVE	#2	80538	diam'r.
LOVELAND ART CENTER		2874	÷	ADISON AVE		80538	1
COBI ILC		129		IDISON AVE		80537	And the second s
Next Generation Holdings	s Boulder Cheescake & Desserts	<u></u>		NDISON AVE		80537	
Johnny's Kitchen	On the second se	101		VOISON AVE	And the state of t	80537	Food
	to the first offers are substituted as well-decided by the first being of the point of the following and the following the first of the	229		IDISON AVE	***	80537	
Shamiock Agn Servoe Inc Oi (e) TV TEST SEDVICES	er kann i deksim ili tay i sykommi odalim i dapodimin odi dasi direksi si kansandan i kana i kana i kanasan i s	233	S	MADISON AVE	Aller of Albert America and the second	80537	Milking equipment
STEET COURT OF THE		107	- 7	COOCIA AVE		00000	Control of the Contro
Machine for Jaion Aretan Inc		540		COCC AVE	and a second of the first stands	7500	าแก้ด
icolomba monación oyolom esta	Mary Charles (Control of Control of Control of Control of Control of Mary Charles and Control of Co	5.40		COOCS AVE		00037	THE STATE OF THE S
Anne Court Food office	ANNES SEES - COMESSOS AND CONTROPOSANDOS ANDRONES HABITANDOS ANDROSOS MATERIAS ANDROSOS ANDROSOS ANDROSOS ANDROSOS AND A SECULO SECULO AND A SECULO SECULO AND A SECULDA A SECUEDA A SECULDA A SECUEDA A SECULDA A SECUEDA A SE	C67	•	JOSON AVE	Address of the same of the same and the same of the sa	0537	
一門ではない。いいのではなるまと、アダス・アダス・アルスの		2105		MAP III OX		80538	0110
CONTINUO DAY CAKE CENTER INC	men in the control of the control to the control of	2109	17.	i	***	80538	
City Fire Suppression		4325	Z.			80538	Fire
	TO A COLOR TO A COLOR	5285	ž	- >		80538	Refail
esidence Inc	Boyd Lake Lodging	5450	M	m		80538	
THE OUTLETS AT LOVELAND	territorio de la constante de la composición del composición de la composición del composición de la c	5600	MC	m	VIST9	80538	Office
OSE CORPORATION	er e een de brook de besteerste de besteerste besteerste de besteerd de besteer de stade de besteerste de een e	2600	22			80538	
BOSE CORPORATION	The strategy of the second of the second	5600	MC	MCWH NNEY BLVD	A/C	80538	Retail
EVI'S OUTLET BY MOST #432	The second of th	5601	Z.			80538	Clothing
LTRA OF ILLINOIS, INC	en e	5602	MC	>-;		80538	Retail
THE OUTLETS AT LOVELAND	the same terms of the same of the same terms of	5604	S _N	MCWH NNEY BLVD		80538	
M-JACK INC		5605	S	MCWH NNEY BLVD		80538	Retail
20 MC	· · · · · · · · · · · · · · · · · · ·	5608	S			80538	Retail
Calendar Olub		5099	OM.	:>-	Andrew Company of the State of	80538	Rein
CSIC VENTURE, INC		5612	2	MOWHINNEY BLVD		80538	Reis:
		5613	Q.	MCWH NNEY BLVD			Retail
AMP COLEMAN		5616	NC.	WH'NNEY BLVD			
OUTLET RETAIL STORE, INC		5617	O.	MCWH NNEY BLVD		80538	
W SPORTS INC		5620	ON:			80538	Retail
Ohrisimas at Heart		5624	<u>~</u>	MCWH NNEY BLVD		80538	Retail
THE OUTLETS AT LOVELAND		5624	MC	WH NNEY BLVD		80538	Refail
KORET OF CALIFORNIA #430		\$625	OM.	ر ا		80538	Retail
RIME OUTLETS LOVELAND	po de samo aspes anadranque se par podrája missa pás apominas sembra sem samos se adestro se por se dominam con pod	5629	MO	MOWH NNEY BLVD		80538	Retail
NATIONAL MONTH A-90		5830	C	TAKE NAMEY BY VO		0000	7.45

Customer_Name	NOTE	S Zera		të j	Zip Activity
HEALTHSTYLES EXER EQUIP LLC		5633	TINNET.		80538 Retail
THE OUTLETS AT LOVELAND		5636	MCM/HINNEY BLVD		80538 Refail
WEI COME HOME A-90		5637	MOWHINNEY BLVD	The same of the sa	80538 Refail
	entre autoritation de la company de la management de la company de la company de la company de la company de l	5640	ä		80538 Clothing
THE COLUMN AT LOVE AND	mediatente de la compania de la comp	5643	MCWHINNEY B! VD		
	ere er er i skrivetet met i skrivet skrivet bet better er er kom i i en i det i in interest et det i kom er	5644	1		80538 Relail
SIG DOG SPORTSWITCH	exploration from the proof of the consequence of th	3645	:		80538 Retail
THE OUTLETS AT LOVELAND	The second section of the second second second second second second second section is a second secon	5648	m		
THE OUTLETS AT LOVELAND	den de la companya d	5649	MCWHINNEY BLVD	A CONTRACTOR OF THE PARTY OF TH	80538 Retail
THE OUTLETS AT LOVELAND	depending of the commonweal of the control of the c	5652	MCW-HINNEY BLVD		80538 Retail
KITCHEN COLLECTION	management of the second secon	5653	MCWHINNEY BLVD	The state of the s	80538 Relail
THE OUTLETS AT LOVELAND	ook oo dhaa ka k	5656	MCWHINNEY BLVD		80538 Refail
SPRINGMAID WAMSUITA	The same of the same and the same of the s	5657	MCWHINNEY BLVD		80538 Retail
THE OUTLETS AT LOVELAND		2660	MCW/HINNEY BLVD		80538 Refail
THE OUTLETS AT LOVELAND	Borders Outlet??	5661	8		(X)
THE OUTLETS AT LOVELAND		5661	MCWHINNEY BLVD		80538 Fast Food
Kitchen Door (LC	The second of th	5651	യ	HO/C	œ
THE OUTLETS AT LOVELAND		5664	MCWHINNEY BLVD		80538 Refail
THE OUTLETS AT LOVELAND		5565	MCWHINNEY BLVD		a)
SZIKASA FACTORY STORE #4.10	ŧ.	5658	MCWHINNEY BLVD		ω:
TABONE ENTERPRISES, LLC	ROCKY MIN CHOC FACTORY	5998	<u>ش</u>		80538 Food
THE OUTLETS AT LOVELAND	,	5672	전 전		ωį
THE CUTLETS AT LOVELAND	was Poor Boy's Pizza	5673	œ,	Î	80538 Food
THE OUTLETS AT LOVELAND		5674	MCWHINNEY BLVD	1	80538 Retail
THE OUTLETS AT LOVELAND		5674	ш >-:	HO/B	80538 Retail
THE OUTLETS AT LOVELAND		5674	~ 1	i	80538 Retail
J CREW FACTORY STORE		5676	MCWHINNEY BLVD		80538 Relail
JOREW FACTORY STORE	The second secon	9676	MC/WHINNEY BLVD	EMTR2	
PHONES PLUS, INC	de la calvar de la campa esta esta esta esta esta esta esta de la calvar de la calvar de la calvar de la calvar	5677	MOWHINNEY BLVD	A CONTRACTOR OF THE PROPERTY O	
Magic Wusic	A THE STATE OF THE PARTY OF THE STATE OF THE	5680	MCWHINNEY BLVD	To the state of th	
The Outlets at Loveland	The state of the s	5661	MCWHINNEY BLVD	Control of the Contro	20
WESTPORT WOMAN #2922		5684	CO :		
ZOD #843		5665	MCWHINNEY BLVD		വ
THE OUTLETS AT LOVELAND		2000000	MCWHINNEY BLVD		
VAN HEUSEN #347		8689	MCWHINNEY BLVD		*** * **
THE OUTLETS AT LOVELAND		5695	MCWHINNEY BLVD		
BASS COMPANY #427		5693			80533 Refail
WILLIAM CARTER CO		9699	ന		80538 Retail
GEOFFREY BEENE #120		5697	മ	The second secon	80538 Refail
RETAILER Z LLC		5700	MCWHINNEY BLVD		
['EGGS/HANES/BALI		5701	ω		80538 Refail
AMS Character Warehouse		5704	**	The state of the s	00
THE OUTLETS AT LOVELAND		5705	MOVENNEY BLVD	The same of the fact that the same of the	
Rue 21 Inc		5203	>-	The second of th	∞
Annual continues to the first term and the property of the continues of th	The second of th	C+12	C7-10 >U25-30 0000		

くぎ こくにしの ひしくじ ここうごうべんと		233 X		The second second second second second	
		5717	HINNEY		80538 Retail
LIZ CLAIBORNE #766		5720	MCWHINNEY BLVD		80538 Retail
WESTPORT LTD #0800/DRESS BARN		5721	MOWHINNEY BLVD		80538 Retail
WESTPORT WOMAN #2922		5721	200	MSTR	80538 : Retail
FURNITURE FACTORY OUTLET		5724	MCWHINNEY BLVD		80538 Retail
FACTORY BRAND SHOES #928 -	regions to the final to the control which was the control who were the control was the control of the control o	5725	:>-		80538 Shoes
FACTORY BRAND SHOES #928 .		5729	MCWHINNEY BLVD		
CASUAL MALE BIG & TALL	THE RESERVE OF THE PARTY OF THE	5732	:>~	and the same of th	80538 Ciolhing
THE OUTLETS AT LOVELAND	A CAMPAN THE COMMAND AND A CAMPAN AND A CAMP	5733	٠.	Committee of the commit	£
MAGNAVOX FACTORY OUTLET	THE PROPERTY OF THE PROPERTY O	5736	:>-		
THE OUTLETS AT LOVELAND	AND THE PROPERTY OF THE PROPER	5737	MCWH NNEY BLVD		80538 Retail
THE OUTLETS AT LOVELAND		5740	MCWH NNEY BLVD		80538 Retail
	Spirit Falloween	5740		of the control of the	80538 Retail
AT LOVELAND	e designations of the production of the producti	5741	٠,		80538 Retail
SORKSERA INC	A THE PARTY OF THE PROPERTY OF THE PARTY OF	5745	\ <u>\</u> \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		80538 Refail
REEBOX FACTORY DIRECT STORE	n professional and special special professional regenerates in the contract of	5749	MOWH NNEY BLVD	-	
REEBOX FACTORY DIRECT STORE	the state of the s	5761	MOWH NNEY BLVD		80538 Retail
OSHKOSH B'GOSH RETAIL INC.	The second second second and the second seco	5753	MOWH NNEY BLVD		80538 Clothing
FIRST NATIONAL BANK	Townson makes a figure of the property of the	5795	MCWHINNEY BLVD		80538 Bank
CRACKER BARREL #270	destructive and definition of the state of t	5800	MCWHINNEY BLVD	2	80538 Restaurant
Tommy Hilliger		5801		-	80538 (Retail
THE OUTLETS AT LOVELAND	THE CAN DESCRIBE A PROPERTY OF THE CANADA AND A CONTRACT OF THE CANADA AND	5803	MCWHINNEY BLVD		80538 Re(sil
SUNGLASS HUT OF CALIFORNIA		5805	MCWHINNEY BLVD		80533 Retail
BEAR CREEK STORES INC.	HARRY AND DAVID	5809	MCWHINNEY BLVD		80538 Retail
PAPER FACTORY OF W! #43708		5813	MCWHINNEY BLVD	4.0	80538 Refail
THE OUTLETS AT LOVELAND		5817	MCWHINNEY BLVD		80538 Retail
Wison'sLeather		5821	>-		80538 Retail
THE OUTLETS AT LOVELAND	Pizza /DQ / other	5823	>		80538 Food
TIMBER OKEEK HOMES		5823	MOWHINNEY BLVD		80538 Retail
TER OUTLETS AT LOVELAND		5825	>-		80538 Retail
THE OUTLETS AT LOVELAND	j	5827	MCWHINNEY BLVD		80538 Retail
BROWNS SHOE STORE	SAS FACTORY SHOES	5828	2		80538 Retail
FURNITURE FACTORY OUTLET		5833	MCWHINNEY BLVD		80538 Retail
LENOX INC	LENOX BRANDS	5837	MCWHINNEY BLVD		80538 HVAC
THE OUTLETS AT LOVELAND		5845	MOWHINNEY BLVD		80538 Retail
THE OUTLETS AT LOVELAND		5340	MCWHINNEY BLVD	.,	8
DEAN, RAYMOND 1		1321	MILNER AVE		80537
SIG THOMPSON MANOR INC		224	į	and the same of th	
SIG THOMPSON MANOR II		230	N MONROE AVE		80537 Elderly Care
JUSTICE CENTER PLACE		954			1
JUSTICE CENTER PLACE		976	i i		80537 Office
Sierra Builders		3	N MONROE AVE		80537 Office
Blundell Funeral Homes, Inc	(a.k.a Kibby Fishburr Funeral)	1108	MONROE AV		80537 Crematorium
KEARNS, JAY MIPINEY P		(172			80537
ZATOURIEK SYSTEMS INC		116	MONROE AV		80537 Molds

tomer_Name		Si Num	Dir Street	25	
		1120			80537 Molds
	and and it, it, in a part has maked the grant of a series of a ser	4.24			80537 Storage
CRADO TIME SYSTEMS	A MANAGEMENT OF THE PROPERTY O	1328			80537 Assembly
ROCK SOLID MARBLE&GRANITE LLC	AND THE CONTRACTOR OF THE PROPERTY OF THE PROP	1132			80537 Counter to
X SOLID MARBLE&GRANITE LLC	The second secon	1136			80537 Counter tops
Was Aroeia	and community to the control of the	1150		#2	80537 Stcrage
Automation	the experimental fractionals and thereof another makes policies of the first of the decision of the	1150		\$±	80537 Stcrage
NOE ELECTIVO	to a trade to the first of the	1150		1.	18.
		1150		\$\psi_0\psi_4	80537 Storage
Stewart, Barry	the same and the s	1150		4# 60	P
Stewart, Barry	and the same and t	1150		4,4	80537 Storage
	ANALOGO CO. CON MANAGO CON CONTRA CANTA CANTA CANTA CONTRA CANTA CONTRA	1208			
RELAN, WAYNE	to the control of the	1220			80537
BETHORISM ALE	AND THE RESIDENCE OF PRINCIPLES OF PRINCIPLES OF THE PRINCIPLES OF THE PRINCIPLE OF THE PRI	1300			80537
EDWARDS, JM D	entre de la companya de destaca de la companya del la companya de la companya de	1330		.,	80537
Section of the section of the section of	THE CONTRACT OF THE CONTRACT O	1403			80538 Pet care
	nna anna 4 Iomradalan channan anna channan channan ann ann ann an ann an ann an ann an a	1500		WATER TER	80538 School
MPSON R21 SCHOOL DIST	design for the design of the form of the f	1500			80538 School
***		2585			80538 Church
SALL MODER SONCOL		2660			80538 School
2884 : [C		2881			80538
MPSON R2J SCHOOL DIST		2890	N MONROE AVE	The state of the s	80538 School
ve All Morlagde Services	ramed france and other names of development of	2893			
ROH OF GOOD SHEPHERD		3429		. ,	80538 Church
PSKI, DREW	No. of the control of	210		, ,	80537
DEMPSKI, DREW		210		SHOP	_
Moose Lodge	No kitchen at this time	1408	MORNING DR		00
THOMPSON RZJ SCHOOL DIST	Mountain View	3500	MOUNTAIN LION DR		80537 School
r Dey Seints		3800	MOUNTAIN LION DR		80£37 Church
HOME DEPOT STORE #1529	And the same of th	1100	NICKEL DR		80537 Lumber
STIVEN CAKE SHOP	eren er skriver er skriver og det de skriver er skriver er skriver er skriver er skriver er skriver er skriver	1975	PARKOR		80538 Park
j	Administration of the property	3755	Precision DR		80538 Office
2		3855	Precision Dr	160	80538 Office
		1405	PROSPECT DR		80538 Retail
S COMMUNTY COLLEGE		310		EMTR1	80537 School
OL CARS ONLY LLO		320	RAILROAD A	EWTR2	80537
STAL LANDSCAPE & GRADING	en e	323	1		80537 Construction
JOHNSON PRINTING-LOVELAND	en de de la completa	(07	RAILROAD A	and the same of th	80537
of Fools inc	Sports Station	409	RAILROAD	And the state of t	80537 Restauran
Colena I C & PMC II C		427	RAILROAD		80537 Office
OHY 3101		450	N RAILROAD AVE	A Large Car	80537 Office
SSROADS COVENTANT CHURCH	The second second and the second seco	401	RAILROAD	EMTR1	80537 Church
CROSSROADS COVENTANT CHURCH	The second secon	451	RAILROAD AV	WATER	80537 Church
Terra Soft Solutions	The second secon	451	N RAILROAD AVE	#102	80537 Sofware
statements and was not the second termination in the first of the constitution of the second termination of the second ter	the second of th		17 CACO 14 CACO	#40Z	0.0507 Co.: 0.000

The state of the s	법 : Og .	- SI NUM -	Ur lareet			710	Activity
erra Soff Solutions		451		••••	<u>%</u>	80537	
		514	N RAILROAD AVE			80537	Retail
SLACK, JOHNS	the second section of the second section is the second section of the second section of the second section sec	(5) (5)	ě.		de la	80537	Retail
VLO-BERTHOUD ASSO OF REALTORS		730		contract of the state of the state of	Commence of the contract of	80537	Office
WILLIAMS, TOM W	contribution by the shirt and the contribution of the contribution	103	1	ii)	EMTR4		Mechining
ENTIMANS FREEZER MEATS	A CAMPAGE AND	207	7			80537	Meat Processor
CITY FOMAN FAIRGROUNDS	a serial companies and water constructions and assessment of assessment of the construction of the constru	700	S RAILROAD AVE	M	WMTR1	80537	Misc
ITY FOMAN FAIRGROUNDS	and order of the following control of the control o	700		111		80537	Misc
TY FOMAN FAIRGROUNDS	s and it determines a parameterial of parameterial and it and and it includes the armeter assembles as measure	700		M		80537	Misc
CITY FOMAN FAIRGROUNDS+D336	AND THE THE PROPERTY OF THE PR	700	4	M		80537	Misc
AGILENT TECHNOLOGIES		701	į.			80537	Vacant
CITY P&R NORTH EDMUNDSON PARK	to the state of th	4900	RANCH ACRES DR			80538	Park
RIGGS, JUDY/ELVIN	Blue Light software	802	REDWOOD DR			80538	Software
ENDY'S RESTAURANT #350		1405	ROCKY MOUNTAIN	AVE		80538	Fast Food
RINKER REST CORP INTL #597	SHO	1425	ROCKY MOUNTAIN AVE	AVE		80538	Restaurant
OF NYY CARINO'S		1455	ROCKY MOUNTAIN	AVE.		80538	Restaurant
COLORADO RESTAURANT MNGVIT	Black Eyed Pea	1505	ROCKY MOUNTAIN AVE	AVE	6 T.T.	80538	Restaurant
Good Times/Taco John's		1535	ROCKY MOUNTAIN AVE	AVE		80538	Fast Food
otrame), Kesneth David	Chick FlyA	. 1545	ROCKY MOUNTAIN AVE	AVE		80538	Fast Food
OCKY MOUNTAIN MARKET		1545	ROOKY MOUNTAIN	AVE		80538	Office
PORTSMAN WAREHOUSE		1675	ROCKY MOUNTAIN	ÀVE	:	80538	Sporting goods
Reliklax Action Brokers @ Centerra		1685	ROCKY MOUNTAIN AVE	AVE		80538	Office
PetSmert		1715	ROCKY MOUNTAIN	AVE		80538	Pet Supplies
McWhinney Property Group LLC		1715	ROCKY MOUNTAIN AVE	AVE		80538	Office
TARGET STORES	The second secon	1725	ROCKY MOUNTAIN	AVE		80538	Department Store
Hinkhouse, Cheryl	Sorub House	1739	ROCKY MOUNTAIN AVE			80538	Clothing
Odoba Mexican Grill	TO A TOTAL TO THE TAX A STATE OF THE PARTY OF THE TAX ASSESSMENT OF THE STATE OF THE TAX ASSESSMENT OF TAX ASSESSMENT OF THE TAX ASSESSMENT OF	1747	ROCKY MOUNTAIN		#140	80538	Fast Food
&L Subway	The second secon	1753	ROCKY MOUNTAIN	AVE		30538	Fast Food
METROPOLITAN MUDD COFFEE LLC	te i de desemble de la mesta de la desemble de la competa de la competa de la competa de la competa de la comp	1759	ROCKY MOUNTAIN	AVE		80538	Food
Sentley's Liquor, LLC	an kelada den denga kemandan kepada par - "dapa) in kara kebahan pagabengan pendiri angganan dengapan dengapan -	1763	ROCKY MOUNTAIN	AVE	#150	80538	Relail
REAL TECH		1767	ROCKY MOUNTAIN	AVE	1		Office
BRIDGER DEVELOPMENT CO. LLC	:	1775	ROCKY MOUNTAIN	AVE	~		Tood
RangeView Two LLC	Bank, Medical, Fairchild Semiconductor	2695	ROCKY MOUNTAIN	AVE	~		Office
	Youth Clinic	2695	ROCKY MOUNTAIN	AVE		and the	Office
MOWHINNEY MANAGEMENT OO	TO BE THE STATE OF	2725	ROCKY MOUNTAIN		200		Office
		3760	ROCKY MOUNTAIN				Vet Research
OTURCH OF OTREST	Service designation of the control o	731	N ROOSEVELT AVE				Church
OJTY P&R GOLFMT MBGC MAINT		499	ROSSUM DR				Golf
Oily P&R Golf	The state of the s	603	ROSSUM DR	æ	Rsim		Misc
_Owe's		1355	Sculpture DR				Lumber
Alterra Healthcare Corp		275	SHUPE CIR	per control and a second secon	***	80537	Elderly Care
Jared Jewelry		5802	Sky Pond Dr			80538	1
Sames & Nobel		5335	Sky Pond Dr	IL.	1	80538	Food
Centerra Lifestyle Center LLC	entrage of the contract of the	5855	SKY Pond Dr	ill.	1		Office
Trosporo A Colon Control Contr	as a complete destination of the byte special destination of the special speci	ADAR	20 2500	1	1		Account to the second s

Customer_Name	m FOX	 57	Dir Street	TE C	Ζ'n
		5855	Sky Pond Dr	F-142	80538 Retail
Ooldwater Oreek		5855	Sky Pond Dr	F154	80538
Ann Taylor Loft		5855	Sky Pond Dr	F-800	80538
SOMA		5865	Sky Pond Dr	G106	80538
BEBE Stroes Inc		5885	Sky Pond Dr	G172	80538 Gadgets
arks Shoes		5805	Sky Pond Dr	G130	80538
Yankee Candle	monotorios i lando interprise vergentalmente dependante de la	5865	Sky Pond Dr	G154	80538
Libban Homestead	a exercised in other cases, and a second process of the second pro	5895	Sky Pond Dr	G180	80538
interra Lifestyle Center LLC	andry de la faction de la faction de la companie de la faction de la companie de la faction de la companie de la faction de la f	5885	Sky Pond Or	O'HO1	80538
Centerra Lifestyle Center LLC	a de la companya	5865	Sky Pond Dr	C/HC2	80538
Hallmark Cards	AND THE RELEASE OF THE PARTY OF	5866	Sky Pond Dr	G138	80538
Dick's Sporting Goods	ed - service and to extra confidence and the service and the s	5875	Sky Pond Dr	E(dg →	80538
Centerra Lifestyle Center LLC	and the second of the second party and the second of the s	5879	Sky Pond Dr	L CLB	
nerican Eagle Cutifiters	The second secon	585	Sky Pond Dr	3100	80538
Bath & Body Works	erin i saman i tan i samanga panaka kataka saman saman saman na kataka manaka saman saman saman saman saman sa	5879	Sky Pond Dr	1512	80538 Re:ail
Express Clothing	AND THE PARTY TO BE AND THE PARTY TO THE PARTY OF THE PAR	5879	Sky Pand Or	2	80538
Victoria's Secret	the state of the s	5878	Sky Pond Dr	3154	
Centerra Lifestyle Center LLC	VALLE - VA CONTO TOTAL CONTRACTOR PRESENT OF PROPERTY OF PROPERTY OF PROPERTY AND ADMINISTRAL CONTRACTOR OF PROPERTY OF PROPER	5897	Sky Pond Dr	ACJ6	80538
Starbucks	After the American Court of the	5867	Sky Pond Dr	X153	
Charlotte Russe		5897	Sky Pond Dr	X100	80538
Pacific Sunwear	money programment and the market from the change from the change of the programment of the change of	7980	Sky Pand Dr	X118	80538
Genesco Inc	LDS	5897	Sky Pend Dr	X136	80538
PF Change		5915	Sky Pend Dr	R2700	80538
Biagg's Hallan's Bistro		5929	Sky Pond Dr	R2600	80538 Restaurant
Children's Place		50043	Sky Pond Dr	E142	30538
Gymboree		5943	Sky Pond Dr	E160	80538
White House Black Warket	The control of the co	5943	Sky Pend Dr	E184	80538
LensCraffers	Control of the Control of Control	5943	Sky Pond Dr	E460	80538
Portreit Innovations		5943	Sky Pend Dr	E136	80538
Centerra Lifestyle Center LLC		5943	Sky Pand Dr	SHO	80538
Centerra Lifestyle Center LLC		5943	Sky Pend Dr	E/H02	80538
Cinquiar		5948	Sky Pond Dr	E112	80538
Eddie Bauer		5957	Sky Pend Dr	D100	80538
Lemer New York		5987	Sky Pend Dr	C139	80538
Banan Republic		2992	Sky Pond Dr	D160	80838
JOS A Banks		1000 1000	Sky Pond Dr	0142	
Build a Bear Workshop	the Charlest trade of sections for Community and Community and the Community of the Communi	5982	Sky Pend Dr	D196	
Centerra Lifestyle Center LLC	e de la composition della comp	2000	Sky Pond Dr	D/HO1	80538 Re:ai
nferra Lifestyle Center LLC	THE REPORT OF THE PROPERTY OF	5857	Sky Pend Dr	D/H02	
Centerra Lifestyle Center LLC		5957	Sky Pond Dr	D/HO3	80538
Chapungu Gallery	era de la celebración de la compressión de la Calabración de la ca	5971	Sky Pond Dr	300	80538
in in	to foreign a version programme and the contract of the contrac	5971	Sky Pend Dr	C124	80538 Food
Sterling Jewelers	Kay Jewlers	507	Sky Pend Dr	C118	80538 Jewelry
April 200	a rate dan kanada da wamana kanada kanad	5971	Sky Pend Dr	C154	80538 Jeweiry
Corporation of the following of the contraction of	AND THE PROPERTY OF THE PROPERTY AND THE PROPERTY OF THE PROPE	1,000	Sky Drnd Dr	CHU	SOE30 Off.

Customer_Name	HOX	Num Num	Dir Street	TE C	ZID /	Activity
Centera Lifestyle Center L.C.		5971	Sky Pond Dr	#OHO#		Office
Seri Fork		5973	Sky Pond Dr	C106	30538	Restaurant
Sundisses Hut	化甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	1286	Sky Pond Dr	0130	80538	20191
Centerra Lifestvie Center LLC	mad someti fortament mentra monomen coprovidamentamento en contra el monomental, y dispositamente propriesamen	5983	Sky Pond Dr	PLAZA	80538	Relail
Regis Corporation #1163	a company of special control of the special c	5985	Sky Pond Dr	B118	80538	Hair care
Helzberg Diamonds	A CALL TO SEA THE THE MENTING WE ARE A CHARLEST AND	5985	Sky Pond Dr	B100	80538	Jewelry
Centerra Lifestyle Center LLC	es de la companya de	3985	Sky Pond Dr	8108	80538	Office
Foley's	Macy's Department Stores Inc.	5995	Sky Pond Dr	alda A	80538	Retail
Red Rebin	;	6005	Sky Pond Dr	R2400	80538	Kestauran.
BRINKER REST CORP INTL	On the Border	6015	Sky Pond Dr	R2300	80538	Sestauran
Swept Away Brida) Boutique	to annual control of any account of the property of the control of	6045	Sky Pond Dr	8112	80538	Clothing
Centerra Lifestyle Center LLC	A CANADA	6045	Sky Pond Dr	Bld R	80538	Office
Ten Salon & Spa	A CONTRACTOR OF THE CONTRACTOR	6045	Sky Pond Dr	R100	80538	Relail
Charley's Grilled Subs	A STATE OF THE STA	9055	Sky Pond Dr	P136	80538	ast Food
Schoffeld's Creamery	a de sale de sale de la composiçõe de la	8055	SXY Posd Dr	P160	80538	Food
Centera Liestyle Center LLC	the control of the co	8055	Sky Pond Dr	Bldg P	80538)ffice
Mr. Neals Formal Wear	and the first of desire parts of the second form of the second of the se	9092	Sky Pond Dr	p142	80538	Xe a
Same Stop	and influence of the control of the	8055	Sky Pond Dr	P148	80538	Retail
SNC SNC	The state of the s	5055	Sky Pond Dr	7154	80538	Retail
Centerra Lifestyle Center LLC		\$065	Sky Pond Dr	Bldg N	80538	Office
Centerra Lifestyle Center LLC	The second secon	9065	Sky Pond Dr	N/P/R	80538	Office
Pounce for Fun	ene i sera de energia de la comprese de la compres	5065	Sky Pond Dr	N118	80538	Relail
Best Buy Stores LP #663		6075	Sky Pond Dr	Bida M	80538	etail
Metrolux Theatre	AND THE PROPERTY OF THE PROPER	6085	Sky Pood Dr	Blog L	80538	Theatre
LONE STAR STEAKHOUSE #4909		5330	STONE CREEK OIR		80538	Restauran:
CHAMBER OF COMMERCE	A TRANSPORTED TO THE TOTAL OF THE TOTAL PROPERTY OF THE TOTAL PROP	3400	STONE CREEK OIR		80538 C	Office
THE GROUP, INC		5401	STONE OREEK OIR		80538)ffce
1422 INC	11HOP 1819 INC	5450	STONE CREEK OIR		80538 F	Restauran;
STONEBRIDGE MOWHINNEY LLO	Hampion fire	2500	STONE CREEK CIR		80537 F	Hotel
CHILDRENS WORKSHOP		4601	SUNVIEW OR		80538 C	Ohid Care
THOMPSON VALLEY HOSP DIST		4645	SUNVIEW DR		38	Amoulance
TUSKEN, RHETT R		704	N TAFT AVE		80537 C	Office
TUSKEN, RPETT R		705			80537 C)fice
TUSKEN, RFETT R		708	·		80537 C)ffice
BIG THOMPSON ANIMAL HOSPITAL		÷14	N TAFT AVE		80537 F	Petcare
STEWARD, MARY L	to the first of the first of the contract of t	903	N TAFT AVE		80537 C	Office
AMERICAN FAMILY INSURANCE		1442			80538	Insurance
Jivi NicEvox, Inc	ASPEN LEAF LIQUOR	1581	N TAFT AVE		80538.1	janor
Westlake Plaza II	The second secon	1585	N TAFT AVE		80538 R	Retail, Foco
YANTS TIM		1803	N TAFT AVE	AND THE PROPERTY OF THE PROPER	80533 C	Vilce
SHERLOOK, PATRICK DR		2203	N TAFT AVE		80538 C)((ice
CITY PAR NORTH NORTHLAKE UITS		2472	N TAFT AVE		80538 P	ž, X
UNIVERSAL COMMUNICATIONS CO		2641	N TAFT AVE		80538 C)ffice
Roger A Hulme, OD PC		2877	N TAFT AVE		80538	yecare
COLUMBINE GALLERY		2883	N TAFT AVE		80538 #	
The second secon	Maria Control of the	The second section and the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section in the second section is a second section of the second section of the second section is a second section of the section	Control of the Contro	THE STATE OF STATE OF STREET STATE OF S	and the management of the control of	A second of the

		ESZ	Dir Street	and the state of t	Cur	Zip Activity	***************************************
		2683	N TAFT AV	111	Ç	80538 Art	
COLUMNIE GALLERY	en ender de la comparable de la comparab	2683	:		4	80538 Art	
	de deservation de la compara de la compa	2683	ンベーゴグトーン		đặ CĐ		
CO IMPINE SALLERY	Services of the services of th	2683	1		C#	80538 An	de como de la companya de la company
TY FIRE SUPPRESSION	demonstrate and the control of the c	2750	:		FDEPT	80538 Fire	
TOVELAND LOAS CLUB		2750	N TAFT AVE	u	BARN	80538 office	
TY P&R NORTH NORTHLAKE 2	American in the second control of the control of th	2750	į.		MANH	80538	
TY P&R NORTH NORTHLAKE RIE	research was not seen to the second control of the	2750	:		RSTEM		Comprehensia Compr
ROSE ONE II C	and and design the state of the	3001	})		80538 Office	AND THE PARTY OF T
CHARD HOLSTAD ENG SVCS LLC	Spekaraten Frieder (Frieder), der deben spekaraten promiseraten, metart makkaten (Frieder), meta en indemensio	3001	1		#120	80538 Office	\$1.00 LB
ICAGO TITLE OF COLORADO	and we have a representation of the properties o	3001	N TAFT AVE		#100	80538 Office	
LARVIK ONF. LLC	many and by a serious and and a serious and another and a serious and another a distribution of the serious and the serious an	3013	TAFT	1	1	80538 Office	
veland Officoraclic		3025	TART	<u>u</u>	4F (0)	80538 Medica	ě
NNINGHAM JOSEPH 6	2	3025	I A	w		80538 Office	
ANSWATION THE PINS OF		3025	;	·	**	a	
MARRID ONES & CO		3025			#2	60	
DEN HOMEN OF COLORADO INC.	Seemly comprehensive transfer of the control of	3037	1	LU LU		ကြ	
I AND & PATHER DONNE IND	the control of the co	3037	5	i i		80538 Office	the state of the s
GOOD DATE AND TAKE DAYS		3041			***************************************	80538 Pet ca	fe.
CAN DESCRIPTION OF CARS DAME		3043		A CONTRACTOR OF THE PROPERTY O		80538 Pet care	re
TO DOOR SOUTH BUILDING ON ONE	The second secon	2374	3		Commence of the Commence of th	80528 Park	
CIT FROM NOTE FOR NOTE FOR NOTE FOR A PARTY. STATE OF THE PROPERTY OF THE PARTY OF	to properly the first marginal application of the particular and the first of the control of the particular part	2478	N TAFT DIVE	The second secon	CHOCK	80808	
	A STATE OF THE STA	200		1		80408	
CONTRACTOR	And the second of the control of the second) a				80537 Office	
Tender Jacob Ive	And the second control of the Andrews of the Second	0 0	- 1	1 14			
いた場合でしない。	response to provide the Contract Configuration of the Contract Con	2 14 4 10 6	- 9	The state of the s			warmerre uteratorists a versi of the 44 April 100 Co.
これがよっていていていている。	obles and the specific order and another column expension and an approximation of the specific columns of the comparations	250	- 4	The second secon	more reasonable reasonable		
ompson R2J School District	ado esperimente de la composition de la companya d	S :	2	H (The second secon
NATIONAL BANK OF THE WIRT	was about the contract of the proof of the proof of the state of the state of the planethouse of the state of	1401	- 3	ш.		2	
		1608	TOPAZ	CR.	5-7-11-1-WW. VARRETTA A / W 11-1-W	80537 Medica	9
		1615	TOPAZ	α	201	80537 Office	en en de la referencia de recentación de la companya de conferencia
X8X ENT LLO	DBAIDREAN CATCHERS DI CENTER	1624	TOPAZ	മ്		0	
DUCTAIN WEST MORTGAGE		1632	TOPAZE	æ		80537 Office	
MOUVIAIN WEST MORTGAGE		1640	TOPAZ D	Œ		80537 Office	
DUNTAIN WEST MORTGAGE		1648	TOPAZ [ŭ		537	
der Instrance & Financial	resident from the control of the second of the second second of the seco	1678	TOPAZ D	었		80537 Realty	
S Programment Most	ender der der der der der der der der der	1694	TOPAZ	<u>~</u>		80537 Office	
SAN CONSTRUCTION	MERCHANICA DE LA COMPANIONA DEL COMPANIONA DE LA COMPANIONA DELA COMPANIONA DEL COMPANIONA	1702	TAGOT	α	The second secon	5	
SNA DEGON ACTIONS FAT INC	and production of the second control of the	1714	TOPAZ	DR	BI DG2	1	
CAS DO ADON DO TOKEN BANK SAD	a desira de maria de	1716	て て な ひ し し し し し し し し し し し し し し し し し し	4	#5.50	2.	Carredon Carredon Control Cont
NA CONTRACTOR OF THE SAME AND CONTRACTOR OF THE	participated control on a community of the Company's material angular and approximate on the control of the con	7.7.7	TOBAT	a constant	3.0	12	
CALCACO NO CALCACA A CALCACACA CALCACA	edy e production of the control of the production of the productio	1717	10P47	a c	14.35	100	the second secon
	control of the Contro	.	1000	÷ (2 2 3	000000000000000000000000000000000000000	
sina Process Group inc	Appropriate to the first of the second secon	1 (4	ΛĖΙ	Σ.	01.1#	80337 Ion bea	am
ROOKY MOUNTAIN APPRAISAL OVC	energy entropings on the content of perhapsive equalitations to describe the Content of the Cont	17.4	TOPAZD	<u> </u>	10 10 10	80537 Office	and the second s
OCKY MOUNTAIN APPRAISAL SVC		1714	TOPAZ	a:	#125	80537 Office	and the second for the second second second second second

usiomer_hame	NOTE	SING	Dir Street		Cait	Zip	Activity
ETTINGER, KENNETH/GINA	FARMERS INSURANCE	1714	TOPAZ DR		#230	80537	Office
ETTINGER, KENNETH/GINA	FARMERS INSURANCE	1714	TOPA2 DR		#135		Office
TITINGER, KENNETHONA	FARMERS INSURANCE	1714	TOPAZ DR		#140	80537	Office
THILLINGER, KENNAFT/OINA	FARMERS INSURANCE	417	TOPAZ DR		#235	80537	Office
FINZER IMAGING SYSTEMS	And the second management of the second seco	1714	TOPAZ DR		#145	80537	and games and the second of th
HINA DRAGON GOURMET ENT INC	demonstrate the control of the contr	7121	TOPAZ DR		472		Focd
CHINA DRAGON GOURMET ENT INC	and a supplication of the conference and the conference of the con	1714	TOPAZ DR		#240	80538	Focd
CHINA DRAGON	AND AND THE PROPERTY OF THE PR	1714	TOPAZ DR		#105	80537	Food
CHINA DRAGON GOURMET ENT INC	A PART OF THE PART	1714	TOPAZOR		#205	80537	Foce
HINA DRAGON GOURMET ENT INC		1714	TOPAZ DR		#210		Food
HINA DRAGON		1714	TOPAZ DR		#225	80537	Focd
CHINA DRAGON	The second secon	17.4	TOPAZ DR		#220	٠.	Food
Kangaroo II Self Storage		90,	VALENCY DR			80537	Storage
argrave, Jim Ryan	Innovative Masonry Consultants	907	 !	u)			Office
URRAD OF RECLARATION	references of the control of the con	010		Ш	SHOP	7	Feceral
URBAU OF RECLAMATION	and so the company of the state	910		u		. 15.	Fecerai
URBAU OF RECLAMATION	to delicate and the second of	910	N VAN BUREN AV	Ш	MANH	Sec.	Feceral
INTERSTATE BRANDS CORPORATION		931		Ш		80537	A MANAGEMENT OF THE PROPERTY O
Zions First National Bank	and described the second of th	666		ĮĮ.	MANH	80537	
weland Lumber	Bloedom Lumber	1212	N VAN BUREN AV			80537	Lumber
GALILEE BAPTIST CHURCH		2525		ιIJ		m	Church
		477	;	₹VE		80537	
e e e en en en en en el en	(CMD CNE エンAC)	452		3 /√E		80537	FVAC
SHAFFER, JOINE A		1336	N WASHINGTON AVE	ive		80537	Office
í		1340		₹VE			Office
nity of the Light		1342		· · ·			Church
CITY SERMAN HEATED VEH PARKING		200				80537	W.Sc
TY SERMAN ADMIN SHOPS/BLD		200					Office
THOMPSON R2J SCHOOL DIST		200	N WILSON AVE		TR810		Office
TY SERMAN WHSE	and the state of t	200	•		WHSE	P	Vŕarehouse
HOMPSON VALLEY HOSP DIST	AND THE RESERVE OF THE PROPERTY OF THE PROPERT	380	:			80537	Ambulance
RST PROFESSIONAL SERVICE		985	;			80537	Office
REMOTE SWITCH SYSTEMS INC		995	N WILSON AVE			80537	
rimer County Mertal Health		1250				80537	Office
UTH EVANGELICAL OHURCH	indestrucksprokentricksprokentered gestrokenteredenstrukenter gestroken gestroken in minimizer in minimizer en	2707	•			80538	Church
NTH EVANCELICAL CHURCH	TOTAL TO THE TOTAL	2767	•		EMTR2	80938	Church
KING OF GLORY LUNERRAN CHURCH	de amende amende a de la compresa d	28.5	N WILSON AVE	The state of the s		80538:(Church
WOODWARD GOVERNOR CO	rake to be a section of the section	3800	i		SWBDA	80538	Engine controls
WOODWARD GOVERNOR CO	a diakan menangkan diakan mengangkan dan pengangkan diakan mengangkan pengangkan pengangkan pengangkan pengang	3800	N WILSON AVE		SWBDB	80538	Engine controls
OODWARD GOVERNOR CO	en de la companya de	3800	į.		SWBDC	80538	Engine controls
OODWARD GOVERNOR CO	and the second contributed of the contributed of th	3800	N WILSON AVE		SWBDD	80538	Engine controls
WOODWARD GOVERNOR CO	and a support of the control of the	3800	N WILSON AVE		SWBDE	80538	Engine controls
CODWARD GOVERNOR CO	MEDIEN KANDEN WANTE DESCRIBERATION CONTRACTOR STORT OF THE STATE OF TH	3800	1		SWBDF	80538	Engine controls
WOODWARD GOVERNOR CO	en orden en demonstration en descharation mentale accedit in contra describe describerations and describeration and contra terminal specifications and describerations and describerations and describerations and describerations and describerations are described as the describeration and describeration are describerations and describerations are describerations are describerations and describerations are describerations	3800	N VAILSON AVE		SWBDG	80538	Encine controls
くり こくこことくく くここんりつ		0000	3	many and the bolt between the same of the		,,,,,,	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -

Sustamer Name	NOTE St. Num Dir Street	Unit Zip Activity
WOODWARD GOVERNOR CO	3800 N WILSON AVE	GDHSE 30538 Landscape
VALLEY ASSEMBLY OF GOD 80537 Church	186 S WILSON AVE	80537 Church
OTY FIRE SUPPRESSION	900 S VVILSON AVE 80537 Fire	80537 Fire

SOPER
š
defined
88
Industria
efreatment.
ď.
Loveland -
ÿö X
-

	21021	EON YOU	Cir istreet	i S	di7		
TO DECORD, WAKKING L	WARRENS AUTOMOTIVE SERVICE	1351	13.1	œ Æ	80537	Service	Auto
Lug Nots, LLC		125		alleg to b.	(80537	Repair	Auto
Lug Nots, LLC		127	••••	hhired	80537	Repair	Auto
GIBSON, TIMOTHY R	Tim's Body Shop	105	W 6THST	Andrew and the second second	80537		Aufo
CITY FOWAN OLD VEH MAINT SHOP	A CONTRACTOR OF THE PROPERTY O	126	W 6TH ST	Andread of the second section of the section of the second section of the section of	80537		Auto
Whok, Teny	Wright Automotive	133	W 6THST	₹	80537		Auto
Kevin Rowley	m journey and Mariana and Marian or might be before the forest and a second of the second of the second or	133	W 6THST	CH.	80537	Service	Auto
Wyco Automotive, LLC	a de la companya antiquada de la companya de la com	413	SE STH ST	9.4-4	80537	Service	Auto
POFF'S AUTO BODY	The profits of the body with the body to the control of the body to the body t	2350		The state of the s	80537		Auto
Jaulo's Services Inc	Cars N Tres	127	SARBERRY PL		80537	Section 5.5	Auto
Davidson's Subaru	oman i della compania di sala della di pola della compania di pola della compania della compania della compania	3930	Byrd Dr	en egita legistatua in mistra e	80538	· · · · · · · ·	Auto
Ferraro's Auto Center	TO THE OWNER OF THE PROPERTY O	4340	Byrd Dr	Abbit with the best with the series of the s	80538	al arres	Auto
CO's BMW Center	And the state of t	4150	Byrd Dr		80538		Auto
Fogle Olds-GMC	King Buick Pentiac GWC	4175	Byrd Dr		80538	Service	Aufo
Expert 4WD & Auto inc	to the statement was a second of the second	245	1		80537		Auto
SERTHOUD, MICHAEL P	And the control of th	136		-	80537		Auto
ENGLE AUTOMOTIVE	TO A THE TOTAL OF	220	3	-	80537	Repair	Auto
Andringa, Brad	THE STATE OF THE PROPERTY OF T	242	S OLEVELAND AVE		80537	Service	Auto
AINSWORTH, DALE D/BARS 3		177	i		80537		Auto
Hector Gonzalez	US Auto Sales	1261	S CLEVELAND AVE	1	80537	Service	Auto
JOHNSON, ROBERT ARTHUR	MAGNUM MOTORS	241			80537	Sales	Auto
SUSHAY, STEVE	Street Rods	551	N DENVER AVE		80537	80537 Mfg	Auto
CUSTOM AUTO		1367			80537	Repair	Auto
Grease Monkey		1160				Service	Auto
mami, Mahmood	Rocky Wountain Motors	502		EMTR2	80537	Repair	Oluk
THE BRAKE SHOP		505	E BISENHOWER BLVD		80537	Service	Auto
COLLINS MUFFLER SHOP		541	i		80537	Service	Auto
MULROY AUTO CENTER, LLC		706			80537	Sales	Auto
HERITAGE FORD LINCOLN MERCURY		666			80537	Repair	Auto
HERITAGE FORD LINCOLN MERCURY		665	E EISENHOWER BLYD	SHOP POP	80537	Repair	Auto
HERITAGE FORD LINCOLNIMERCURY		. 1303			80537	Repair	Auto
OVELAND BEAR ALIGNMENT		110		Anee-	180537	Service	Auto
LADD SWITH CORP	Jiffy Lube	1544		••••	80537	Service	Auto
Aspan Wheel Alignment & Brake		2308				Service	Auto
CEHNE, JEFF D		700		- Names	80537	Repair	Auto
LOVELAND GREASE MONKEY	The second secon	2397	GARFIELD		80538	80538 Service	Auto
ADVANCED AUTO PARTS #5222	Brekes Plus	3200	N GARFIELD AVE		80538	Service	Auto
HUFFORD, HAL		3206	GARFIELD		80538	Service	Auto
PARKMOOR STORAGE LLC	од тех мария во оставите на оставителна во оставите	3210	GARFIELD	r 14 may	80538	Service	Auto
E & B AUTOMOTIVE INC		3210		##	80538	80538 Service	Auto
E & B AUTOMOTIVE INC		3210		Ω 14:	80538	80538 į Service	Aufo
JACK'S AUTO SERVICE CENTER LLC		3210	N GARFIELD AVE	₽	80538	80538 Repair	Auto
AUTOMOTIVE TRANS SERVICES INC		3210	GARFIELD	#	80538	Service	Auto
O. St. 25 . The St. 2 April		() ((C L L C C				

BY COPPLE	
is defined i	
Industrial a	•
Pretreatment	
Loveland -	
ŏ,	

Carly of Edversary - 1 representative markets	ULCX	St. Num Dir Street		7.0	Category	Activity
CONCERN INDIAN Advantage Anto Soci Inc	THE PARTY OF THE PROPERTY AND A PROPERTY OF THE PARTY OF			80538	ervice	Auto
3	manamana debaga debenara dan sana dan manamana manamana dan angkara galamban dan sana sana sana sana sana sana Sanamana dan sana dan sanamana dan sanamana manamana dan sanamana sanamana sanamana sanamana sanamana sanaman	Z	And the second s	R 30538 Sales	Sejes	Auto
DAN STREET, WILL ALL	-; (1	***************************************	20520	Solos	A 11.50
Damosso, thizabemikhison	Faicon (Turner) Wolors	2	7.E	50000	00100	0.00
THE RELLIM GROUP, INC	Meinke Mufflers	o Z	シンド	30538	Service	Auto
HUFFORD, HAL		Z.			Service	Auto
STINES, EUCENE	Honda Doctor	Z.	/E	80537	Repair	Auto
DAVES AUTO BOOK		Z.	/E EMTR2	80537	Repair	Auto
KECK AUTO & COMPANY	. A de la company de la compan	233 N LINCOLN A		60537	Sales	Auto
B & J AUTO SERVICE CENTER INC	en e	į		80537	Service	Auto
NICK DAVIDSON INC	engage pominental mental consistencial construction resembles a sociological construction of the social construction of the socia	1504 N LINCOLN A		80538	Repair	Auto
NICK DAVIDSON INC	to the state of th	2	ZE CFFIC	80538	Repair	Auto
NICK DAVIDSON INC		1604 N LINCOLN AVE			Repair	Auto
NICK DAVIDSON INC	recommendation of the commentation of the comment of the commentation of the commentat	Z	JE WAMT	α.	Repair	Auto
NOK DAVIDSON	A STATE OF THE STA	N	ZE.	80538	Service	Auto
NICK DAVIDSON INC	. On the second was a compared an interpretation of the second control of the second con	z	1	80538 F	Repair	Auto
NICK DAVIDSON INC	A CAMPANA MANAGEMENT AND A CAMPANA MANAGEMENT OF A CAM	1619 N LINCOLN A	3/	80538	Repair	Auto
NICK DAVIDSON INC	A COLUMN TO THE PROPERTY OF TH	Z	3	80538 Service	Service	Auto
SACK TO BASICS AUTO INC	MOUNTAIN VIEW MOTORS	×			Repair	Auto
Bio Horn Transmission Center Inc.	e meneral debeneral meneral meneral meneral meneral compositions of the debeneral meneral meneral meneral debeneral meneral debeneral meneral debeneral meneral debeneral debene	2400 N LINCOLN AVE		EWTR 80538 F	Repair	Auto
LOVE AND CHRYSPI YAOUTH	to be provided that the second of the control of the second of the secon	z			Sales	Auto
LOVELAND CHRYS-PLYMOUTH	A STATE OF THE STA	ļ	A Company of the Comp	80538	Repair	Auto
ALL PHASE AUTO SODY & FRAME	designation to compress the proper proper minimal control of the house designation and the compression of the control of the c	S		80537	Service	Auto
ALL PHASE AUTO BODY & FRAME	which the second control of the second of th	30		80537	Repair	dup.
Davis Merri	Wetric Wofor	co	√Ē.	80537	Repair	Auto
BLUE RISBON TOWING		S		#A 80537 8	Service	Àuto
PRO-TRANSMISSION INC	The state of the s	S	200000000000000000000000000000000000000	80537	Service	Auto
ROCKY WOUNTAIN OUICK TUBE	AND THE PROPERTY OF THE PROPER	S	∕E	80537	Service	Auto
STAN'S AUTO SERVICE	ten and a raid of the displacement with the day of the approximation of of the appro	co	3	80537	Service	Αυίο
Auto Collision Specialist of LVLD	Amended Amended for the constitution with the constitution of the	1425 S LINCOLN AVE	7F	30537 F	Repair	ลุขเจ
THE SHOP OF LOVELAND INC	make to the "district designation of the property of the prope	z	E.	80537	Service	Auto
Loveland Lube Depot				80537	Service	Auto
CUSTOM AUTO		DESA	~.	80537	Repair	Auto
COMBS, BRIAN J	Ace Transmission	W)	m	80537	Service	Auto
VEE W UNLIMITED		ψ)	4 ‡	B 80537	Service	Αυίο
SOWWAN, ROBERT G		1805 TOPAZ DR	The second secon	80537	Service	Auto
FRED'S AUTOMOTIVE, INC.			SS -41	80537	Repair	4uto
OTY SERMAN VEH MAIN			ш	80537	Govt	Auto
WARNER, ANDREW J	energy desired the energy the state of the s	187 SE 14TH ST		#A 80537	Repair	Aufo Body
SONRAY JOINT VENTURES	and the confidence of the conf	SI SI	BA	90537	₹epair	Auto Body
ROWLEYS AUTO BODY	A CAMPAGE AND	TS W 6TH ST		80537 (Repair	Зера їг	Auto Body
MORGAN BROTHER RENTALS	THE PROPERTY OF THE PROPERTY O	W 6TH			Repair	Auto Body
MORGAN BROTHER RENTALS	ender i den en de de desperadores de la companya d La companya de la companya del companya de la companya de la companya del companya de la companya del la companya de la			ELECT 80537	Repair	Auto Body
JO's Collision Repair LLC	And of the same a surface of the same of t	603 N DENVER A	'n	80537	Repair	Auto Body
JD's Collision Repair LLC		2.	3/	80537 //	Repair	Auto Body
:	CANANA TO ANA THE TAXABLE TO THE TAX					

Щ	
y COP	
sined t	
il as de	
dustria	
ent Ine	
etreatin	
5 Pr	
oveian	
可能分	
$\overline{\ddot{o}}$	

Customer Name	NO.TI		Unit Zip Catego	ory (Activity
Ozzie's Body Shop		5280 N GARFIELD AVE	80538 Repair	Auto Body
BJ'S BODY SHOP	i de de de la respectación de la companya de deservación de deservación de deservación de deservación de la companya del la companya de la companya de la c	Z	ELECT 30538 Repair	Auto Body
Smith, Stephanie/Terry	Front Range Auto Detailing	2359 W 8TH ST	80537	
At Time & Tine of Colorado		2	\$0538 Service	Auto Detail
Carquest		î.	80538 Sales	
McBroome, Scott	US Performance		#C 80537 Sales	
Wash-Me carwash		121		
TB Holdings	Muddy's Truck & Auto Wash		80538	Carvash
Mtn Weve Carwash			80537	ĺ
ENTERPRISE RENT A CAR		1117 E EISENHOWER BLVD	EWMT3	1
SCHRADER OL CO)
TEXACO STATION		**	60537	ί
Tang, Khuong		⋛	WWTR1 30537	
Tang, Khuong	LOVELAND GETTY	<u> </u>	WWTR2 80537	
JONES, DAVID	AND	2106 W EISENHOWER BLVD		Carwash
DIAMOND SHAMROOK	терия дей дей, акторого до подержание пределения выпадавания и подержание дей выпадавания поделения выпадавания выпадавания в поделения выпадавания выпадавания в поделения в	×	80537	
WASH MASTERS	THE PARTY OF THE P	λ	80537 Service	Sarvash
204 VENTURES LLC	e companyor in the store of the second to th	2		
PREFERRED AUTO DETAIL INC		Z	#E 80538 Service	Canvash
DIAMOND SHAMROCK		3675 N GARFIELD AVE	80538	
DIAMOND SHAMROOK	The first transfer of the first transfer of the second second second second second second second second second	22	CWASH 80538 Service	
NOOR (LC	Conoco Carvash	z	30538 Service	
WASH MASTERS	te a fis delete i desent i 1100/20. Visidata equalidad planta que d'a pos desente parte parte del delete del tenen es especial especial del conserva especial especial del conserva especial		80538	
WASH MASTERS	A BOOK AND A STATE OF THE STATE	×	ELEC2 80538 Service	
ALL PHASE AUTO BODY & FRAME	eer with the day, is to the total about the property of the sense effectives are an extensive and extensive account of the sense effectives and the sense effectives are sense effectives and the sense effectives and the sense effectives are sense effectives.	co	EWTR3 80537 Service	
WASH MASTERS		- 7		Canvash
PHAGURA, SUKHDEV S		တ	80537 Service	1
DIAMOND SHAMROCK #698	e system system of strandards related by the authorize mathematics of the Police of the School of th	}		
WASH HOLD CAR WASH			80537 Service	1
TROUTING OF CAR WANT IN		The William of Court of the Cou	80538 Service	
ころより、アカートでしたのでは、ことのできません。		2985 N TAFT AVE		
VALKER, DWAYNE	. 200 200 200 200 200 200 200 200 200 200	7)	80537	
WALKER, DWAAYNE	MAGE CAR WASH (BIGG 2)	W.		1
ACCEPTION OCCU	A RESERVED TO MENT OF THE PROPERTY AND ADMINISTRATION OF THE PROPERTY OF THE P	2	80537	-
City Pub Works/Streets		Z	SJBTR 80537 Govt	Carvash
CITY SERVIN VEH WASH		z	WBAY3 80537 Gov	Canvash
WOLF ELECTRONIX	The state of the s	NS.		Oircuit boards
COLUMBINE CLEANERS	te a de la Completa de de la completa del la completa de la completa de la completa de la completa de la completa del a completa della della completa	2241 W EISENHOWER BLVD		
Justin Cran	Cycle Cenfral	z	,	
Justin Cran	Cycle Central	X	#A 80538 Service	
ROCKY MOUNTAIN MOTORSPORTS	and the side of th	Z	80538 Sales	Oycles
COMFORT DENTAL		1405 SW 10TH ST	80537 Service	
NEXT OF THE PROPERTY OF THE PR		w	80537	Dental
SOURCE OF ROKERS		100 Eloc 25 - 9901 -	#1 80538 Service	

Customer Name	A D O N	St_Num		Cart	Zip Cate	~.	Activity
VRIGHT, DAVID W	and described formation or other properties of the contract of	2304	3.	ج 40	780538 Serv		Dental
SATHRE, RICHARD A DR	and of the professional and a service of the contract of the c	2004	₩ 15TH ST	# C#	80538 Service		Dental
JEWETH, OLIFFORD	James K Richards, DDS	1347	,		180538 Service	•	Dentai
AODUSKI, TED E JR DDS	Implant Demstry of N Colo	1414	W 28TH ST		80538 Service		Dentaí
MIODUSKI, TED E JR DOS		7 7 7	W 28TH ST	₩ #	80538 Service		Dentai
AIODUSKI, TEO E JR DDS		1414	W Z8TH ST	£3	80538 Service		Dentai
TECHNICRAFI DEVIALARIS		3440	W 2974 ST	် လူ (၁၈)			Dentai
OVELAND DENTAL CENTER	Monarch Dental Associates	1440	W 29TH ST	#400	80538 Service		Dental
PETERSON JOHN W (EFT)	Ron Harden, DDS	144 0	W 29TH ST	009#	80538 Service		Dentai
Hargrave Enterprises, LLC	Creation Dental Laboratory	241	To III	#2	80537 Service		Dentai
BRUNER, LARRY DR	the many that we have been accounted to the second of the	2502	ABARR DR		80538 Service		Dentai
Stower's Orthodontics	transaction for district hands in wave as an aprily of party and the stress was not transaction and the first of the district	2520	ABARR DR		80538 Service		Dental
LACY, EDWARD J.R.	A CANADA IN THE STATE OF THE ST	2550	ABARK DR		80538 Service	,	Dentaí
HOWARD ANDREW P DDS	and the second resolution of the second of the second seco	2541	ABARR DR		80538 Service		Dentai
DILDINE JOHN	we begin to display to the first the first of the first o	2354	ABARR DR		80538 Service		Dental
Peak to Peak Peroconfics/Implant	R Todd Singiser, CDS	2580	ABARR DR		80538 Service	1	Dental
FRANCKUM JAMES		2903	ASPEN DR	9#	80538 Service	i	Dental
STACEY, ROBERT L	des harmanes and management of the control of the c	1930	BLUE MESA CT		80538 Service		Dental
HARRISON, RICHARD C	to design the result is a general contraction of the contraction of th	2008	BLUE MESA CT		80538 Service		Dental
TARTAGLA LOUIS JR DR	A CANAL AND A CANA	1708			80538 Service		Dentai
NORDSTROM, DAVID W (DDS)	and supported as places of secretaring as entertheoretic and contraders and operation of the contraders.	1307	N BOISE AVE	## 140	(80538 Service		Dentai
Drane, Merk D. & Wollean John J. DDS	and and a superior of the supe	1331	N BOISE AVE	2#	80538 Service		Dentai
	LOVELAND FAMILY DENTISTRY	1242	N CLEVELAND AVE				Dental
Holling George DDS MS LLC	1	640	E EISENHOWER BLVD	#¥			Dentai
PITT DAVID G DDS		1524	W EISENHOWER BLVD	14: 111	80537 Service		Dental
PITT DAVID G DDS		1524	W ESENHOWER BLYD	윺			Dentai
PERFECT TEETH		3400	W EISENHOWER BLVD		180537 Service	,	Dentai
SHERICK PAUL MIDDS.MS		2964	GINNALA DR			1	Dental
ORAL & FACIAL SURGERY OF LYLD		2882	GINNALA DR		180538 Service		Dental
Endedontic Association		2395	GINNALA DR	#101	80538 Service	1	Dental
WCKEE FAMILY DENTISTRY		2398	GINNALA OR	#101	80538 Service	1	Dentai
BRANCA, RICHARD W, DDS	Endodontic Associat N Colo	2398	GINNALA DR	#102	80536 Sen	1	Dental
GALBREATH, JACK	Schreiber William, DDS	1323	HARLOWIN		80537 Service	1	Dental
Joshua Wyte DDS		935	M LINCOLN AVE		80837 Service	:	Dental
WARD CONSTRUCTION	Carter David, Oligmueller James, DDS 777	2314			80538 Seri	- :	Dentzi
PEDODONTICS OF LOVELAND	Flossm Dental Hygiene?	2700	MADISON SQUARE DR	#182	80537 Service		Dental
GERKEN, LOUS		2800	MADISON SQUARE DR	7#	80538 Service		Oental
JDS.PC	The second secon	2800	MADISON SQUARE DR	#5	80538 Service		Dentaí
PEARSON, RANDALL C		2889	N MONROE AVE		80538 Service		Dental
Hood Steven J. DMD	A management of the second of	3013		₹ 30	80538 Service		Dentai
or M Jimison DDS, PC	And a proposed transfer over the control of the con	3013	N TAFT AVE	#2	80538 Service		Dental
Lori M Jimison ODS, PC	THE REPORT OF THE PROPERTY ADMINISTRATION OF THE PROPERTY OF T	3013	1	#28			Dentai
MASTER CRAFT DENTAL LAB		1556	TOPAZ DR		80537 Service		Dental
	the control of the co	7336	TOPAY DR		205537 Common		Donto


y CDPHE
,C }
celined
ŝ
=
ĭ
3
\mathbf{z}
-=
imeni
03
ő
O.
٠
Š
ñ
Ü
ő
.,,}
۲ő.
>.

The state of the s		בוואי זא	Dir Street	กาแ	dI7	Category	
<u>α</u> .	FRAME CORKS CONTAL LAB	1570	TOPAZ DR		80537		
		301	N LINCOLN AVE		80537		Dry cleaning
VANS CLEANERS	and the control of th	702	N LINCOLN AVE		180517	Sporto	Dor Chapting
TORYNIA INTERPORTER NO	Grand Rental Station	3404	しておないし		80537	20000	Simportal Current
the standard and antique device in the last standard of the last standar	A Pri vi i tri mai e e e e e e e e e e e e e e e e e e e	1440	מסוסם אינעו		00000		3 2 3 3 5
Discould Freedray Leaven of		244C			; "		- unera:
Service of the property of the	er en men demokratien en 1904 dan heid stelle de propriet beginne großen der tradstrag et defenten mengen.	7102	N LINCOLN AVE	WAILK			Funerai
ALLWOIL FUNEXAL HOME		2100	i			Service	Funeral
MCKEE MEDICAL CENTER		2000		OFFIC			Hosp (e)
DYNAMIC MOLDING		1106	N BOISE AVE			Mfq	ini mold (plastic)
LOVELAND'S CENTRAL LAUNDROMAT		265	į		80538	Service	
LOVELAND'S CENTRAL LAUNDROMAT		268	1		80538		Laundiv
LOVELAND STEAM LAUNDRY		403	E 4THST		80537		Sindry .
LV. D STEAM LAUNDRY	and the first of t	6.4	7		80537	פטוינופט	ייוסקויים [
i	and the second of the second o	2589	W PISFNHOWFR RIVD	American commence of the comme	180837	80537 Service	אויושלייא
Anead Start Inc	Jefferson Street Leadings	540			いっという	Conico	2 acroding
A the contract of the contract		(518	N MADISON AVE	#44 #4	30533	Section	i winder
SURVE OLITANERS, ICO	ation of defending the second	1595	N TAFT AVE		20528	Sections	anador
Grey Star Construction	and the profession will be the property with a purposer, and constitutionally with the constitution of the professional and and a second constitution of the professional and a second constitution of the second constitution o	550	N JEFFERSON AVE	a), Mi	(80537		i sundin/
THOMPSON VALLEY AUTO & MACHINE	endinendade grant into the state of the stat	.0.	F 380.8T		80537	80537 Service	Machining
KIMBLE PRECISION, INC	A STATE OF THE PARTY OF THE PAR	418	í	I T	ととないな	Mfr	Machinis
S & MANUFACTURING	A GOOD TO SEE THE THE THE THE THE THE THE THE THE T	505	N C C C C C C C C C C C C C C C C C C C		30000	2162	Machining
THE COLUMN TWO IS NOT THE OWNER OF THE OWNER OWNER OF THE OWNER	House Precision Machining	2330			0000	8000	Transfer of the second
CHARITOR	der dem de	1205	***		2 C C C C C C C C C C C C C C C C C C C	200327 NAFA	*10C 111 12 C
	er ermen endersteller ermen en eget engem ermenen ermen ermen en en ermen en en ermen ermen ermen er	000	A RONDON AVE		10000	Si Si	WIGO III III E
1811 1255 TO TO SE 181		0011		101	70000	ر د د	waching
	The Control of the Co	50		n TEM T	80537 P/Itg	Mig	ฟลตากเกต
LVLD (Wedica) chiefprises LLV.		2555	,			Service	Medical
VLD Medical Enterprises LLC		2555		EMTR2		Service	Medical
Kirk Holdings, LLC		3550			80538	Service	Medical
EE & LEE DRS		2004	ì	#5	80538	Service	Medical
GROUP, PC		1527	E 18TH ST		80538	80538 Service	Medical
~ i	Plant Services	1538	ģ 🔭 -	-	80538	Service	Medical
		1703	ļ.°	44 C) (44	80538	Service	Medical
		1703	ļ.	#4-5	80538	Service	Wedical
		1805		6-9#	80538	80538 Service	Medical
MOKEE MEDICAL CENTER	THE RESERVE OF THE PARTY OF THE	1825	1	-	80538	Service	Medical
MCKEE VEDICAL CENTER	AND THE PROPERTY OF THE PROPER	1825	1.	EMTR2	·;····	Service	Medical
XOXIIII XIID		270	29TH		80538	Service	Medical
		272	29TH		60538	Service	Medical
		274	29TH		80538	Service	Medical
MOKEE WED CNTR OCCU MED PRO		276	1 1		80538	Service	Medical
MOKER VEDICAL OFINITION		278	29TH		80538	Service	Medical
ACKAN SAD		282	E 29TH ST		80538	Service	Wedical
MCKEE WED CNTR WORKCARE CLINIC.	مساوعها والمحافظ والمارات والمقاولا وإنجارات والحوافظ والموافظة المؤاملة والمعاملة والمواولة والموافقة والموافقة	284	E 28TH ST		30538	Service	Medical
SOMED VIDE ONTRINOPROARD OF INDI-		238	MIDC.		00100		


Customer_Name	NOTE	St. Num	h.	Š	Zip Category	ory (Activity
ALLEN, THOMAS J MD		582	- ;		SUDJS SERVIC	1
MENTENNIAL MEDICAL DUNC		232	W (4TH ST		80537 Service	Medical
BIG THOMPSON MEDICAL GROUP, PC		914	1.		80537 Service	
ALLEN THOMAS J MD	de de la compressión	1475	:		80538 Service	
BIG THOMPSON MEDICAL GROUP PC	A CONTRACTOR OF THE CONTRACTOR	1798	3		80538 Servic	Medical
BIG THOMBSON MEDICAL GROUP BC		5081	1		80538 Service	
	the state of the s	1907	N BOISE AVE	1	30538 Service	Medical
ANDERSEN DENNIS LOR	n Sada sada sada sada sada sada saga saga s	1907	1		80538 Servic	
-	ten de ten de	1907	ſ		80538 Service	% edica!
BRUNS, THOMAS DR		1907	N BOISE AVE		80538 Service	 Medicai
SOKEE WEDIOAL CENTER	nder stemmenstelle bestehn som state i syndry tyske helde stemmen bestek de bestek bestek i state stem state s Bestek stemmenstelle bestek stemmen stemmen stemmen bestek stemmen stemmen stemmen stemmen stemmen stemmen stem	1907	N BOISE AVE	(C)	80538 Servic	 Medical
Crill, Joshua James	A COLUMN TO THE PROPERTY OF TH	1931	}		80538 Service	Medicel
NO CO ALLERGY/ASTHMA CLIN	The state of the s	1931	N BOISE AVE	4 4	80538 Service	 Medicai
Aff. Johsua James	LOVELAND YOUTH OLINIC	1931			80538 Service	e Medical
CKEE NEDICAL CENTER	į	2000	į.		80538 Service	e Medica!
MCKEE WEDICAL CENTER	AND THE TOTAL OF THE PROPERTY	2000	N BOISE AVE	MSTR	80538 Service	e Medicai
ACKEE WEDICAL CENTER	e adapta para grapa unde de departamenta de la varia de la varia de la varia dos composos de la variada de la defenda de la defe	2000	;		80538 Service	e Medical
Loveland Youth Clinic		2021	N BOISE AVE		80538 Service	Medical
ACKEE WEDICAL CENTER	Andrew Comment of the	2050			80538 - Service	Medical
ACKEE MEDICAL CENTER	Annah (Annah (An	320			80537 Service	e Medical
ACKER WEDICAL CENTER	er er park i den krommendelsen er de ek amerikanske met stadisten i krommen den men en en en en en en en en en	430	:	-	80537 Service	}
MOKEE WEDICAL CENTER	Application of the second seco	440	N OLEVELAND AVE		30537 Service	e Medical
ACKEE MEDICAL CENTER	The second of th	442	N CLEVELAND AVE		80537 Service	e Medical
ACKEE MEDICAL CENTER	e de la companya del la companya de la companya de	444			80537 Service	e Medical
OVELAND DERMATOLOGY CLINIC	The state of the s	776	W EISENHOWER BLYD		80537 Service	e Medical
770-790 W EISENHOWER LLC	n or namenga manda bandan bandan bandan bandan bandan maka sant a mpor cet a mandan bandan bandan banda a ceta Bandan bandan bandan bandan bandan bandan bandan bandan maka sant a mpor ceta a mandan bandan bandan bandan ba	190	W EISENHOWER BLVD		80537 Service	e Medical
TOVELAND DERMATOLOGY CLINIC	m and it was a few contract of the contract of	061	V/ EISENHOWER BL/D		80537 Service	e Medical
Noscma Audiology	A PROPERTY OF THE PROPERTY OF	2902	GINNALA DR		30538 Servic	s Medicai
CEOL JENNERS	The second secon	2908	GINNALA DR		80538 Service	a Medical
Osius. Dr Timo:hy/Eizabeth	A CANADA NA MANANA NA MANA	2980	GINNALA DR	******	30538 Service	e Medical
LOVELAND SURGERY CENTER	Sundance Medical Plaza	3800	N GRANT AVE		80538 Service	Medical
BECKER PROPERTIES	Or, Schutte & Or, Knutson	3850	GRANT AVE	\$100	80538 Service	e Medical
ACKEE MEDICAL CENTER 2251	The state of the s	008	JOSEPHINE CT	#4	30537 Service	e Medical
DER OSHON, TOBY		2700	MADISON SOUARE DR	es/11/e	80538 Service	٠ :
UP.PC		2701	MADISON SQUARE DR		80538 Service	e Medical
A SECULAR SECU	LOVELAND PEDIATRICS	2802	MADISON SOUARE DR		80538 Service	
	LOVELAND PEDIATRICS	2802	MADISON SQUARE DR	~~ ¥1;	30538 Service	e Medical
Roberts, Everrette/Conv	LOVELAND PEDIATRICS	2802	MADISON SQUARE DR	#3	S0538 Service	
	designations of the control of the c	307	S CLEVELAND AVE		80537 Mfg	Metal Finisher
SUPER VACUUM MFG CO	Control of the first of the second confidence of the second second of the second secon	(305)	= 11TH ST	EMTR	80537 Mfg	Metal Finisher
WOODWARD SOVERNOR CO	and a state of the	3800			90538 M/G	Metal Finisher
DYNAMIC MOLDING		4.08		¥#	80537 Mfg	Plastic Moding
QUEBECOR PRINTING LOVELAND INC	en dangen kana naderikanya, mpekalan untukan menamanakanansa amilahan dan sebisara dan itaha makanisi.	380		WATER	80538 Mig	Printing
	the control of the second control of the second control of the second of	the party and the springers are seen to be a second to the	The property of the party of th			

Customer_Name		St_Num Dir Street	Unit Zip Category	< Activity
Graphics Partners Inc		855 W 8TH ST	80537 Mg	7 Mfg Printing
Light-Speed Color L.C	namen normanistis ora normanistis de su generalizares, emplemente emblementanda de mais estados de anos estados	225 S MADISON AVE	80537 Service	Printing
WEST-TEC PRESS		1853 N CHEYENNE AVE	60538 M/g	School
	MINCTEMAN PRESS	<u>.</u>	ELECT 80537 Service	Printing
HEE, BRUCE B	MINUTEMAN PRESS	12		Printing
R Lanning Machine Services		1260 S GRANT AVE	.80537 Repair	Srinting
Terra Soft Soutions		z	.02B 80537 Sales	Printing
GROUP PUBLISHING, INC		1515 CASCADE AVE	80538 Mfg	Publishing
a.	Ì	2303 W 871-ST	MANH 80537 Mfg	Quartz Resonators
GREAT WESTERN RAILWAY	(Omin Trax)	: :2% :	MH8TH 80537 Mg	Refurbish Locomo
SOYULAKE STATE PARK		z	80538 Govt	JV Park
Mountain Vista Rv		1550 E EISENHOWER BLVD	80537 Service	₹V Park
Loveland Essential Group, LLC	LOVELAND RV VILLAGE	442 EISENHOWER BLVD	80537 Service	RV Park
OUALITY MACHINE INC		951 N DES MOINES AVE	80537 Ma	Tool & Die

Attachment C




Attachment D



Attachment E

Ş.



SECTION IV - RECEIVING WATER INFORMATION

18. Is analytical data required to be submitted?

No analytical data is required to be submitted. However, the Big Thompson Watershed Forum (BTWF) and the USGS have been implementing a monitoring program along the Big Thompson River. This program includes a monitoring station upstream of the City of Loveland Wastewater Treatment Facility. The results of the upstream monitoring can be found on the attached CD. The CD includes data from the BTWF website and from the USGS website. The period of record for the data is approximately from 2001 through 2006 for the BTWF data and 2000 through 2005 for the USGS data. Because the BTWF and the USGS work in conjunction with this monitoring, there may be duplicate data between the two databases. The following table summarizes what parameters are included in each database.

Upstream Water Quality Parameters

BTWF Database	USGS Database
Alkalinity	Alkalinity
Hardness	Hardness
Carbonate as CO ₃	Carbonate
Bicarbonate as HCO ₃	Bicarbonate
Dissolved ammonia	Dissolved ammonia
Total ammonia plus organic nitrogen	Dissolved nitrite
Nitrite plus nitrate	Total ammonia plus organic nitrogen
Dissolved oxygen	Nitrite plus nitrate
Total phosphorus	Dissolved oxygen
Dissolved phosphorus	Total phosphorus
Orthophosphate	Dissolved phosphorus
Total organic carbon	Orthophosphate
Н	Total organic carbon
Calcium	рH
Magnesium	Calcium
Sodium	Magnesium
Potassium	Sodium
Chloride	Potassium
Sulfate	Chloride
Specific Conductance	Sulfate
Temperature	Fluoride
Turbidity	Silica

BTWF Database	USGS Database
TDS	Specific Conductance
	Temperature
<u>Metals</u>	Turbidity
Arsenic, dissolved	
Copper, dissolved	<u>Metals</u>
Iron, dissolved	Aluminum, dissolved
Lead, dissolved	Arsenic, dissolved
Manganese, dissolved	Cadmium, dissolved
Mercury, dissolved	Cadmium, total
Nickel, dissolved	Chromium, dissolved
Selenium, dissolved	Chromium, total recoverable
Silver, dissolved	Copper, dissolved
	Copper, total recoverable
Organic Compounds	Iron, dissolved
Benzene	Iron, total recoverable
Ethylbenzene	Lead, dissolved
Toluene	Lead, total recoverable
Xylene	Manganese, dissolved
	Manganese, total recoverable
<u>Biological</u>	Mercury, dissolved
E. coli	Mercury, total recoverable
Total Coliform	Nickel, dissolved
	Selenium, dissolved
	Silver, dissolved
	Silver, total recoverable
	Zinc, dissolved
	Organic Compounds
	Benzene
	Ethylbenzene
	Toluene
	Xylene

EVALUATION OF TREATMENT FACILITY

FACILITY NAME: City of Loveland WWTF CDPS: CO-0026701

UNIT PROCESS	UNIT PROCESS FEATURES/DESCRIPTION	CAPACITY HYDRAULIC/ ORGANIC
Preliminary Treatment	Channel Monster Grinder and Auger w/ 5/16-Inch dia, openings Channel Width - 4 feet Channel Depth - 5.83 feet	20.7 MGD
	Acrated grit basin – 1 unit Volume = 27,500 gat Ociention Time = 2,29 min at Peak Flow (17,3 MGD) Grit Concentrator = 1 cyclone unit Grit Washing = 1 classifier unit	15.8 MGD
Influent Flow Measuring	2-foot Parshall Flume, ultrasonic sensor/recorder	0 – 2024 MGD
Primary Treatment Facilities	2 Primary Clarifiers 78 foot diameter Volume = 0.39 MG each Detention Time = 1.1 hrs. at Peak Flow (17.3 MGD) SWD = 11 ft Surface Area = 4.778 sq. ft. each Overflow Rate = 1.798 gpd/sq. ft. at Peak Flow (17.3 MGD) Weir Loading Rate = 20.230 gpd/Lft at Peak Flow (17.3 MGD)	12.0 MGD, max month 27,800 lbs. BOD ₅ /day
Secondary Treatment	Activated Sludge Process - Step Acration 6 Cells @ 0.47 MG each Total Volume = 0.83 MG Detention Time = 3.9 hrs. @ 17.3 MGD Organic Loading = 54 lbs/1000 cu. ft/d. Horsepower = 900 HP (Blowers w/ fine bubble diffusers) Firm Capacity = 10.200 scfm	10,9 MGD, max month 20,236 lbs. BOD₅/day
	3 Secondary Clarifiers Diameter = 90 feet Volume = 0.76 MG each Detention Time = 2.1 hrs. at Peak Flow (17.3 MGD) SWD = 16 ft Surface Area = 6.362 sq. ft. each Overflow Rate = 1.360 gpd/sq. ft at Peak Flow (17.3 MGD) Weir Loading Rate = 20.300 gpd/Lft at Peak Flow (17.3 MGD)	10.9 MGD max month 20.236 lbs. BOD ₅ /day

EVALUATION OF TREATMENT FACILITY

FACILITY NAME: City of Loveland WWTF

CDPS: <u>CO-0026701</u>

Disinfection

Ultraviolet Light Disinfection - Low-pressure, high-output type

20.7 MGD (Peak Flow)

two parafal disinfection channels

Volume = 1,396 gallons

Length/Width Ratio = XXX (Approximation)
Detention Time = 6.9 sec. @ Peak Flow

Dose 30 indisquir

UV Transmittance 254 nm: 65 %/cm

Effluent Flow Measuring Dual 32-inch magnetic flow motors sensor/recorder

2 - 20.7 MGD

City of Loveland - Design of Wastewater Secondary Clarifier and Digester Renovations (Project W434HG)

Process Analysis

PREPARED FOR:

City of Loveland

PREPARED BY:

Anne Childs/CH2M HILL

DATE:

April 22, 2005 (revised June 3, 2005)

Purpose and Background

This technical memorandum (TM) describes the results of a detailed process analysis of proposed liquid stream modifications to the existing Loveland Wastewater Treatment Plant (WWTP), defined as Project I in the Wastewater Reclamation Site Feasibility/Incremental Expansion Study (1999 Study). Proposed modifications to the secondary treatment system include the addition of a third clarifier, associated return activated sludge (RAS) and secondary scum (SSM) pump stations, and a new clarifier influent flow splitting structure.

The City of Loveland recently completed a significant modification to the secondary treatment process at the Loveland WWTP. These projects are defined as Projects A3 and B (Step Feed Aeration and UV Disinfection), and are described in the 1999 Study. A previous process analysis was completed as part of those projects and is documented in the technical memorandum "City of Loveland Wastewater Treatment Plant Project A3 – Step Feed Aeration Conceptual Design" dated November 27, 2002 (2002 Process Analysis).

The current analysis builds on the 2002 Process Analysis. In particular, the computer model of the plant that was previously developed using CH2M HILL's Professional Process Design System (Pro2D) process model was updated to reflect the recently completed step-feed activated sludge configuration. At the time the 2002 Process Analysis was completed, the design of modifications to the secondary treatment system was not complete. In addition, certain modifications to the design were made during the construction phase. These modifications have been incorporated into the plant model under the current study to provide an accurate representation of the plant's current secondary process facilities.

Recent Step-Feed Project Background

The recently completed Project A3, Step-Feed Aeration, consisted of improvements to the activated sludge, diffused air aeration, and RAS pumping facilities. Improvements included the addition of two new aeration basins and modifications to the existing basins, with a resulting configuration that provides step-feed treatment configured as two trains of three consecutive basins; addition of anoxic zones at the head of each basin to provide partial denitrification; replacement of existing with new secondary aeration fine-bubble diffusers and blower system; and replacement of the existing RAS pumping units. In addition, it was determined that the existing trickling filters were no longer necessary due to the expanded

DEN/PROCESS TM FINAL DOC

aeration basin capacity, and they were removed from service on December 9, 2004, to help with odor control issues at the WWTP.

The primary function of step-feed operation is to allow higher influent loadings than with a conventional complete mixed operation, while limiting solids loadings to the secondary clarifiers. This is accomplished by feeding all of the return activated sludge (RAS) to the first upstream zone, while feeding the influent in a step-wise manner, split among the three aeration zones. As a result, the two upstream aeration zones are operated at higher mixed liquor suspended solids (MLSS) concentrations, while the last downstream zone, which determines the clarifier loadings, is operated at the same MLSS concentration as with a conventional activated sludge system. The higher upstream MLSS concentrations provide a greater total sludge inventory, which in turn can accommodate higher loadings and/or allow operation at a higher sludge age, or SRT. As a result, nitrification, which requires a certain minimum SRT, can still be accomplished even with higher influent loadings.

Construction of the two new basins and modifications to two of the existing basins were completed in July of 2004. The WWTP step-feed process was put on-line on July 20, and initially consisted of one train in a modified configuration. The configuration consisted of two basins in series followed by a third group in which mixed liquor and primary effluent flow was split to two basins as shown in Figure 1:




FIGURE 1
Modified Step-Feed Process During Construction of the WWTP Improvements

In September 2004, modifications to the remaining two basins were complete and the basins were put on line to provide two trains of three basins in series as shown in Figure 2:




FIGURE 2
Final Step-Feed Process for the Loveland WWTP

Table 1 presents the summary of plant performance for the years 2003 and 2004. The average influent flows in million gallons per day (mgd) and the influent and effluent concentrations in milligrams per liter (mg/L) for biochemical oxygen demand (BOD), total suspended solids (TSS), and ammonia (NH3) were obtained by averaging the daily effluent parameters included in the "DLYPAR" files provided by the City. These files are presented in Appendix A. Note that throughout this TM, the acronym "BOD" is synonymous with "5-day BOD", or "BOD5".

TABLE 1 Summary of Plant Performance for 2003 and 2004

Average		Average In	ıfluent Paran	neter, mg/L	Average E	ffluent Paran	neter, mg/L
Month	Flow, mgd	BOD	TSS	NH3	BOD	TSS	NH3
January 2003	4.9	327	329	25.3	40.6	20.12	6.37
February 2003	8.6	307	274	26.3	24.2	13.25	9.45
March 2003	5.4	272	239	24.3	77.3	62.30	6.32
April 2003	5.5	265	277	21.6	20.2	6.66	4.28
May 2003	6.2	262	273	17,8	14.6	4.87	3.32
June 2003	6.8	230	237	18.3	10.2	5.50	0.29
July 2003	6.8	208	220	16.3	11.6	8.54	0.13
August 2003	6.4	245	269	16.9	7.7	5.56	0.10
September 2003	6.3	264	260	17.7	8.4	7.17	0.10
October 2003	5.4	280	273	22.7	10.4	9.49	0.13
November 2003	5.1	317	283	25.5	11.2	6.85	0.30
December 2003	5.0	332	273	27.3	18.6	8.79	2.68

TABLE 1
Summary of Plant Performance for 2003 and 2004

	Average	Average In	fluent Paran	neter, mg/L	Average E	age Effluent Parameter, m	
Month	Flow, mgd	BOD	TSS	NH3	BOD	TSS	NH3
January 2004	4.9	334	253	28.2	24.0	10.16	7.90
February 2004	8.6	328	262	28.7	24.6	11.56	2.66
March 2004	4.8	300	260	28.7	17.5	6.74	4.62
April 2004	4.7	328	273	31.0	24.6	6.09	8.68
May 2004	5.1	283	239	27.5	16.8	5.86	3.17
June 2004	6.1	261	229	21.8	9.2	4.76	0.40
July 2004 ⁽¹⁾	6.8	231	294	17.9	5.9	6.42	0.34
August 2004	6.8	226	228	17.8	3.4	4.79	0.12
September 2004 ⁽²⁾	6.4	208	229	18.6	5.1	5.74	80.0
October 2004	6.4	219	223	19.8	4.6	6.42	0.06
November 2004	5.6	255	245	25.1	6.2	7.27	0.05
December 2004	5.6	270	233	26.9	5.3	5.27	0.11

^{(1) 4} basin step-feed on-line 07/20/04

If the average effluent parameters for the corresponding months in each of the two years are examined in Table 1, it appears that the step-feed process has resulted in an approximate one-half decrease in monthly average effluent BOD concentrations. More importantly, a significant decrease in effluent ammonia concentrations was observed during the colder winter months. This is because the step-feed process allowed operation at a higher SRT than was possible with the previous conventional activated sludge system, as limited by clarifier loadings. Although the City runs a lower MLSS than was previously run to the secondary clarifiers, the average MLSS concentration is higher in the overall process due to the MLSS gradient across the basin. This gradient is experienced because the concentrated RAS is returned to the first basin in each aeration train and is subsequently diluted in each basin by the incoming primary effluent, until it reaches its minimum value in the last basin. The higher average MLSS concentration corresponds to a longer overall SRT.

Process Model Development

The model of the CITY's WWTP unit processes developed for the 2002 Process Analysis was updated using CH2M HILL's Pro2D modeling tool. The modeling effort for the 2002 Process Analysis included an analysis of the existing treatment facilities and wastewater flow and loading characteristics and operating parameters. The model was used to estimate the fate of key wastewater constituents such as BOD, ammonia, and nitrate through each unit process at the WWTP, and to develop a solids balance through the existing plant for the proposed Project A3 improvements. This model has been updated for the current study to

4

^{(2) 6} basin step-feed on-line 09/07/04

include the changes made to the existing facilities as a result of the construction of the Project A3 improvements as well as the addition of the secondary clarifier facilities proposed under the Project I improvements.

Model Revisions

Revisions to the Pro2D model developed for the 2002 Process Analysis included both physical and operational changes as follows:

- Removal of the trickling filters, which were taken out of service on December 9, 2004.
- Adjustment of the sizes of the individual aeration basins to account for changes made during construction.
- Addition of a third secondary clarifier equal in size to the existing clarifiers.
- Adjustment of the basic process parameters in accordance with the model calibration described in subsequent paragraphs.
- A decrease in the expected primary concentrations based on the plant performance data from 2003 and 2004. The average primary sludge concentration over the last two years is approximately 3 percent. This is 0.5 percent lower than observed during our original analysis.
- A decrease in the expected WAS thickening capture rate based on the plant performance data from 2004.

Model Calibration

The observed effluent parameters presented previously were somewhat better than those predicted by the Pro2D modeling efforts in the 2002 Process Analysis. As such, efforts were made to recalibrate the model for the constructed step-feed facilities based on reported data provided by the plant operators from the following representative operating periods:

- September 20-26, 2004
- October 9-15, 2004
- November 22-28, 2004
- December 23-29, 2004 (w/o trickling filters)

To calibrate the model, the average influent and operating conditions for each period were entered into the model, including flows and loads, and the operating dissolved oxygen (DO) level, solids retention time (SRT), and return sludge flow. All parameters were obtained from data taken from the "DLYPAR" or "DLYAS" files.

Data used to calculate SRT, in days, was obtained from the "DLYAS" files, and included the aerobic aeration basin volume and mixed liquor suspended solids (MLSS); WAS flow and solids concentration; effluent flow and TSS. Daily SRT was calculated based on the following equation:

SRT, days =
$$\frac{V * X}{(Q_w * X_v + Q_e * X_e)}$$

where:

V = Aerobic aeration basin volume, million gallons (MG)

X = Aeration basin MLSS concentration, mg/L

 $Q_w = WAS$ flow, mgd

 $X_r = WAS$ solids concentration, mg/L

Qe = Effluent flow, mgd

 $X_e = Effluent TSS, mg/L$

Basic process parameters in the model were adjusted within ranges acceptable in the industry until a close approximation to the observed effluent ammonia levels, MLSS concentration, and air flow for the specific period was achieved. These process parameters were then averaged for all of the periods analyzed to establish the parameter values for the calibrated model. Using the calibrated model, the operating characteristics for the four periods were input to confirm that the model reasonably predicted the observed performance. The model calibration results are presented in Appendix B.

Secondary Treatment Process Capacity Evaluation

The calibrated model was used to evaluate capacity and performance capabilities of the proposed secondary treatment unit processes at the Loveland WWTP with respect to the City's current Colorado Discharge Permit System (CDPS) permit for the plant. Year-round nitrification is necessary to achieve compliance with the permitted whole effluent toxicity (WET) limits and to reliably meet the numeric limits for ammonia listed in the discharge permit. The WET limit in the current CDPS permit for discharge into the Big Thompson River is: No lethality at an 86 percent in-stream waste concentration (IWC). Using an estimated zero-lethality concentration of 8 milligrams per liter (mg/L) of ammonia, per CH2M HILL's laboratory data, and dividing it by 0.86, results in a limit of 9.3 mg/L in 100 percent effluent. Interpreting this as a daily maximum limit, and dividing by a typical treatment variability factor of 2.2, results in an average target ammonia concentration of approximately 4 mg/L. Therefore, it was assumed in this study that the treatment target is a mean ammonia concentration of 4.0 mg/L during all seasons.

As discussed in the 2002 Process Analysis, since the model predicts WWTP nitrification performance under steady-state, ideal operating conditions, it cannot be used directly to assess plant operational constraints for a desired annual mean effluent ammonia value. Instead, a minimum operating SRT must be determined for the wastewater conditions of concern (primarily temperature and dissolved oxygen concentration). The analysis of historical plant data presented in the 2002 Process Analysis determined a conservative operating factor of 1.71 for a target effluent ammonia concentration of 4.0 mg/L. This operating factor is applied to the minimum theoretical SRT for nitrification to determine the operating SRT for the analysis.

Three seasonal models were developed to account for differing wastewater temperatures and loading parameters observed throughout the year as follows:

Winter

January-March

Spring/Fall

April-June & October-December

Summer

July-September

For each of the seasonal models, the OF of 1.71, along with an assumed DO concentration of 2.5 mg/L in the aerobic zone of each basin, was used to establish the operating SRT in the model. Seasonal flow rates were established by assuming a maximum month design flow of 10.9 mgd, and multiplying it by the corresponding historical seasonal to maximum month flow ratios to get seasonal design flow rates for the model runs. Influent TSS, ammonia, and total Kjeldahl nitrogen (TKN) concentrations were also adjusted in the model to relative to the incoming BOD loadings based on a comparative analysis of historical plant data. With the operating conditions established for each of the three seasonal models as shown in Table 2, the models were run with incrementally increasing BOD loadings at the seasonal flow which corresponds to a maximum month design flow of 10.9 mgd, and at the SRT determined as described above to meet a target effluent ammonia concentration of 4.0 mg/L, until a maximum clarifier solids loading rate of 25 pounds per day per square foot (lbs/day/sq ft) resulted. The RAS rate for the analysis was assumed to be 100 percent of the peak month flow, or 10.9 mgd. In addition aeration requirements were not allowed to exceed the firm capacity of the installed aeration blowers of 10,300 scfm.

TABLE 2
Seasonal Influent and Operating Conditions for Capacity Assessment

Season	Influent Parameter	Value
Winter	Flow, mgd (average)	8.3
	Temperature, deg C	12.5 (12.3) ^a
	Required SRT, days	10,1
	Ratio of influent TSS to BOD	0.88
	Ratio of influent Ammonia to BOD	0.084
	Ratio of influent TKN to BOD	0.128
Spring/Fall	Flow, mgd (peak month)	10.9
	Temperature, deg C	14.0
	Required SRT, days	8.4
	Ratio of influent TSS to BOD	0.87
	Ratio of influent Ammonia to BOD	0.087
	Ratio of influent TKN to BOD	0.127
Summer	Flow, mgd	10.5
	Temperature, deg C	20.0 (21.4) ⁸
	Required SRT, days	4.3
	Ratio of influent TSS to BOD	0.96
	Ratio of influent Ammonia to BOD	0.078
	Ratio of influent TKN to BOD	0.128

Notes:

^aTemperature in parentheses is the typical extreme value for the season.

Modeling results are presented in Table 3 for the three seasonal operating conditions and the model runs are included in Appendix C.

TABLE 3
Secondary Treatment System Capacity Analysis Results

Parameter	Winter	Spring/Fall	Summer
Flow Rate, mgd	8.3	10.9	10.5
Allowable BOD Loading, lbs/day	20,759	22,264	23,810
Effluent Ammonia, mg/L	3.9	3.9	1.5
Clarifier Solids Loading, lbs/day/sq ft	21.4	21.0	17.6
Aeration Requirements, scfm	10,300	10,300	10,300
Limiting Factor	Aeration	Aeration	Aeration

The allowable BOD loading rate increase over the permitted 20,236 lbs/day for the secondary treatment system are smaller than would be expected with the addition of a third clarifier because the loading rates in each season are limited by the capacity of the aeration blowers and diffused aeration system, rather than the solids loading rate to the clarifiers. This can be explained because the aeration supply system, along with the step-feed aeration basins, were originally designed for a maximum design BOD loading rate of 19,325 lbs/day at a flow rate of 7.6 mgd during the winter and a maximum month design flow rate of 10.0 mgd and a BOD loading rate of 16,674 lbs/day in the spring, which was based on historical plant loading data from 1998 through 2001. In the last three years (2002 through 2004) the BOD loads have increased noticeably and an analysis was performed to determine the actual BOD capacity of the secondary treatment system at the request of the City. Results of this analysis showed the system BOD capacity to be somewhat higher than the original design capacity and an amendment to the WWTP site application was requested and approved by the Colorado Department of Health and Environment (CDPHE) to raise the permitted WWTP organic BOD capacity to 20,236 lbs/day.

The allowable BOD loading results shown in Table 4 are based on the maximum BOD that the system can treat under the parameters for that particular season and not on expected BOD loading rates for that season. To determine which maximum is appropriate to use for rating the organic capacity of the WWTP, it is important to explore the historical plant loading data to determine when the maximum month BOD loadings usually occur. Table 4 shows the historical peak month BOD load to the plant and the month in which it occurred from 1993 to 2004.

TABLE 4
Historical WWTP Influent BOD Loads

Year	Max Month BOD Load, lbs/day	Month in which Max BOD Occurred
1993	11,030	October
1994	10,268	January
1995	11,101	May
1996	12,838	November
1997	12,590	December
1998	13,177	May
1999	13,551	December
2000	13,308	December
2001	13,578	January
2002	15,758	July
2003	13,592	January
2004	11,030	October

Historically the maximum month BOD load has occurred in either the spring or fall, which would justify using the spring/fall maximum month capacity. However, there have been two instances when this load occurred in the winter months in the past ten years. Therefore, an analysis of historical peaking factors was performed to relate the seasonal peak month capacities to annual average capacities as shown in Table 5.

TABLE 5
Historical Peaking Factors for Seasonal BOD Loads

Parameter	Winter	Spring/Fall
Seasonal Maximum Month to Annual Average BOD Load Ratio		
1998	1.15	1.12
1999	1.03	1.14
2000	1.10	1.13
2001	1.04	1.11
2002	1.04	1.08
2003	1.05	1.11
2004	1.08	1.06
Average Peaking Factor	1.07	1.11

TABLE 5
Historical Peaking Factors for Seasonal BOD Loads

Parameter	Winter	Spring/Fall
Maximum Month BOD Capacity, lbs/day	20,759	22,264
Corresponding Annual Average BOD Capacity, lbs/day	19,400	20,057

Results of this analysis show that the winter maximum month BOD loading capacity of 20,759 lbs/day provides a lower annual average capacity and is therefore the more conservative value to use for permitting of the WWTP rather than the spring loading as originally assumed. The relatively limited increase in capacity resulting from the process modeling evaluation was discussed with the City at an interim workshop, and it was decided that the small increase in capacity did not justify the effort involved in submitting a new site application amendment to CDPHE. While the discussion in the meeting was based on the maximum month number for spring, subsequent analyses, as presented herein, have determined an even lower capacity, based on winter operation, adding validity to the decision to defer another site application amendment.

Additional Capacity Considerations

Although the secondary treatment system will gain capacity with the addition of a third secondary clarifier, other treatment process at the Loveland WWTP will impact the overall plant flow and BOD loading capacity.

WAS Thickening System

Currently WAS from the secondary treatment system is thickened in a 30 foot diameter dissolved air floatation (DAF) thickener located west of the Administration Building prior to being combined with the primary sludge for anaerobic digestion. The operators have noticed a marked decrease in performance of the DAF thickener over the past three years. An analysis of the solids treatment data provided by the plant operators was performed; the results of which are presented in Table 6.

TABLE 6
DAF Thickening System Performance

Parameter	2002	2003	2004
Average WAS flow, gpd	83,200	120,300	113,400
Average WAS solids loading, lbs dry solids (DS)/day	3874	4241	4242
Average TWAS solids recovery, lbs DS/day	2249	1344	1749
Average TWAS concentration, %	3.2	2.9	3.0
Average Solids Capture in the DAF, %	65.7	48.0	43.0

TABLE 6
DAF Thickening System Performance

Parameter	2002	2003	2004
Average Hydraulic Loading, gpd/sq ft	118	170	160
Average Solids Loading, lbs DS/day/sq ft	5.5	6.0	6.0

Although the thickened WAS concentration has remained fairly constant, the DAF solids capture rate has decreased steadily over the past three years. In addition, the current solids loading rate is at the recommended design limit (5 to 6 lbs DS/day/sq ft) for this type of thickener in a WAS application.

As WAS thickening is not a treatment process required by the State of Colorado, exceeding the design limits for the DAF thickening process will result in decreased unit performance but will not create a limiting process in terms of plant capacity.

The need for an evaluation of the Loveland WWTP's sludge thickening and dewatering systems has been identified in the City's CIP. The evaluation has been preliminarily scheduled for 2006.

Headworks Facilities

The Loveland WWTP headwork facilities include influent screening, grinding, grit removal and dewatering, influent flow measurement and sampling, and influent pumping. A screened bypass is included around the influent grinder and a bypass is also provided around the aerated grit basin. The grinding and grit removal facilities have a rated peak flow capacity of 15.4 mgd. Using the historic plant instantaneous to maximum month flow peaking factor of 1.73, this correlates to a maximum month flow of 8.9 mgd. However, these systems can be partially bypassed without affecting the overall rating maximum month flow rating of the WWTP. It is assumed that at a peak instantaneous flow of 20.7 mgd, as established in the 2002 Process Design Report for the WWTP, 5.3 mgd will be diverted through the manual bar screen in the grinder bypass channel and around aerated grit basin to join the remaining influent flow at the existing 24 inch partial flume. The existing flume is rated for a flow of 20.7 mgd.

The existing Influent Screw Pumping Station consists of a wetwell with three screw pumps, which transfer plant influent to the primary clarifier facilities. Each pump has a rated capacity of 5,350 gallons per minute (gpm). This equates to a firm pumping capacity of 15.4 million gallons per day (mgd) with two pumps on line and one pump on standby. Using a 1.73 historic peaking factor, this correlates to a maximum month flow of 8.9 mgd. The pump station includes a bypass channel from the pump station wetwell to the secondary clarifiers and, therefore, a redundant pump is not required by the CDPHE. The peak capacity of the pumping station with all three pumps on line is 23.1 mgd, which equates to maximum month flow of 13.4 mgd based on the historic peaking factor, and exceeds the peak instantaneous design flow of 20.7 mgd.

The need for an evaluation of the Loveland WWTP's headworks facilities has been identified in the City's CIP. The evaluation has been preliminarily scheduled for 2006.

Aeration Lift Pump Station

The existing Aeration Lift Pump Station consists of a wetwell with four vertical turbine pumps, which transfer primary effluent to the aeration basin splitter structure for further treatment. Each pump has a rated capacity of 3,600 gallons per minute (gpm). This equates to a firm pumping capacity of 15.6 million gallons per day (mgd) with three pumps on line and one pump on standby. Using the historic plant instantaneous to maximum month flow peaking factor of 1.73, this correlates to a 9.0 mgd maximum month flow. The pump station includes a bypass piping system that can convey flow from the pump station wetwell to the secondary clarifiers and, therefore, a redundant pump is not required by the CDPHE. The peak capacity of the pumping station with all four pumps on line is 20.7 mgd, which equates to maximum month flow of 12.0 mgd at the historic peaking factor, and equals the design peak instantaneous design flow.

The Aeration Lift Pump Station is currently being evaluated under a separate TM, and recommended improvements may be included with the design and construction of the new secondary clarifier, anaerobic digester, and trickling filter decommissioning improvements under this project.

Summary and Recommendations

The process analysis determined that the secondary treatment system could treat 10.9 mgd of wastewater flow and 20,759 pounds per day of influent BOD with the addition of the third secondary clarifier. The flow and BOD loading capacities were shown to be limited by the aeration basin and air supply systems. These results were presented at the interim project workshop to the City, and it was decided that the small increase in flow and loading capacity over the currently permitted value of 20,236 lbs/day does not justify the cost of pursuing an amendment to the site application and discharge permit through the CDPHE.

Once the evaluations of the sludge handling system, headworks, and aeration lift pump station have been completed, the impacts of these systems on the overall plant capacity will be better understood. The renewal process for the plant's discharge permit will take place in 2007, and additional capacity may be requested at that time.